

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19012019/KBA3Q2

**Date:** 07/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800094448

**Claimant**  
**Vehicle No :** SJR432Z **Insured Vehicle No :** SMD2207H

Date of Loss: 20/06/2019 Nature of Claim: TP Claim No: 3252544925SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR432Z		
Make & Model:	TOYOTA ALLION, 1.5 (A)	Engine No:	1NZD297434
Reg. Date:	05/06/2009 (Man. Year: 2008)	Chassis No:	NZT2603038241
Colour:	Metallic Black	Odometer:	172511 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,919.92	1,806.90	113.02	5.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	760.00	240.00	24.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,919.92</b>	<b>2,566.90</b>	<b>353.02</b>	<b>12.09</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,050.00</b>		
<b>(S\$)</b>	2,919.92	2,050.00	869.92	29.79
<b>+ GST 7.00/7.00% (S\$)</b>	204.39	143.50	60.89	29.79
<b>Nett Amount (S\$)</b>	<b>3,124.31</b>	<b>2,193.50</b>	<b>930.81</b>	<b>29.79</b>
<b>+ Car Rental (3.0 x S\$85.00/day + 7.00% GST) (S\$)</b>		272.85		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,468.35</b>		

### INSPECTION

Date of Assignment: 15/07/2019

Date Inspected: 15/07/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun  
Industrial Park A  
Singapore 768761

Estimated Period of Repair: 3.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	927.50 FL	*927.50 FL
2	1		*FRONT BUMPER REINFORCEMENT	Buckled	421.70 FL	*421.70 FL
3	1		*FRONT BUMPER CENTRE LOWER GRILLE	Serviceable	150.70 FL	*- FL
4	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
5	1		*FRONT GRILLE	Dented	411.50 FL	*411.50 FL
6	1		*RH HEADLAMP	Mtg Cracked	627.50 FL	*627.50 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,559.90</b>	<b>2,409.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>639.98</b>	<b>602.30</b>
<b>Total Parts (\$)</b>	<b>1,919.92</b>	<b>1,806.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	500.00	360.00
2	PUTTY & RESPRAY PAINT	New	500.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>1,000.00</b>	<b>760.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**