

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19012033/ERA3Q2
Date: 14/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994309
Claimant Vehicle No :	FBN5178R	Insured Vehicle No :	SKR5601H
Date of Loss:	30/06/2019	Nature of Claim:	TP
		Claim No:	5334896645SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN5178R		
Make & Model:	YAMAHA SNIPER T150, 150cc	Engine No:	G3E6E0433259
Reg. Date:	18/10/2018 (Man. Year: 2018)	Chassis No:	MH3UG0740J0126177
Colour:	Blue	Odometer:	14277 km
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	120/70 R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,421.00	2,394.00	5,027.00	67.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	500.00	1,040.00	67.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,961.00	2,894.00	6,067.00	67.70
Approved Total (Overridden) (S\$)		2,300.00		

Nett Amount (S\$)	8,961.00	2,300.00	6,661.00	74.33
+ Loss of Use (6.0 x S\$30.00/day) (S\$)		180.00		
Nett Liability (S\$)		2,480.00		

INSPECTION

Date of Assignment: 04/07/2019

Date Inspected: 08/07/2019

Estimated Period of Repair: 4.0 days

Inspected At:

KARZ WORKS PTE LTD
 53 Ubi Ave 1 #01-23/24
 Paya Ubi Industrial Park
 Singapore 408934

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH SIDE FAIRING	Broken	430.00 FL	*185.00 FL
2	1		*FRONT LH INNER GARNISH	Cut	130.00 FL	*100.00 FL
3	1		*FRONT LH SIGNAL	Cut	150.00 FL	*48.00 FL
4	1		*LH FOOTREST	Broken	180.00 FL	*65.00 FL
5	1		*LH FOOTREST BRACKET	Bent	250.00 FL	*80.00 FL
6	1		*LH PILLION FOOTREST	Not Necessary	130.00 FL	*- FL
7	1		*REAR LH FAIRING	Not Necessary	410.00 FL	*- FL
8	1		*HANDLE BAR	Bent	350.00 FL	*110.00 FL
9	1		*HANDLE BAR GRIP	Torn	230.00 FL	*10.00 FL
10	1		*BALANCER	Cut	170.00 FL	*30.00 FL
11	1		*CLUTCH LEVER	Not Necessary	130.00 FL	*- FL
12	1		*FRONT LH FORK ASSY	Bent	550.00 FL	*280.00 FL
13	1		*FRONT RH FORK ASSY	Bent	550.00 FL	*280.00 FL
14	1		*STEERING HEADCROWM	Not Necessary	150.00 FL	*- FL
15	1		*STEERING STEM UNDERBRACKET	Bent	210.00 FL	*180.00 FL
16	1		*STEERING STEM BEARING	Necessary	130.00 FL	*30.00 FL
17	1		*GEAR LEVER	Cut	130.00 FL	*30.00 FL
18	1		*RUBBER STAND	Not Necessary	180.00 FL	*- FL
19	1		*FORK BRACKET	Repeated	90.00 FL	*- FL
20	1		*HANDLE BAR BRACKET	Bent	120.00 FL	*90.00 FL
21	1		*FRONT HEADLAMP FAIRING	Cut	250.00 FL	*115.00 FL
22	1		*FRONT DIM LIGHT	Cut	500.00 FL	*58.00 FL
23	1		*FRONT DIM LIGHT COVER	Cut	150.00 FL	*125.00 FL
24	1		*FRONT FENDER	Not Necessary	350.00 FL	*- FL
25	1		*GEAR SHIT SHAFT OIL SEAL	Necessary	12.00 FS	*12.00 FS
26	1		*FORK OIL SEAL	Necessary	45.00 FS	*30.00 FS
27	1		*FORK OIL	Necessary	12.00 FS	*12.00 FS
28	1		*WING MIRROR	Cut	400.00 FS	*40.00 FS
29	1		*RUBBER STAND COVER	Not Necessary	300.00 FS	*- FS
30	1		*REAR BOX	Cut	500.00 FS	*250.00 FS
31	1		*RIM	Bent	500.00 FS	*250.00 FS
32	1		*EXHAUST COVER	Cut	180.00 FL	*65.00 FL
33	1		*MUFFLER PROTECTOR	Cut	180.00 FL	*119.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)
8,049.00
2,594.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (\$\$)					628.00	200.00
Total Parts (\$\$)					7,421.00	2,394.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE ,REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM	New	600.00	250.00
2	TO KNOCK ,STRAIGHTEN CHASSIS AND BODY BALANCING	New	380.00	0.00
3	TO REMOVE /REFIT ,REPLACE FRONT FORK TUDES	New	180.00	50.00
4	SPRAY PAINTING	New	380.00	200.00
Gross Labour Cost (\$\$)			1,540.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >