2:27(3)(2002 -	T T		N		336	(+	
ASS, REC. B		FF: CSIMSGIA	012060   Kigf	De Special	Instructions		
"Surayor :_		ASSIGNA	MENT (Office)	01			
From (Perso	on); Ong zi hui	of	5		7 000	8/7/1985	5700
Estimated C	ost:		The same of the sa	Da	te/Time: _	0171196)-	27/1
OD (TP)/W	VS/TP RES/OD RES	EVA/TNV/MV					
To Inspect V	Pehicle No:	SHC 620	27	Terminada	91	K 3596C	
	m/s				6544		-
of			2# 01-0	. rer: —	0 244	,	P
Policy No:	29114756	J. Gorgin Nive	Claim No:		1-02	Fire brees.	
Sum Insured				20	10-17		
Make of Veh			Excess:				
(Client's Recor	-0.0M			D.C	).A_ 5	17/2019	-
CA / REV	/ REP. / REV 24 HRS	5		**			
Date/Time; 0	1am@ 917/19	Person Contrated	1 1	11	LO.D. Endors	sement:	-
			- Therif	Vehic	CINIO	UT	
Date/Time	Action/Instruction	phromby S					
	SLK 3596C :X						
1 /	SHC 61917-00	HIASMISOLLE	47/11/200	0.0.0.1	01-1-	ve:	
10/11/10/17	nop varges	to OM 25 H	ui Va Wen	nen.	11/1/20	10	-
7				The second second			
					-		

ASS. REC. BY: Kalas REF: MSIG	9
	GNMENT
From: Date: 917 2019	Veh No: SHC 62 927 Yr Regn: 25/18r /2014
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Tati / Prime Mover /
OD (TP )WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SHC 6392Z	Make: CIA optim c.c /685  Colour Silm A/C: Ins@ed/Std/NI/NA
at Workshop m/s Premier Automotive	
of 23 Chargi south Are 2 # 01-02	Sp.Reading 465965 T/Radio: Inserred / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: KNAhm 414 MP555535
Claims No.	Gen. Cond: Good / Ear / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder/-Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD AFRim or
4.1	Tyre Size: F: 201/65 116
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO OF Hankark
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm R/Bal. 7 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal.
Est. Repairs:	D.O.A. 5/3/19 D.O.I. 9/7/19
Lum Sum: % 3 Val.: Yes or No	Survey held at Premer
	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	0/5 Body.
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction  16/9/19 Color U/S \$1500 / 4/4.	Red \$ 1763.24, 54%)
RECEIVE	D 1 6 SEP 2019 16 9 2019
	, ,
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 4
1) 16 19 Main : Final Report	Resurvey No. of Trip:/ Survey Fee:
Date/Time, File Return to?	Transportation:

Add Fee:

Report Format:

Lump Sum / I.B.t. (\$

: Site Insp (\$

: Interview (\$

Tech. Invs (\$

Weelrend (\$

\_S + RS,\_\_\_SI

11

Photos

Others

TOTAL

# Nivitha (LKK Auto)

From:

Ong Zi Hui <zihui ong@sg.msig-asia.com>

Sent:

Monday, 8 July 2019 5:57 PM

To:

admin-d@lkkauto.com; assignments@lkkauto.com

Cc:

Crystal Lee

Subject:

Survey Request - Manual Assigned

Attachments:

08072019132827-0001.pdf

Importance:

High

# Pre-inspection/Accident involving between SHC6292Z & SLK3596C on 05.07.2019

#### Manual Assigned

Dear LKK

Refer to the email and attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Ong Zi Hui Admin Officer, Claims Serivces

D: +65 6643 1320 | F: +65 6225 7402 | zihui\_ong@sg.msig-asia.com



# MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg









A Member of MS&AD INSURANCE GROUP

From: Vincent Chua [mailto:vincent.chua@premiertaxi.com]

Sent: Monday, 8 July, 2019 2:49 PM

To: Motor Survey < motorsurvey@sg.msig-asia.com>

Cc: Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>

Subject: FW: Pre-inspection/Accident involving between SHC6292Z & SLK3596C on 05.07.2019

# EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

We refer to the email sent below.

Please kindly take note that SHC6292Z is grounded and available for survey at any time.

Kindly arrange for survey first.

Thank you.

Regards

Vincent Chua Operations Assistant Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511

Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

A Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Vincent Chua

Sent: Monday, 8 July, 2019 2:47 PM

To: 'Motor Survey' < motorsurvey@sg.msig-asia.com>

Cc: Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>

Subject: Pre-inspection/Accident involving between SHC6292Z & SLK3596C on 05.07.2019

Dear all,

We refer to the vehicles mentioned above.

Vehicle to be Surveyed: SHC6292Z

Insured Vehicle: SLK3596C Date of Accident: 05/07/2019

Name of Workshop: Premier Automotive Services Pte Ltd

Address of Survey Location: 23 Changi South Avenue 2, #01-02, S (486443)

Name of Contact Person: Mr Vincent Chua

Contact Number: 65446689

Email Address of Contact Person: vincent.chua@premiertaxi.com

# \*Vehicle not yet available for survey\*

#### Kindly send us your panel list.

Kindly arrange for survey first.

Thank you.

Regards

Vincent Chua
Operations Assistant
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511

Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

♣ Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION ♣

#### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

# Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Pauline Tham

10 Jul 2019 Date:

# Preliminary Advice

Insured Vehicle No : SLK3596C

TP Vehicle No

: SHC6292Z

Accident Date

: 05/07/2019

Make

: KIA OPTIMA

Assignment Date

: 09/07/2019

Date of Inspection : 09/07/2019

Est. Duration of Repair

: 4.00

Inspection At

: PREMIER AUTOMOTIVE SERVICES PTE LTD (CHANGI)

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

# Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,263.24
Revised Amount	:S\$	1,793.64
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,793.64

:S\$ Lump Sum Repair

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

## Remarks

) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

Text size + -

# **Enquire Transaction History**

## Transaction History Details

Log Date/Time:

25 Nov 2014 / 09:32:57

Receipt No .:

AACCK001-AX239-141125-000010

Asset Type:

Vehicle

Transaction Amount:

\$64,194.00

Asset ID:

SHC6292Z

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

**Business Transaction** 

01.02 Register New Vehicle (AA)

Reference No.:

20141125093257426533

Vehicle No.:

SHC6292Z

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 25 Nov 2014

Original Registration

Date:

25 Nov 2014

Vehicle Make:

KIA

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414MF5555235

Engine No.:

D4FDEH311816

Motor No.:

Trailer Chassis No.:

Diesel

Propellant: Passenger Capacity:

Engine Capacity:

1685

Power Rating:

1584

Unladen Weight: Maximum Laden

2050

Weight:

Silver

Primary Color:

Secondary Color: Manufacturing Year:

2014

Open Market Value:

\$20,155.00

Minimum PARF

Benefit:

\$7,630.00

PARF Eligibility: No. of Transfer:

Effective Ownership

25 Nov 2014 09:32:57

Date/Time:

2014112501001367N

COE No .:

24 Nov 2022

COE Expiry Date:

COE Bid Category: Actual QP/PQP Paid

Amount:

\$51,337.00

Lifespan Expiry Date:

24 Nov 2022

Owner ID Type:

Company.

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	08/07/2019 09:27
Date Of Accident	05/07/2019 15:10
Exact Location Of Accident	WOODLANDS AVE 2 // WOODLANDS AVE 1
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC6292Z
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	
Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107202885
Cover Note Number	
Driver	
Name of Driver	QUAH KIM CHWEE
NRIC No	S1167560C
Date Of Birth	07/03/1956

 NRIC No
 S1167560C

 Date Of Birth
 07/03/1956

 Occupation
 OUTDOOR

 Date Of Driving Pass
 13/04/1977

Driving Experience 42 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98627679

Fax Number

Contact Number

EMail Address NOEMAIL

Address

BLK 436C #24-172 FERNVALE ROAD

Postcode

793436

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - SUPER RELIEF - ANG MO KIO

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NAME:

: PAX IN THE FRONT SEAT - MALAY

GENDER:

: MALE

Passenger 2

NAME:

: PAX IN THE REAR SEAT - MALAY

GENDER:

: MALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

VEH. A - 2 PAX VEH. B - 1 PAX

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SLK3596C

Vehicle Make/Model/Colour

TOYOTA PRIUS

**Details Of Properties** 

VEH. B

Vehicle Category

PRIVATE HIRE

Name of Driver

Contact Number

NRIC/Passport Number

NG BOONE SING

S2598607E 93852379

Address

Postcode

Page 2 of 15

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.[collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

\axi

Driver's Signature (If driver is not the policyholder)

Date & Time:

0 8 JUL 2019

Reporting Centre Personnel's Signature

NRIC/FIN No .:

SKETCH PLAN			MOODEN
	WOODLANDS	A B	A
DESCRIBE CIRCUMSTANCE	ES OF THE ACCIDENT	3 7	1
	A. OHC 62922		
	b. SLK 3596C.		
/We destries the foregoing pa	rticulars are true in every respect.	0 8 JUL 2019	
Policyholders signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:  3/167560 C	Reporting Centre Personnel's Sig Name: NRIC/FIN No.:	nature

#### Sketch Plan Pg. 3

# Describe Circumstance of the Accident.

ON 05/07/2019 @ 1510HRS, I WAS DRIVING MY TAXI ( SHC 6292 Z ) – TRAVELLING ALONG WOODLANDS AVE 2 AT THE TRAFFIC LIGHT JUNCTION OF WOODLANDS AVE 1, WITH 2 PASSENGERS ONBOARD IN LANE 3.


WHILE I WAS MOVING STRAIGHT AHEAD – SUDDENLY VEHICLE B
( SLK 3596C – TOYOTA PRIUS ) WHICH WAS INITIALLY IN THE LANE 2 –
FAILED TO KEEP FOR PROPER LOOK OUT & FAILED TO OBSERVE FOR
CLEARANCE FROM MY ROUTE – HAD ENCROACHED ONTO MY PATH ON
MY RIGHT ABRUPTLY.

AS SUCH THE LEFT FRONT OF VEHICLE B COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE RIGHT PORTION & VEHICLE B HAD DAMAGES ON THE LEFT FRONT PORTION.

NO INJURY INVOLVED.
VEHICLE B HAD A PASSENGER ONBOARD.

\*VIDEO FOOTAGE CAPTURED



Claim Reference:

Assessment number: 010142

Version: 1810

Date calculated: 09/07/2019 12:10 PM

Full Report

Registration: SHC6292Z

Printed: 09/07/2019 12:10 PM

# Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

MSIG Insurance

(Singapore) Pte Ltd

Printed by:

WEEDEK GOH

Currency:

SGD

Claim Reference:

Estimated Repair Time:

Date of Incident: Hire Car Start:

05/07/19

Actual Repair Days:

Hire Car End:

# **Vehicle Details**

Vehicle

Manufacturer:

KIA

Model:

OPTIMA (TF)

Sub Model: Model Sheet Number: 2 LUXE

28 36 38 SHC6292Z

Registration: VIN number:

Odometer:

#01-02, 23 Changi Sth Ave 2 486443

Claim Reference:

Full Report

Assessment number: 010142

Registration: SHC6292Z

Version: 1810

Printed: 09/07/2019 12:10 PM

Date calculated: 09/07/2019 12:10 PM


# **Vehicle Condition**

#### Vehicle Status

Pre-Accident Damage: Date of Inspection:

# **Damage Areas**

All Underbody



#### Labour

	Time Base 10 WU/h	Price = 50.	00 SGD/h
Code	Description	WU	Price SGD
66300R00)	R + R RIGHT FRONT WING (BUMPER REMOVED)	5.0	25.00
86512R00 ZAX	R + R FRONT BUMPER	3.0	15.00
76000R00	RENEW R/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY	16.0	80.00
76000RF0)	R + R R/F DOOR HINGE/S	4.0	20.00
77000R00	RENEW R/R DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY	18.0	90.00
77000RF0	RENEW R/R DOOR HINGES	2.0	10.00
87755R00	R + R R/SILL TRIM	3.0	15.00
86520R00	RENEW REAR BUMPER (REMOVED)	11.0	55.00
3486	R/R OUTER SIDE PANEL REPAIR	20.0*	100.00
9552	R/R WHEEL CHECK	12.0*	60.00

Claim Reference:

**Full Report** 

Assessment number: 010142

Registration: SHC6292Z

Version: 1810

Printed: 09/07/2019 12:10 PM

Date calculated: 09/07/2019 12:10 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	9.40	94.0	470.00
Total of Labour			470.00

#### Paint

Paint Work	SYSTEM AZT	Time Basis	s 10WU/h
Code	Description	wu	Price SGD
	RIGHT FRONT DOOR NEW PART PAINTING	15.0	
	R/R DOOR NEW PART PAINTING	14.0	
	R/SILL PANELLING NEW PART PAINT K1R	6.0	
	REAR BUMPER NEW PART PAINT K1R	12.0	
	R/R OUTER SIDE PANEL REPAIR PAINTING < 50%	15.0	

#### Paint Material Per Part

Code	Description	Price SGD
1482	RIGHT FRONT DOOR NEW PART PAINTING	35.06
1782	R/R DOOR NEW PART PAINTING	31.03
2208	R/SILL PANELLING NEW PART PAINT K1R	20.24
2583	REAR BUMPER NEW PART PAINT K1R	49.91
3486	R/R OUTER SIDE PANEL REPAIR PAINTING <50%	20.25

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint			62.0	
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.30	3.0	15.00
Total	10 WU/h	8.20	82.0	410.00

Material Cost - Paint	Price SGD
New Part Painting	66.09
New Part Painting - Plastic K1R	70.15
Repair Painting	20.25
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	183.59

# **Spare Parts**

prices as at 2015-06-01

Claim Reference:

Full Report

Assessment number: 010142

Registration: SHC6292Z

Version: 1810

486443

Pi

Printed: 09/07/2019 12:10 PM

Date calculated: 09/07/2019 12:10 PM

Code	Description	Part Number	Supplier	Price SGD
1482	RIGHT FRONT DOOR	760042T000	- RALL	761.00
1488	R/F UPPER DOOR HINGE	793203K000	× ~	34.00
1496	R/F LOWER DOOR HINGE	793203K000	× M	34.00
1688	R/F DOOR RR MOULDING	863732T000	XMX	0.00
1692	R/F UPP DOOR MLDG	828602T000	* ~	0.00
1782	R/R DOOR	770042T000	×1402	791.00
1788	R/R UPPER DOOR HINGE	794203K000	× m	34.00
1796	R/R LOWER DOOR HINGE	793203K000	X se	34.00
1984	R/R DR FRM FRT TRIM	831452T000	× see	0.00
1986	R/R DOOR FRM UP TRIM	831342T000	Se on	0.00
1988	R/R DOOR FRT MLDG	863912T000	×n	0.00
1992	R/R UPP DOOR MLDG	838602T000	× se	0.00
2208	R/SILL PANELLING	877522T000	× Man	286.00
2583	REAR BUMPER	866112T500	x report	696.00
2618	R/R BUMPER BRACKET	866142T501		29.00
2770	REAR BUMPER SPOILER	866122T500	x se	206.00
9560	R/R WHEEL COVER	529602T100	1 huzed	116.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			3,021.00
u: Used parts	Subtotal Discount(+	35.00%)		-1,057.35
	Total			1,963.65

## **Extras**

Code	Description		Price SGD
1000 1001	Rear bumper clips Rear R Wing sticker	X 17	48.00* 60.00*
1001	RH door stickers	- ME	100.00*
1002	RH Sill garnish clip		28.00*
1005	Total Extras	* 2	236.00

Claim Reference:

Full Report

Assessment number: 010142

Registration: SHC6292Z

Version: 1810

Printed: 09/07/2019 12:10 PM

Date calculated: 09/07/2019 12:10 PM

# **Final Calculation**

		SGD	SGD
Parts Total Discount(+35.00%) Total Parts		3,021.00 1,057.35	1,963.65
Labour Time Base 10 WU/h Total 094.0 WU X 50.00 SGD/h Total of Labour		470.00 540	470.00
Total Of Extras			236.00
Paint Work Time Base 10 WU/h Labour Cost 82.0 WU X 50.00 SGD/h Material Cost Ay Total Paint Including Material	LKK Apple Consider is hence notify  the Reporter of the following:  • To rest for the plant play conting:	410.00 465 183.59 65.	ر 593.59
Repair Cost Excludes GST	To test in     To test in		3,263.24
GST (+7.0%) Repair Cost Included GST	Ports prome are sur Third party across is on a company Prejudice basis Third party across is on a company No illegal moducation(s) is allowed.  Supplementary nerros) must be resurveyed and Is subject to final approval from insurance Company Acknowledged by Repairer	Amounta	228.43 3,491.67
* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS	Signature: Kahni ICICA)  1 9/2/19 17  4 Pg.  45  Aller Reprir p	10/1/1k	<b>\</b>

**Insurer Reference:** 

Repairer Reference: SHC6292Z

Date calculated: 13/09/2019 9:07 AM

Full Report Registration: SHC6292Z Printed: 13/09/2019 9:07 AM

# **Summary Information**

Claim

Location:

Singapore (SG)

Work Provider:

MSIG Insurance

(Singapore) Pte Ltd

Printed by:

Claim Reference:

WEEDEK GOH

Currency:

SGD 05/07/19

Estimated Repair Time:

Estimated Repair Time Actual Repair Days: Date of Incident: Hire Car Start:

Hire Car End:

# **Vehicle Details**

Vehicle

Manufacturer:

KIA

Model:

OPTIMA (TF)

Sub Model:

2 LUXE 28 36 38

Model Sheet Number: Registration:

SHC6292Z

VIN number:

Odometer:

## **Vehicle Condition**


#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

#### **Damage Areas**

All

Underbody



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Insurer Reference:

Full Report

Repairer Reference: SHC6292Z

Registration: SHC6292Z

Date calculated: 13/09/2019 9:07 AM

Printed: 13/09/2019 9:07 AM

Description		WU	Price SGD
RENEW R/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		16.0	80.00
R/R DOOR REPAIR		20.0*	100.00
R/SILL PANELLING REPAIR		20.0*	100.00
REAR BUMPER REPAIR		20.0*	100.00
R/R OUTER SIDE PANEL REPAIR		20.0*	100.00
R/R WHEEL CHECK		12.0*	60.00
Labour Cost	Hrs	wu	
Panel / Mechanical Labour	10.80	108.0	540.00
Total of Labour			540.00
	RENEW R/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY R/R DOOR REPAIR R/SILL PANELLING REPAIR REAR BUMPER REPAIR R/R OUTER SIDE PANEL REPAIR R/R WHEEL CHECK  Labour Cost Panel / Mechanical Labour	RENEW R/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY R/R DOOR REPAIR R/SILL PANELLING REPAIR REAR BUMPER REPAIR R/R OUTER SIDE PANEL REPAIR R/R WHEEL CHECK  Labour Cost Panel / Mechanical Labour  Hrs 10.80	RENEW R/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY R/R DOOR REPAIR R/SILL PANELLING REPAIR REAR BUMPER REPAIR R/R OUTER SIDE PANEL REPAIR R/R WHEEL CHECK  Labour Cost Panel / Mechanical Labour  16.0  16.0  10.0  10.0  10.0  10.0  10.0  10.0

#### Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU Price SGD
	RIGHT FRONT DOOR NEW PART PAINTING	15.0
	R/R DOOR REPAIR PAINTING <50%	14.0
	R/SILL PANELLING REPAIR PAINT PLASTIC	11.0
	REAR BUMPER REPAIR PAINT PLASTIC	15.0
	R/R OUTER SIDE PANEL REPAIR PAINTING <50%	15.0

# **Paint Material Per Part**

Code	Description	Price SGD
1482	RIGHT FRONT DOOR NEW PART PAINTING	35.06
1782	R/R DOOR REPAIR PAINTING <50%	19.25
2208	R/SILL PANELLING REPAIR PAINT PLASTIC	17.40
2583	REAR BUMPER REPAIR PAINT PLASTIC	42.90
3486	R/R OUTER SIDE PANEL REPAIR PAINTING <50%	20.25

Labour Cost - Paint		Hrs	wu	Price SGD
Factor	50.00 SGD/h			
Time Paint			70.0	
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.60	6.0	30.00
Total	10 WU/h	9.30	93.0	465.00

**Insurer Reference:** 

Repairer Reference: SHC6292Z

Date calculated: 13/09/2019 9:07 AM

**Full Report** 

Registration: SHC6292Z

Printed: 13/09/2019 9:07 AM

Material Cost - Paint	Price SGD
New Part Painting	35.06
Repair Painting	39.50
Repair Painting Plastic	60.30
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	165.66

# Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
1482	RIGHT FRONT DOOR	760042T000		761.00
1688	R/F DOOR RR MOULDING	863732T000		0.00
1692	R/F UPP DOOR MLDG	828602T000		0.00
9560	R/R WHEEL COVER	529602T100		116.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			877.00
u: Used parts	Subtotal Discount(	+35.00%)		-306.95
	Total			570.05

#### **Extras**

Code	Description	Price SGD
1001	Rear R Wing sticker	60.00*
1002	RH door stickers	100.00*
	Total Extras	160.00

**Insurer Reference:** 

Repairer Reference: SHC6292Z

Date calculated: 13/09/2019 9:07 AM

Full Report Registration: SHC6292Z

Printed: 13/09/2019 9:07 AM

# **Final Calculation**

Thial Calculation		
	SGD	SGD
Parts	877.00	
Total Discount(+35.00%)	-306.95	
Total Parts		570.05
Labour Time Base 10 WU/h		
Total 108.0 WU X 50.00 SGD/h	540.00	
Total of Labour		540.00
Total Of Extras		160.00
Paint Work Time Base 10 WU/h		
Labour Cost 93.0 WU X 50.00 SGD/h	465.00	
Material Cost	165.66	
Total Paint Including Material		630.66
Repair Cost Excludes GST		1,900.71
GST (+7.0%)		133.05
Repair Cost Included GST		2,033.76

#### Comments

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

## **Assessment Note**

No assessment notes entered.

**Insurer Reference:** 

Repairer Reference: 010142

Date calculated: 16/09/2019 10:32 AM

**Summary Information** 

Full Report

Registration: SHC6292Z

Printed: 16/09/2019 10:32 AM

Claim

Location:

Singapore (SG)

Work Provider:

MSIG Insurance

(Singapore) Pte Ltd

Printed by:

Claim Reference:

KK LAU

Currency:

SGD

Estimated Repair Time: Actual Repair Days:

Date of Incident: Hire Car Start:

05/07/19

Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

KIA

Model:

OPTIMA (TF)

Sub Model:

2 LUXE 28 36 38

Model Sheet Number: Registration:

SHC6292Z

VIN number: Odometer:

Vehicle Condition


**Vehicle Status** 

Pre-Accident Damage: Date of Inspection:

**Damage Areas** 

AII

Underbody



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Insurer Re	ference:		F	ull Report
Repairer R	eference: 010142	Regist	ration:	SHC6292Z
	lated: 16/09/2019 10:32 AM	Printed: 16/09/2019 10:32 AM		
Code	Description		WU	Price SGD
76000R00	RENEW R/F DOOR		16.0	80.00
	INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY			
1782	R/R DOOR REPAIR		20.0*	100.00
2208	R/SILL PANELLING REPAIR		20.0*	100.00
2583	REAR BUMPER REPAIR		20.0*	100.00
3486	R/R OUTER SIDE PANEL REPAIR		20.0*	100.00
9552	R/R WHEEL CHECK		12.0*	60.00
	Labour Cost	Hrs	wu	
	Panel / Mechanical Labour	10.80	108.0	540.00
	Total of Labour			540.00

# Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU Price SGI
	RIGHT FRONT DOOR NEW PART PAINTING	15.0
	R/R DOOR REPAIR PAINTING <50%	14.0
	R/SILL PANELLING REPAIR PAINT PLASTIC	11.0
	REAR BUMPER REPAIR PAINT PLASTIC	15.0
	R/R OUTER SIDE PANEL REPAIR PAINTING <50%	15.0

# **Paint Material Per Part**

Code	Description	Price SGD
1482	RIGHT FRONT DOOR NEW PART PAINTING	35.06
1782	R/R DOOR REPAIR PAINTING <50%	19.25
2208	R/SILL PANELLING REPAIR PAINT PLASTIC	17.40
2583	REAR BUMPER REPAIR PAINT PLASTIC	42.90
3486	R/R OUTER SIDE PANEL REPAIR PAINTING <50%	20.25

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint			70.0	
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.60	6.0	30.00
Total	10 WU/h	9.30	93.0	465.00

Insurer Reference: Repairer Reference: 010142 Date calculated: 16/09/2019 10:32 AM

Total

Registration: SHC6292Z Printed: 16/09/2019 10:32 AM Price SGD **Material Cost - Paint New Part Painting** Repair Painting Repair Painting Plastic Material-constant Metal Material-constant Plastic

**Spare Parts** 

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
Couc	Description			
1482	RIGHT FRONT DOOR	760042T000		761.00
1688	R/F DOOR RR MOULDING	863732T000		0.00
1692	R/F UPP DOOR MLDG	828602T000		0.00
9560	R/R WHEEL COVER	529602T100		116.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			877.00
u: Used parts	Subtotal Discount(	+35.00%)		-306.95
	Total			570.05

## **Extras**

Code	Description	Price SGD
1001	Rear R Wing sticker	60.00*
1002	RH door stickers	100.00*
2002	Total Extras	160.00

Full Report

35.06

39.50

60.30

18.10

12.70

165.66

**Insurer Reference:** 

Full Report

Repairer Reference: 010142

Registration: SHC6292Z

Date calculated: 16/09/2019 10:32 AM

Printed: 16/09/2019 10:32 AM

#### **Final Calculation**

rillar calculation		
	SGD	SGD
Parts	877.00	
Total Discount(+35.00%)	-306.95	
Total Parts		570.05
Labour Time Base 10 WU/h		
Total 108.0 WU X 50.00 SGD/h	540.00	
Total of Labour		540.00
Total Of Extras		160.00
Paint Work Time Base 10 WU/h		
Labour Cost 93.0 WU X 50.00 SGD/h	465.00	
Material Cost	165.66	
Total Paint Including Material		630.66
Repair Cost Excludes GST		1,900.71
GST (+7.0%)		133.05
Repair Cost Included GST		2,033.76

#### Comments

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

#### **Assessment Note**

No assessment notes entered.

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj S	Submitted	Ins Auth'ed	Status	
Main	08 Jul 2019		09 Jul 2019 10:52 Edit Adj Rpt	S\$1,500.00 Edit Estimat	1000	,500.00 ew Rpt		Pending for Survey Report Cancel Case	
	Main	R	eference	Clair	n Details		Documents		Show All
CLAIM SL	JBFOLDER DI	ETAILS				Created	by insurer]		
Insured:	GRAB RE	NTALS PTE LTD,	Co. Reg. No.: 201	617200G		1.7			
Main Claimant:	PREMIER	TAXIS PTE LTD	Co. Reg. No.: 20	0304975Н					
Vehicle Rei No.:	9. SHC629	)2Z		Da	te of Loss:		9 15:00 - :59 as and <b>10</b> Days Fro	m LTA Reg i	Date (Man Yr)]
Claim Type	Policy/Cover Note No.: Policy/Cover 29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020								
Vehicle Re No. (Insured):	SLK3596	SLK3596C Policy No. (Claimant):							
				1.000	cess:	2 #01 02 4	05442 Channi Tal	le .	
Repairer: Handling Insurer:			rices Pte Ltd (Char ore) Pte. Ltd. (HQ)						
Adjuster:	08/08/2		Ltd (HQ) - Tel: 62	256-3561 [Ha	ndled by <b>K</b>	ALVIN AND	G WEI KUN ] [F	Final Rpt	due
Driver/Cus dian (Insured):	NG BOON	E SING ( / Male) ,	NRIC: S2598607	E Email:					
Adj Asg. Remarks:	on WP. (n	nanual assigned to	LKK) Liab: Dispute	. Contact: Vince	nt @ 6544	6689. Manua	al assigned to LKK	via email on	08/07/19.
ASSOCIA	TED MAIL RE	CEIVED					Vie	w All Co	mpose Case Mail
There are	no mail for this	case.							
ALL ASS	OCIATED TAS	sks⊡				View All	Search Tasks C	reate New T	ask   Complete
Due Dat		Type Task	Group Subje	ct Handler	Assig	ned By	Completed On	Create	ed On Done

Merimen e-Claims Page 1 of 2

## **Claim Documents**

\*SHC6292Z (599093) [SLK3596C] TP PREMIER TAXIS PTE LTD Jul 5 2019 3:00PM [GRAB RENTALS PTE LTD] **Premier Automotive Services Pte Ltd** 

Ass	essment Reports		1 per	page V	V
20070	The second second second	LVV Auto Consultants Pto Ltd (HO)	11 per	Thumbnail	
No 1	Finalized On 10/07/19 12:02	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	6	Load HTM	Prin
_	10/07/13 12:02	Adjuster immediate Advice		Loud IIII	
Pho	tos/Images		3 per	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	10/07/19 08:40	General View	0	Load JPG	V
2	10/07/19 08:40	General View	0	Load JPG	V
3	10/07/19 08:40	General View	0	Load JPG	V
4	10/07/19 08:40	General View	0	Load JPG	V
5	10/07/19 08:40	General View	0	Load JPG	V
6	10/07/19 08:40	General View	0	Load JPG	V
7	10/07/19 08:40	General View	0	Load JPG	V
8	10/07/19 08:40	General View	0	Load JPG	V
9	10/07/19 08:40	General View	0	Load JPG	V
10	10/07/19 08:40	General View	0	Load JPG	V
11		General View	0	Load JPG	V
	10/07/19 08:40		0	Load JPG	V
12	10/07/19 08:40	General View	0	Load JPG	₩.
13	10/07/19 08:40	General View			_
14	10/07/19 08:40	General View	0	Load JPG	2
15	10/07/19 08:40	General View	0	Load JPG	V
16	10/07/19 08:40	General View	0	Load JPG	V
17	10/07/19 08:40	General View	0	Load JPG	Z
18	10/07/19 08:40	General View	0	Load JPG	₹
19	10/07/19 08:40	General View	0	Load JPG	₹
20	10/07/19 08:40	General View	0	Load JPG	V
21	10/07/19 08:40	General View	0	Load JPG	V
22	10/07/19 08:40	General View	0	Load JPG	V
23	10/07/19 08:40	General View	0	Load JPG	V
24	10/07/19 08:40	General View	0	Load JPG	V
25	10/07/19 08:40	General View	0	Load JPG	V
26	10/07/19 08:40	General View	0	Load JPG	V
27	16/09/19 08:30	Reinspection Photo	0	Load JPG	V
28	16/09/19 08:30	Reinspection Photo	0	Load JPG	V
29	16/09/19 08:30	Reinspection Photo	0	Load JPG	2
30	16/09/19 08:30	Reinspection Photo	0	Load JPG	2
50	20,00,20,00.00		- 0		
Doc	umentation		1 per	page 🔻	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	The state of the s	Thumbnail	-
1	09/07/19 09:48	PRI	0	Load PDF	
2	09/07/19 09:48	OI Accident Report	0	Load PDF	
3	09/07/19 09:48	TP SHC6292Z E-REPORT	0	Load PDF	
4	09/07/19 10:09	Acknowledge PRI	- 0	Load PDF	n .
No	Finalized On 09/07/19 10:49	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) Survey Request - Manual Assigned	0	Load PDF	Prir

# **Documents Checklist**

OCUMENTS CHECKLIST		Reset Save Prin
here are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultant	ts Pte Ltd (HQ)	
Show Remarks To: Handling Insurer lote: Remarks are private unless you show it to other parties.		

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19012060/K1QF3E2

Date: 02/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29114756

Claimant Vehicle No :

SHC6292Z

Insured Vehicle No:

SLK3596C

Date of Loss:

05/07/2019

Nature of Claim:

TP

Claim No: 599093

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SHC6292Z

Make & Model:

KIA OPTIMA, 1.7 D (A)

Engine No:

D4FDEH311816

Reg. Date: Colour: 25/11/2014 (Man. Year: 2014) Silver Chassis No: Odometer:

465965 km

KNAGM414MF5555235

Engine Capacity: Market Value/New Car

1685 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

res

CONDITION OF TYRES

Front Tyre Size:

205/65 R16

Rear Tyre Size:

205/65 R16

Front Left Side: Front Right Side: Hankook 7 mm Hankook 7 mm Rear Left Side: Rear Right Side: Hankook 7 mm Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,199.65	730.05	1,469.60	66.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,188.59	1,170.66	17.93	1.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,388.24	1,900.71	1,487.53	43.90
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	3,388.24	1,500.00	1,888.24	55.73
+ GST 7.00/7.00% (S\$)	237.18	105.00	132.18	55.73
Nett Amount (S\$)	3,625.42	1,605.00	2,020.42	55.73

INSPECTION

Date of Assignment:

09/07/2019

Date Inspected:

09/07/2019 Inspected At:

Premier Automotive Services Pte Ltd

(Changi)

23 Changi South Ave 2 #01-02

Singapore 486443

Estimated Period of Repair:

4.0 days

Adjuster: KALVIN ANG WEI KUN Manager: SHIAU CHAN

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Reference
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Oct 2019)

Parts: 143 KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC6292Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT FRONT DOOR	Buckled	761.00 FL	*761.00 FL
2	1		*R/F UPPER DOOR HINGE	Serviceable	34.00 FL	*-FL
3	1		*R/F LOWER DOOR HINGE	Serviceable	34.00 FL	*-FL
4	1		*R/F DOOR RR MOULDING (NPA)	Repair	0.00 FL	*-FL
5	1		*R/F UPP DOOR MLDG (NPA)	Serviceable	0.00 FL	*-FL
6	1		*R/R DOOR	Repair	791.00 FL	*-FL
7	1		*R/R UPPER DOOR HINGE	Serviceable	34.00 FL	*-FL
8	1		*R/R LOWER DOOR HINGE	Serviceable	34.00 FL	*-FL
9	1		*R/R DR FRM FRT TRIM (NPA)	Serviceable	0.00 FL	*-FL
10	1		*R/R DOOR FRM UP TRIM (NPA)	Serviceable	0.00 FL	*-FL
11	1		*R/R DOOR FRT MLDG (NPA)	Repair	0.00 FL	*-FL
12	1		*R/R UPP DOOR MLDG (NPA)	Serviceable	0.00 FL	*-FL
13	1		*R/SILL PANELLING	Repair	286.00 FL	*-FL
14	1		*REAR BUMPER	Repair	696.00 FL	*-FL
15	1		*R/R BUMPER BRACKET	Serviceable	29.00 FL	*-FL
16	1		*REAR BUMPER SPOILER	Serviceable	206.00 FL	*-FL
17	1		*R/R WHEEL COVER	Grazed	116.00 FL	*116.00 FL
18	1		*REAR BUMPER CLIPS	Not Necessary	48.00 FS	*-FS
19	1		*REAR R WING STICKER	Necessary	60.00 FS	*60.00 FS
20	1		*RH DOOR STICKERS	Necessary	100.00 FS	*100.00 FS
21	1		*RH SILL GARNISH CLIP	Not Necessary	28.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.			
				Sub Total (S\$)	3,257.00	1,037.00
			- List Item Discount on L Items	35.00/35.00% (S\$)_	1,057.35	306.95
				Total Parts (S\$)	2,199.65	730.05

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	108.0 WU X 50.00 SGD/H	New	540.00	540.00
2	LABOUR COST 93.0 WU X 50.00 SGD/H	New	465.00	465.00
3	MATERIAL COST	New	183.59	165.66
		Gross Labour Cost (S\$)	1,188.59	1,170.66
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >