

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19012081/K1PA3Q2

Date: 30/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHB8686M	Insured Vehicle No :	SHD3945M
Date of Loss: 05/07/2019	Nature of Claim:	TP Claim No: MCT19070130

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8686M		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU155972
Reg. Date:	14/02/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU129603
Colour:	Silver	Odometer:	43382 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	929.12	457.12	472.00	50.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,120.00	900.00	44.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,949.12	1,577.12	1,372.00	46.52
+ GST 7.00/7.00% (S\$)	206.44	110.40	96.04	46.52
Nett Amount (S\$)	3,155.56	1,687.52	1,468.04	46.52
+ Car Rental (4.0 x S\$126.26/day) (S\$)		505.04		
		(S\$)		
		2,192.56		
Liabile Amount (50.00%) (S\$)		1,096.28		
Global Sum Settlement (S\$)		1,090.00		

INSPECTION

Date of Assignment: 08/07/2019

Date Inspected: 08/07/2019 Inspected At:

Premier Automotive Services Pte Ltd
(HQ)
23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Nov 2019)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB8686M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*WHEEL COVER	Grazed	346.40 FL	*346.40 FL	
2	1		*REAR BUMPER	Repair	459.40 FL	*- FL	
3	1		*REAR BUMPER N/S SIDE BRACKET	Serviceable	33.10 FL	*- FL	
4	1		*SET REAR BUMPER CLIPS	Not Necessary	48.00 FS	*- FS	
5	1		*SET N/S DOOR STICKERS	Necessary	100.00 FS	*100.00 FS	
6	1		*REAR N/S FENDER STICKER	Necessary	60.00 FS	*60.00 FS	
7	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS	
					Sub Total (\$\$)	1,096.90	526.40
					- List Item Discount on L Items 20.00/20.00% (\$\$)	167.78	69.28
					Total Parts (\$\$)	929.12	457.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	0.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE REAR N/S DOOR ,N/S ROCKER PANEL GARNISH ,REAR N/S FENDER	New	950.00	400.00
3	TO PUTTY AND SPRAY PAINTING ON REAR N/S DOOR ,N/S ROCKER PANEL GARNISH ,REAR N/S FENDER ,REAR BUMPER	New	800.00	720.00
4	TO APPLY RUSTPROOF ON REPAIRED PANELS	New	150.00	0.00
Gross Labour Cost (\$\$)			2,020.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >