

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19012088/KBA3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SGH2832C

Insured Vehicle No : SMH2297B

Date of Loss: 01/07/2019

Nature of Claim: TP

Claim No: 4049683631SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGH2832C

Make & Model: DAIHATSU TERIOS, 1.5 4WD (A)

Engine No: 1601391

Reg. Date: 05/06/2006 (Man. Year: 2006)

Chassis No: JDAJ210G001007070

Colour: Metallic Black

Odometer: 167306 km

Engine Capacity: 1495 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/65 R16

Rear Tyre Size: 215/65 R16

Front Left Side: West Lake 9 mm

Rear Left Side: West Lake 9 mm

Front Right Side: West Lake 9 mm

Rear Right Side: West Lake 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,545.00	2,569.20	975.80	27.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	960.00	560.00	36.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,065.00	3,529.20	1,535.80	30.32
Approved Total (Overridden) (S\$)		3,150.00		
(S\$)	5,065.00	3,150.00	1,915.00	37.81
+ GST 7.00/7.00% (S\$)	354.55	220.50	134.05	37.81
Nett Amount (S\$)	5,419.55	3,370.50	2,049.05	37.81
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,612.50		

INSPECTION

Date of Assignment: 08/07/2019

Date Inspected: 09/07/2019 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A,
#01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE CHROME MOULDING (WCP)	Serviceable	200.00 F	*- F
2	2		*HEADLAMP LH & RH (WCP)	O/S Mtg Broken / N/SMtgCracked	1,120.00 F	*1,120.00 F
3	1		*FRONT BUMPER (WCP)	Bent	240.00 F	*240.00 F
4	2		*FRONT BUMPER SIDE RETAINER LH & RH (WCP)	Cracked	64.00 F	*64.00 F
5	15		*FRONT BUMPER CLIPS (WCP)	Necessary	45.00 F	*45.00 F
6	1		*FRONT BUMPER LOWER AIR GRILLE (WCP)	Cracked	120.00 F	*120.00 F
7	1		*FRONT BUMPER TOW COVER (WCP)	Missing	24.00 F	*24.00 F
8	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	280.00 F	*280.00 F
9	1		*FRONT FENDER LH (WCP)	Bent	190.00 F	*190.00 F
10	1		*FRONT FENDER COWLING (WCP)	Cracked	58.00 F	*58.00 F
11	8		*FRONT FENDER COWLING CLIPS (WCP)	Not Necessary	24.00 F	*- F
12	1		*FOGLAMP LH (WCP)	Serviceable	180.00 F	*- F
13	1		*FRONT BONNET (WCP)	Repair	380.00 F	*- F
14	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,960.00	2,141.00
+ Margin on L,N Items 20.00/20.00% (S\$)	585.00	428.20

Total Parts (S\$)	3,545.00	2,569.20
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD ,TO KNOCK & REPAIR FRONT BONNET ,FRONT FENDER RH ,FRONT WHEELHOUSE PANEL LH INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	600.00	400.00
4	TO SPRAY FRONT BONNET ,FRONT BUMPER ,FRONT FENDER LH & RH ,RADIATOR SUPPORT PANEL	New	800.00	540.00
Gross Labour Cost (\$\$)			1,520.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >