

REF:

CS/TP19012/04/Avd3n2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SDM3928M Yr Regn: 2005 JulyType: ☒ M. Car ☐ M. Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make: Honda Integra c.c. 1998Colour: Black A/C: ☐ Insured ☐ Std ☐ NI ☐ NASp. Reading 250313 T/Radio: ☐ Insured ☐ Std ☐ NI ☐ NA

Eng/No: _____

C/No: JHMDCS45055201212Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orModi: Nil ☒ S/Rim ☐ STD A/Rim orTyre Size: F: 225/45R17R: 225/45R17BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC ☐ OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. 28/6/19 D.O.I. 05/07/19Survey held at Hua MengDes. of Damages: ☒ Frt ☒ Rear ☐ O/S ☐ N/S ☐ UIC ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP HL Independent.

COE Expiry: 30/06/25.

SDM 3928M - FC3/A1919111782/KK43

DPA: 28/6/2019

SLA 8513L - CS/FC1/7007332/Lgh3n2

DPA: 1/7/2019

MV: 51K (Depreciation 8.51K).

PV: 44.7K

Nett: 6.3K.

RECEIVED 10 SEP 2019

18/9/19 LS \$12,400 (Red 14,681, sub)

Date/Time, File Pass to?

Date/Time, File Return to?

1) 18/9 - typist

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date: 17/10/255

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

1701 255

50

50

177

80

782



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Renewal Coe Toyota Vios 1.5A E

3.18% P.A \$0 Admin Fees At GV Finance, 2 Years Warranty. Monthly From \$488. 0% Credit, No L10 StarAd

AutoInn
An Inspiration For Car Buyers

click here to view our **PRISTINE USED CARS** at **GREAT PRICES**

Browse by Category Save Search Print Sort by Date Posted 20 results/page

| | | | | | | | | | | | | | | | | | |
|------------------|--|---------|--|---------|--|-----------------|--|------------------|--|----------|--|---------|--|----------|--|-----------|--|
| 3 vehicles | | Search | | Integra | | Advanced Search | | Search | | View All | | | | | | | |
| Make | | Model | | Price | | Depreciation | | Reg Date | | Eng Cap | | Mileage | | Veh Type | | Status | |
| Search Selection | | Integra | | Any | | Any | | > 10 year(s) old | | Any | | Any | | Any | | Available | |



☐ **Honda Integra 2.0A (COE till 05/2021)** \$15,888 \$8,330 /yr 06-Jun-2006 1,998 cc - Sports Available

Extremely Well Maintained Honda Integra Up For Sale. Comes In Lamborghini Yellow With Sporty Black Interior. Owner Selling To Upgrade. We Welcome STA/Vicom Inspection, Welcome Trade Ins. Attractive Loan Packages Available. Full Loan Possible. Why Wait? Call...

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|--------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 0545D |
| Vehicle Details | |
| Vehicle No.: | SDM3928M |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 05 Jul 2019 |
| Vehicle Make: | HONDA |
| Vehicle Model: | INTEGRA 2.0A |
| Primary Colour: | Black |
| Manufacturing Year: | 2005 |
| Engine No.: | K20A34800886 |
| Chassis No.: | JHMD545055201212 |
| Maximum Power Output: | 118.0 kW (158 bhp) |
| Open Market Value: | \$24,009.00 |
| Original Registration Date: | 02 Jul 2005 |
| First Registration Date: | 02 Jul 2005 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$26,410.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Forfeited |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 30 Jun 2025 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 10 |
| PQP Paid: | \$74,629.00 |
| COE Rebate Amount: | \$44,673.00 |
| Total Rebate Amount: | \$44,673.00 |

The information contained herein is correct as at 05 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 28/06/2019 17:55 |
| Date Of Accident | 28/06/2019 15:30 |
| Exact Location Of Accident | BEDOK SOUTH AVE 1 TWDS BEDOK NORTH ST 3 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SDM3928M |
| Insured/Policyholder | |
| Name Of Registered Owner | NG HOCK SING |
| NRIC No | S6900545D |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-96919556 |
| Alternative Phone No | OFFICE-96919556 |

Vehicle Particulars

| | |
|--|-------------|
| Manufacturer | HONDA |
| Model | INTEGRA |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage | THIRD PARTY FIRE AND/OR THEFT |
| Fleet Policy | NO |
| Policy Number | 2100148026 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | NG HOCK SING |
| NRIC No | S6900545D |
| Date Of Birth | 11/01/1969 |
| Occupation | INDOOR |
| Date Of Driving Pass | 16/06/1990 |
| Driving Experience | 29 YEARS AND 0 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96919556 |
| Fax Number | |
| Contact Number | OFFICE-96919556 |
| Email Address | NOEMAIL |

| | |
|---|----------------|
| Address | 74 FRANKEL AVE |
| Postcode | 458203 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-----------------|
| Type Of Accident | CHAIN COLLISION |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 3 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------|
| Vehicle Registration Number | SLA8513L |
| Vehicle Make/Model/Colour | |
| Details Of Properties | VEHICLE B |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|-----------------------------|---------|
| Vehicle Registration Number | SHD486R |
|-----------------------------|---------|

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

NG HOCK SING

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SDM3928M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

HQA MBN

SKETCH PLAN



(A) SDM 3928M

(B) SLA 8513L

(C) SHD 486R

Bedok North Avenue 1
towards Bedok North Street 3
(Before Bedok North Road Junction)


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

On 28.06.19 at about 15:30 hours, I was driving along Bedok North Avenue 1 towards Bedok North Street 3 (Before Bedok North Road Junction). I was travelling straight on the lane 2, when my front Vehicle (C) stopped hence I followed suit and my vehicle (A) came to a complete stop.

Suddenly I heard a loud bang from behind and the impact forced my vehicle (A) to move forward hit onto the rear portion of vehicle (C). When I alighted I realised it was vehicle (B) who hit my rear portion of my vehicle (A) causing damages to my front & rear portion of my vehicle (A). It was a chain collision of a total of 3 vehicles involved.

Vehicle (A): SDM 3928M

Vehicle (B): SLA 8513L

Vehicle (C): SHD 486R


Ng Hui Sing

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NG HOCK SING
74 FRANKEL AVENUE
S 458203

Veron.

Date :25.07.2019
Vehicle No :SDM 3928 M
Make/Model :HONDA INTEGRE
Accident date :28.06.2019

| No | DESCRIPTION | Qty | Amount (\$\$) |
|-------------------|--|-----|------------------------|
| <u>List Items</u> | | | |
| 1 | Rear bootlid <i>Dented</i> | 1 | \$ 993.3 ✓ |
| 2 | Rear bootlid hinges @ \$ 93.50 <i>new</i> | 2 | \$ 187 ✓ |
| 3 | Rear bootlid upper lock <i>Dented</i> | 1 | \$ 385 ✓ |
| 4 | Rear bootlid lower lock <i>new</i> | 1 | \$ 99 ✓ |
| 5 | Rear bootlid weather strip <i>cut</i> | 1 | \$ 121 ✓ |
| 6 | Rear bootlid Integra emblem <i>2</i> | 1 | \$ 50.6 ✓ |
| 7 | Rear bootlid H logo <i>new</i> | 1 | \$ 31.9 ✓ |
| 8 | Rear bootlid mugen emblem <i>new</i> | 1 | \$ 40.7 ✓ |
| 9 | Rear bootlid third brake lamp <i>new</i> | 1 | \$ 231 ✓ |
| 10 | Rear bootlid top spoiler <i>new</i> | 1 | \$ 1091.2 ✓ |
| 11 | Rear bootlid top spoiler bracket @ \$ 60.50 <i>new</i> | 2 | \$ 121 ✓ |
| 12 | Rear bootlid inner board <i>new</i> | 1 | \$ 264 ✓ |
| 13 | Rear bootlid inner handle <i>new</i> | 1 | \$ 209 ✓ |
| 14 | Rear bootlid shock absorber @ \$ 198.00 <i>new</i> | 2 | \$ 396 ✓ |
| 15 | Rear bootlid inner side garnish @ \$ 231.00 <i>new</i> | 2 | \$ 462 ✓ |
| 16 | Rear windscreen rubber <i>new</i> | 1 | \$ 198 ✓ |
| 17 | Rear end panel <i>Dented</i> | 1 | \$ 561 ✓ |
| 18 | Rear end panel inner top garnish <i>crushed</i> | 1 | \$ 121 ✓ |
| 19 | Rear lamp @ \$ 396.00 <i>crushed</i> | 2 | \$ 792 ✓ |
| 20 | Rear lamp housing @ \$ 159.50 <i>new</i> | 2 | \$ 319 ✓ |
| 21 | Rear lamp inner cover @ \$ 121.00 <i>new</i> | 2 | \$ 242 ✓ |
| 22 | Rear lamp lower bracket @ \$ 31.90 <i>new</i> | 2 | \$ 63.8 ✓ |
| 23 | Rear bumper <i>Dented</i> | 1 | \$ 953.7 ✓ |
| 24 | Rear bumper side holder @ \$ 46.20 <i>new</i> | 2 | \$ 92.4 ✓ |
| 25 | Rear bumper lower lip <i>Dented</i> | 1 | \$ 561 ✓ |
| 26 | Rear bumper reverse sensor (1 set) <i>Dented</i> | 1 | \$ 418 <i>200 (SN)</i> |
| 27 | Rear bumper clips (1 set) <i>new</i> | 1 | \$ 77 <i>30</i> |
| 28 | Rear number plate garnish <i>crushed</i> | 1 | \$ 209 ✓ |
| 29 | Rear number plate lamp @ \$ 61.60 <i>new</i> | 2 | \$ 123.2 ✓ |
| 30 | Rear number plate <i>Bent</i> | 1 | \$ 55 <i>30 (SN)</i> |
| 31 | Rear number plate holder <i>Dented</i> | 1 | \$ 55 <i>30 (SN)</i> |

9533.8

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NG HOCK SING
74 FRANKEL AVENUE
S 458203

Date :25.07.2019
Vehicle No :SDM 3928 M
Make/Model :HONDA INTEGRE
Accident date :28.06.2019

| No | DESCRIPTION | Qty | Amount (\$S) |
|---------------|--|-----|-------------------------|
| 32 | Rear spare tyre well top board <i>new</i> | 1 | \$ 187 <i>X</i> |
| 33 | Rear spare tyre well <i>Ris</i> | 1 | \$ 1485 <i>X</i> |
| 34 | Rear spare tyre well insulation @ \$ 121.00 <i>new</i> | 3 | \$ 363 <i>X</i> |
| 35 | Rear exhaust pipe <i>Bent</i> | 1 | \$ 616 <i>✓</i> |
| 36 | Rear exhaust pipe chrome <i>Bent</i> | 1 | \$ 198 <i>✓</i> |
| 37 | Rear fender @ \$ 913.00 <i>Ris</i> | 2 | \$ 1826 <i>+</i> |
| 38 | Rear fender inner trim @ \$ 352.00 <i>new</i> | 2 | \$ 704 <i>X</i> |
| 39 | Rear fender lower air vent <i>Cracked</i> | 1 | \$ 44 <i>✓</i> |
| 40 | Front oil cooler <i>Dented</i> | 1 | \$ 605 <i>✓</i> |
| 41 | Front susport panel <i>Ris</i> | 1 | \$ 506 <i>X</i> |
| 42 | Front bonnet <i>Dented</i> | 1 | \$ 1980 <i>1400(SN)</i> |
| 43 | Front boonet lock <i>new</i> | 1 | \$ 209 <i>+</i> |
| 44 | Front boonet lock bracket <i>new</i> | 1 | \$ 52.8 <i>+</i> |
| 45 | Front grille <i>Dented</i> | 1 | \$ 165 <i>✓</i> |
| 46 | Front grille logo <i>new</i> | 1 | \$ 28.6 <i>✓</i> |
| 47 | Front grille type S emblem <i>new</i> | 1 | \$ 41.8 <i>✓</i> |
| 48 | Front headlamp @ \$ 806.70 <i>cracked</i> | 2 | \$ 1613.4 <i>✓</i> |
| 49 | Front bumper <i>Deformed</i> | 1 | \$ 667.7 <i>✓</i> |
| 50 | Front bumper side holder @ \$ 50.60 <i>new</i> | 2 | \$ 101.2 <i>✓</i> |
| 51 | Front bumper lower lip <i>Deformed</i> | 1 | \$ 312.4 <i>✓</i> |
| 52 | Front bumper centre grille <i>new</i> | 1 | \$ 154 <i>+</i> |
| 53 | Front bumper side fog lamp garnish @ \$ 49.50 <i>new</i> | 2 | \$ 99 <i>+</i> |
| 54 | Front bumper reinforcement <i>Bent</i> | 1 | \$ 222.2 <i>✓</i> |
| 55 | Front bumper bracket @ \$ 49.50 <i>new</i> | 2 | \$ 99 <i>+</i> |
| 56 | Front bumper inner sponge <i>new</i> | 1 | \$ 49.5 <i>+</i> |
| 57 | Front fender @ \$ 858.00 <i>3 new</i> | 2 | \$ 1716 <i>✓</i> |
| 58 | Front fender inner shield @ \$ 114.40 <i>16227.5</i> | 2 | \$ 228.8 <i>X</i> |
| 59 | Front number plate <i>Bent</i> | 1 | \$ 55 <i>30(SN)</i> |
| 60 | Radiator <i>Dented</i> | 1 | \$ 1665.4 <i>✓</i> |
| 61 | Air con condenser <i>Bent</i> | 1 | \$ 832.7 <i>✓</i> |
| | | | \$ 26351.3 |
| Less 20% Disc | | | \$ 5270.3 |
| Total | | | \$ 21081.04 |

12254
9803.20

SN: 1690

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NG HOCK SING
74 FRANKEL AVENUE
S 458203

Date :25.07.2019
Vehicle No :SDM 3928 M
Make/Model :HONDA INTEGRE
Accident date :28.06.2019

| No | Description | Qty | Amount (\$\$) |
|--------------------|--|-----|---------------|
| Labour Cost | | | |
| 1 | Towing fee | | \$ 150 + |
| 2 | To supply rear windscreen sealant nll | | \$ 50 ✓ |
| 3 | Remove & reinstall rear widnscreen | | \$ 150-120 |
| 4 | Remove & reinstall bootlid inner garnish+roof lining | | \$ 200-20 |
| 5 | Remove & reisntall reverse sensor | | \$ 150-60 |
| 6 | Remove & reinstall exhaust pipe | | \$ 200-100 |
| 7 | Remove & reinstall air con fill in gas | | \$ 150-120 |
| 8 | Remove ,replace & repair consistent to the accident | | \$ 2800-1800 |
| 9 | Respray painting | | \$ 2000-1600 |
| 10 | Tuff kote | | \$ 150-100 |
| Total | | | \$ 6000 |
| Grand Total | | | \$ 27081.04 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 15523.20
2/5 : 12.4K
15 Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|----------------------------|------------|--|
| HUA MENG SPRAY PAINTING WORKSHOP | | Ref : CS/TP19012104/Avf3n2 | | |
| 1 KAKI BUKIT AVE 6 #01-61 AUTOBAYSINGAPORE 417883 | | Date : 24-09-2019 | | |
| ON BEHALF OF NG HOCK SING | | Code : TP127 | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | Veh. Inspected | | SDM 3928M | |
| Policy No. | Coverage (\$) | | 0.00 | |
| Claim No. | Excess (\$) | | 0.00 | |
| Assign From | Assign Date | | 05/07/2019 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HONDA INTEGRA | c.c | 1998 | |
| Engine No. | HIDDEN | Year of Reg. | 2005 | |
| Chassis No. | JHMDC54505S201212 | Colour | BLACK | |
| Odometer | 250313 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 225/45 R17 | MICHELIN | 6 mm | |
| L/H Front Tyre | 225/45 R17 | MICHELIN | 6 mm | |
| R/H Rear Tyre | 225/45 R17 | MICHELIN | 6 mm | |
| L/H Rear Tyre | 225/45 R17 | MICHELIN | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 28/06/2019 | Inspection Date | 05/07/2019 | |
| Survey held at | HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 15 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDM 3928M

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | REAR BOOTLID | DENTED | 993.30 | 993.30 |
| 2 | REAR BOOTLID HINGES @\$93.50 | NOT NECESSARY | 187.00 | - |
| 1 | REAR BOOTLID UPPER LOCK | DAMAGED | 385.00 | 385.00 |
| 1 | REAR BOOTLID LOWER LOCK | NOT NECESSARY | 99.00 | - |
| 1 | REAR BOOTLID WEATHER STRIP | CUT | 121.00 | 121.00 |
| 1 | REAR BOOTLID INTEGRA EMBLEM | NECESSARY | 50.60 | 50.60 |
| 1 | REAR BOOTLID H LOGO | NECESSARY | 31.90 | 31.90 |
| 1 | REAR BOOTLID MUGEN EMBLEM | NECESSARY | 40.70 | 40.70 |
| 1 | REAR BOOTLID THIRD BRAKE LAMP | NOT NECESSARY | 231.00 | - |
| 1 | REAR BOOTLID TOP SPOILER | NOT NECESSARY | 1,091.20 | - |
| 2 | REAR BOOTLID TOP SPOILER BRACKET @\$60.50 | NOT NECESSARY | 121.00 | - |
| 1 | REAR BOOTLID INNER BOARD | NOT NECESSARY | 264.00 | - |
| 1 | REAR BOOTLID INNER HANDLE | NOT NECESSARY | 209.00 | - |
| 2 | REAR BOOTLID SHOCK ABSORBER @\$198.00 | NOT NECESSARY | 396.00 | - |
| 2 | REAR BOOTLID INNER SIDE GARNISH @\$231.00 | NOT NECESSARY | 462.00 | - |
| 1 | REAR WINDSCREEN RUBBER | NECESSARY | 198.00 | 198.00 |
| 1 | REAR END PANEL | DENTED | 561.00 | 561.00 |
| 1 | REAR END PANEL INNER TOP GARNISH | CRACKED | 121.00 | 121.00 |
| 2 | REAR LAMP @\$396.00 | CRACKED | 792.00 | 792.00 |
| 2 | REAR LAMP HOUSING @\$159.50 | TO REPAIR SEE LABOUR | 319.00 | - |
| 2 | REAR LAMP INNER COVER @\$121.00 | NOT NECESSARY | 242.00 | - |
| 2 | REAR LAMP LOWER BRACKET @\$31.90 | NOT NECESSARY | 63.80 | - |
| 1 | REAR BUMPER | DEFORMED | 953.70 | 953.70 |
| 2 | REAR BUMPER SIDE HOLDER @\$46.20 | NECESSARY | 92.40 | 92.40 |
| 1 | REAR BUMPER LOWER LIP | DEFORMED | 561.00 | 561.00 |
| 1 | SET REAR BUMPER CLIPS | NECESSARY | 77.00 | 30.00 |
| 1 | REAR NUMBER PLATE GARNISH | CRACKED | 209.00 | 209.00 |
| 2 | REAR NUMBER PLATE LAMP @\$61.60 | NOT NECESSARY | 123.20 | - |
| 1 | REAR SPARE TYRE WELL TOP BOARD | NOT NECESSARY | 187.00 | - |
| 1 | REAR SPARE TYRE WELL | TO REPAIR SEE LABOUR | 1,485.00 | - |
| 3 | REAR SPARE TYRE WELL INSULATION @\$121.00 | NOT NECESSARY | 363.00 | - |
| 1 | REAR EXHAUST PIPE | BENT | 616.00 | 616.00 |

Report Ref No. CS/TP19012104/Avf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| 1 | REAR EXHAUST PIPE CHROME | BENT | 198.00 | 198.00 |
| 2 | REAR FENDER @\$913.00 | TO REPAIR SEE LABOUR | 1,826.00 | - |
| 2 | REAR FENDER INNER TRIM @\$352.00 | NOT NECESSARY | 704.00 | - |
| 1 | REAR FENDER LOWER AIR VENT | CRACKED | 44.00 | 44.00 |
| 1 | FRONT OIL COOLER | DENTED | 605.00 | 605.00 |
| 1 | FRONT SUPPORT PANEL | TO REPAIR SEE LABOUR | 506.00 | - |
| 1 | FRONT BONNET LOCK | NOT NECESSARY | 209.00 | - |
| 1 | FRONT BONNET LOCK BRACKET | NOT NECESSARY | 52.80 | - |
| 1 | FRONT GRILLE | DEFORMED | 165.00 | 165.00 |
| 1 | FRONT GRILLE LOGO | NECESSARY | 28.60 | 28.60 |
| 1 | FRONT GRILLE TYPE S EMBLEM | NECESSARY | 41.80 | 41.80 |
| 2 | FRONT HEADLAMP @\$806.70 | CRACKED | 1,613.40 | 1,613.40 |
| 1 | FRONT BUMPER | DEFORMED | 667.70 | 667.70 |
| 2 | FRONT BUMPER SIDE HOLDER @\$50.60 | NECESSARY | 101.20 | 101.20 |
| 1 | FRONT BUMPER LOWER LIP | DEFORMED | 312.40 | 312.40 |
| 1 | FRONT BUMPER CENTRE GRILLE | NOT NECESSARY | 154.00 | - |
| 2 | FRONT BUMPER SIDE FOG LAMP GARNISH @\$49.50 | NOT NECESSARY | 99.00 | - |
| 1 | FRONT BUMPER REINFORCEMENT | BENT | 222.20 | 222.20 |
| 2 | FRONT BUMPER BRACKET @\$49.50 | NOT NECESSARY | 99.00 | - |
| 1 | FRONT BUMPER INNER SPONGE | NOT NECESSARY | 49.50 | - |
| 2 | FRONT FENDER @\$858.00 | NOT NECESSARY | 1,716.00 | - |
| 2 | FRONT FENDER INNER SHIELD @\$114.40 | NOT NECESSARY | 228.80 | - |
| 1 | RADIATOR | DENTED | 1,665.40 | 1,665.40 |
| 1 | AIR CON CONDENSER | BENT | 832.70 | 832.70 |
| | LESS 20% DISCOUNT | | -4,757.66 | -2,450.80 |
| | | | 19,030.64 | 9,803.20 |
| 1 | SET REAR BUMPER REVERSE SENSOR (SN) | DAMAGED | 418.00 | 200.00 |
| 1 | REAR NUMBER PLATE (SN) | BENT | 55.00 | 30.00 |
| 1 | REAR NUMBER PLATE HOLDER (SN) | DEFORMED | 55.00 | 30.00 |
| 1 | FRONT BONNET (SN) | DEFORMED | 1,980.00 | 1,400.00 |
| 1 | FRONT NUMBER PLATE (SN) | BENT | 55.00 | 30.00 |
| | LESS 20% DISCOUNT | | -512.60 | - |
| | | | 2,050.40 | 1,690.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | REAR WINDSCREEN SEALANT (SN) | NECESSARY | 50.00 | 50.00 |
| | | | 50.00 | 50.00 |
| | <u>LABOUR</u> | | | |
| | TOWING FEE. | NOT NECESSARY | 150.00 | - |
| | REMOVE & REINSTALL REAR WINDSCREEN. | | 150.00 | 120.00 |
| | REMOVE & REINSTALL BOOTLID INNER GARNISH + ROOF LINING. | | 200.00 | 80.00 |
| | REMOVE & REINSTALL REVERSE SENSOR. | | 150.00 | 60.00 |
| | REMOVE & REINSTALL EXHAUST PIPE. | | 200.00 | 100.00 |
| | REMOVE & REINSTALL AIR CON FILL IN GAS. | | 150.00 | 120.00 |
| | REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR LAMP HOUSING,REAR SPARE TYRE WELL,REAR FENDER AND FRONT SUPPORT PANEL. | | 2,800.00 | 1,800.00 |
| | RESPRAY PAINTING. | | 2,000.00 | 1,600.00 |
| | TUFF KOTE. | | 150.00 | 100.00 |
| | | | 5,950.00 | 3,980.00 |
| | GRAND TOTAL | | 27,081.04 | 15,523.20 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 12,400.00 |

Report Ref No. CS/TP19012104/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.