

INS. CASE OWNER:

CC 4/AIG1901

LKK:
IDAC:

Surveyor:

DOE:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES/ NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
SUB 37955 teamwork	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☐ ☐
	Release Voucher:	☐ ☐
	Final Repair Bill:	☐ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA:	☐ ☐
Medical Bill:	☐ ☐	
PIR:	☐ ☐	
Mandate/Reject Instruction:	☐ ☐	
LOD:	☐ ☐	
Payment Breakdown Form:	☐ ☐	
Post-Repair Photos:	☐ ☐	
Others:	☐ ☐	
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	
Repair Cost: SS	(days) Reduction: %	Confirm by: Email ☐ Call ☐
FINAL SETTLEMENT Date/Time:	Confirm with:	
Final Liability: %	(Agreed / Assessed) BOLA S/N No.:	Email ☐ Call ☐
Repair Cost: SS	If NO or B 28, Ass. Lia:	
Loss of Rental (LOR): SS	(days)	
Loss of Use (LOU): SS	(\$ x days)	
Loss of Income (LOI): SS	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	SS	
Medical:	SS	
Disbursement:	(e.g. Tow/ Independent)	
Legal Cost	SS	
Total:	SS Global Sum SS:	
FINAL PAYMENT Date/Time:	Confirm with:	
Payee 1:	SS	Name 1:
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

180
+ 11
191

ASS. REC. BY:

REF:

AIG

K

ASSIGNMENT

From:

Date:

30/7/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLB 3795S

at Workshop m/s

Teamwork Garage

of

53ubi Ave 1 #01-24

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (cup)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLB3795S

Yr Regn.

05 Apr 2016

Type: M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda odyssey

2.4

C.C 2356

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

86791

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JH MRC 1890 Gc 203000

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/45 ZR18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIA / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

Survey held at

w/s

30-07-19

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / L&E (\$)

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(X) (3)Check (C)
(4)Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	Re	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	LH	CRA	-
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	/	
1159	993327	Rear End Panel	X	Repair	
1160	993339	Rear End Panel Top Garnish	Re	/	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	Repair	X	
1182	991328	Tailgate Emblem	Re	/	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No:

SLB37955

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items:

Assessor:

SLB37955 (2019)



Pte Ltd

AIG Singapore

78 Shenton Way

Singapore 079120

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475 Fax : 6844 2474

E-mail : claims@teamworkgarage.com

Register number : 201015366H

3RD PARTY CLAIM ESTIMATION

Vehicle number	:	SLB3795S
Make / Model	:	HONDA/ODYSSEY
Chassis number	:	JHMRC1890GC203000
Accident date	:	04 July 2019
Reference	:	1907-18

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE <i>x Repair</i>	1371.95
4	TAILGATE GLASS MOULING <i>x</i>	253.00
1	TAILGATE LOGO <i>-</i>	36.00
1	TAILGATE LOCK <i>x</i>	212.75
1	TAILGATE STRIKER <i>x</i>	40.25
1	TAILGATE WEATHERSTRIP <i>x</i>	134.43
1	TAILGATE LOWER CHROME GARNISH <i>x</i>	201.25
1	REAR BUMPER <i>-</i>	810.75
2	REAR BUMPER RETAINER <i>x</i>	57.50
1	REAR BUMPER REINFORCEMENT <i>x</i>	293.20
2	REAR BUMPER REFLECTOR <i>?</i>	106.49
1	END PANEL <i>?</i>	597.30
1	END PANEL TOP GARNISH <i>?</i>	262.20
		4377.07
Less 20%		875.41
Subtotal		3501.66
Balance C/F		3501.66
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		3501.66
1 SET	REAR BUMPER CLIP <i>- MC</i>	30.00
1 SET	REAR REVERSE SENSOR <i>?</i>	200 400.00
1	WINDSCREEN SEALANT <i>x</i>	150.00
1	JOINT SEALANT <i>x</i>	150.00
Subtotal		730.00
Balance C/F		4231.66
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
Balance B/F		4231.66
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	<i>x</i> 60.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	<i>40</i> 150.00
3	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	<i>?</i> 150.00
4	REMOVE AND STRAIGHTEN REAR EXHAUST	<i>x</i> 120.00
5	REMOVE AND REFIT REAR WINDSCREEN	<i>x</i> 120.00

6	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW		X	200.00	
7	PANEL BEATING ON AFFECTED AREAS	(300)	200	1000.00	
8	SPRAY PAINTING ON AFFECTED AREAS		400	900.00	
9	APPLY ANTI RUST ON AFFECTED AREAS		X	120.00	
	Subtotal			2820.00	
	Grand total			7051.66	

3-4 Days.

Imps repair.

After repair photos

Gmelina - 82880282

30/7/19.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	125F
Vehicle Details	
Vehicle No.:	SLB3795S
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	K24W72011347
Chassis No.:	JHMRC1890GC203000
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$30,530.00
Original Registration Date:	05 Apr 2016
First Registration Date:	05 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$34,742.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Apr 2026
PARF Rebate Amount:	\$26,056.00
Intended COE Rebate Details	
COE Expiry Date:	04 Apr 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,604.00
COE Rebate Amount:	\$31,801.00
Total Rebate Amount:	\$57,857.00

The information contained herein is correct as at 30 Jul 2019

OK

PRE-REPAIR INSPECTION REQUEST - SLB3795S vs SJA6001J (OI) on D.O.A.: 04/07/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Sent: 7/8/2019 4:41:03 PM
Attachments:  [lock.pdf](#) 2019_07_05_15_39_28.pdf

Hi,

Please refer to the enclosed request from **Teamwork Garage Pte Ltd**.

Claim no : 4933859308SG003
Case Owner : Wan Nur Saliha Binte Syed Yusoff

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations - Auto
Yinnul.Hor@aig.com | www.aig.sg

P. Darren
T. 4.46pm
v. out
G ✓

From: Darren [<mailto:claims@teamworkgarage.com>]
Sent: Monday, July 08, 2019 4:28 PM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLESJA6001J AND SLB3795S ON 04/07/2019

This message is from an external sender; be cautious with links and attachments.

Hi Yinnul,

Please appoint LKK

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Hor, Yinnul
Sent: Monday, 8 July 2019 4:30 PM
To: claims@teamworkgarage.com
Cc: [Fong, Andy-SY](#); [Chin, Lee-Ying](#); [Abu Kassim, Noor Mariesa](#); [Azlan, Syazairdina](#); [Chan, Yoke Shi](#); [Lim, Sheng Yang](#); [Mithoosingh, Aashweenjeetkaur](#); [Subramaniam, Divyashni](#); [Tong, Wahxin](#)
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLESJA6001J AND SLB3795S ON 04/07/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-07-15 16:30 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com

To: claims@teamworkgarage.com

Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashri.Subramaniam@aig.com, Wahxin.Tong@aig.com

Subject: aigencript PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJA6001J AND SLB3795S ON 04/07/2019

Date: Fri, 5 Jul 2019 08:29:44 +0000

Without Prejudice

Your Reference : 1907-18

Our Reference : 4933859308SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations - Auto

Yinrul.Hor@aig.com | www.aig.sg

From: TEAMWORK [mailto:claims@teamworkgarage.com]

Sent: Friday, July 05, 2019 3:40 PM

To: Hor, Yinrul; Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi

Cc: TEAMWORK

Subject: [EXTERNAL] OUR REF : 1907-18 // YOUR REF : SJA6001J ACCIDENT INVOLVING SJA6001J AND SLB3795S

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

OUR REF : 1907-18

YOUR REF : SJA6001J

Dear Sir / Madam,

PRE-REPAIR INSPECTION FOR SLB3795S

ACCIDENT INVOLVING SJA6001J AND SLB3795S ON 04.07.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regards,

Shu Shan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1

#01-24

• Paya Ubi Industrial Park

• Singapore 408934

• Tel: 6844 2475

Fax: 6844 2474

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jul 2019 Edit Reg		08 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	GOOI HONG PENG, ID: S1468349F		
Main Claimant:	THAM GIM CHUAN, ID: S2200125F		
Vehicle Reg. No.:	SLB3795S	Date of Loss:	04/07/2019 06:00 - :59 [38 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4933859308SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SJA6001J	Policy No. (Claimant):	SD18V03132/VPC2/R00
		Excess:	
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 18/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLB3795S (4933859308SG)**
[SJA6001J]

TP

THAM GIM CHUAN

Jul 4 2019 6:00AM

[GOOI HONG PENG]

Teamwork Garage Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/07/19 17:18	General View	 Load JPG	☒
2	31/07/19 17:18	General View	 Load JPG	☒
3	31/07/19 17:18	General View	 Load JPG	☒
4	31/07/19 17:18	General View	 Load JPG	☒
5	31/07/19 17:18	General View	 Load JPG	☒
6	31/07/19 17:18	General View	 Load JPG	☒
7	31/07/19 17:18	General View	 Load JPG	☒
8	31/07/19 17:18	General View	 Load JPG	☒
9	31/07/19 17:18	General View	 Load JPG	☒
10	31/07/19 17:18	General View	 Load JPG	☒
11	31/07/19 17:18	General View	 Load JPG	☒
12	31/07/19 17:18	General View	 Load JPG	☒
13	31/07/19 17:18	General View	 Load JPG	☒
14	31/07/19 17:18	General View	 Load JPG	☒
15	31/07/19 17:18	General View	 Load JPG	☒
16	31/07/19 17:18	General View	 Load JPG	☒
17	31/07/19 17:18	General View	 Load JPG	☒
18	31/07/19 17:18	General View	 Load JPG	☒
19	31/07/19 17:18	General View	 Load JPG	☒
20	31/07/19 17:18	General View	 Load JPG	☒
21	31/07/19 17:18	General View	 Load JPG	☒
22	31/07/19 17:18	General View	 Load JPG	☒
23	31/07/19 17:18	General View	 Load JPG	☒
24	31/07/19 17:18	General View	 Load JPG	☒
25	31/07/19 17:18	General View	 Load JPG	☒
26	31/07/19 17:18	General View	 Load JPG	☒
27	31/07/19 17:18	General View	 Load JPG	☒
28	31/07/19 17:18	Odometer Reading	 Load JPG	☒
29	31/07/19 17:18	Chassis Number	 Load JPG	☒
30	31/07/19 17:19	Dismantled Parts	 Load JPG	☒
31	31/07/19 17:19	Dismantled Parts	 Load JPG	☒
32	31/07/19 17:19	Dismantled Parts	 Load JPG	☒
33	31/07/19 17:19	Dismantled Parts	 Load JPG	☒
34	31/07/19 17:19	Dismantled Parts	 Load JPG	☒
35	31/07/19 17:19	Dismantled Parts	 Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
37	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
38	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
39	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
40	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
41	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
42	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
43	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
44	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
45	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
46	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
47	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
48	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
49	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
50	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
51	31/07/19 17:19	Dismantled Parts	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/07/19 16:35	EMAIL FROM AIG DD 08072019	 Load PDF	
2	09/07/19 16:35	TP GIA REPORT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/07/19 10:03	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19012124/GB3S2
Date: 05/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SLB3795S **Insured Vehicle No :** SJA6001J
 Date of Loss: 04/07/2019 Nature of Claim: TP Claim No: 4933859308SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB3795S**
 Make & Model: HONDA ODYSSEY, 2.3 (A) Engine No: K24W72011347
 Reg. Date: 05/04/2016 (Man. Year: 2016) Chassis No: JHMRC1890GC203000
 Colour: White Odometer: 86791 km
 Engine Capacity: 2356 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 ZR18 Rear Tyre Size: 235/45 ZR18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/07/2019
 Date Inspected: 30/07/2019 Inspected At: Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Lau Shu Pei

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER LH	Cracked	0.00 F	*- F
4	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
7	1		*TAILGATE	Repair	0.00 F	*- F
8	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >