

Driving License

1058341



S1551338A



APRIL 2001

APRIL 2001

23-06-1993

APT BLK 741 PASIR RIS STREET 71 #12-43
SINGAPORE 510741

APRIL 2001 S1551338A Date: 03/08/2001 (R)

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	1. Mar 1988
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	9. May 1984
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kg	20 Mar 1991
Class 5	Motor Vehicles which are not designed to carry any load and the weight of which unladen exceeds 2500 kg	12 Aug 1991

NP 426A

Identification Card



Accident Photo



Accident Photo



Driving License

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identification Number: **S2660220C**

Name: **RATHINA SABAPATHY SELVA PANDIAN**

Birth Date: **05 Jun 1967**

Issue Date: **12 Apr 2003**

900379354C

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S2660220C**



Name

RATHINA SABAPATHY SELVA PANDIAN

ரதீனா சபாபதி சேல்வா பந்தியன்

Race

INDIAN

Date of birth

05-06-1967

Sex

M

Country of birth

INDIA

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2000 kilograms

VALID DATE
30 May 2008

NP 429A

Licence No. **S2660220C**



4836231

NAME No. **S2660220C**



Date of issue
02-04-2013

Address

**71 PASIR RIS GROVE
#08-20
SINGAPORE 518205**

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Sketch Plan



Accident Sketch Plan

Enquire Vehicle & Owner Information (Vehicle No. SLR1150G As At 11 Apr 2018 / 20:00:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: MN.IG.S4.1812351

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S2660220C

Owner Name: RATHINA SABAPATHY SELVA PANDIAN

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 71

Registered Street Name: PASIR RIS GROVE

Registered Unit No.: # 08 - 20

Registered Building Name: -

Registered Postal Code: 518205

Current Vehicle Details

Vehicle No.: SLR1150G

Make Description/Model: VOLKSWAGEN / SPORTSVAN 1.4 HIGHLINE AM14HZ

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Sincerelead Garage Pte Ltd

38 Woodlands Industrial Park E1 #05-13 Singapore 757700

E-mail : sincerelead@hotmail.com

Fax : 62877949

Name : Supreme Container & Warehousing Pte Ltd

Date : 8-Nov-18

Address : c/o 38 Woodlands Industrial Park E1
#05-13
Singapore 757700

Final repair bill for UD Trucks XD 7036 X

To supply and replace parts, labour charges for
repairing, knocking, welding and to respray painting
(Lump Sum Repair)

\$ 9,600.00

Dollars : Nine Thousand Six Hundred Only

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 09-18016/DY / 2018
Date of Report : 8 Nov 2018

Supreme Container & Warehousing Pte Ltd
c/o 38 Woodlands Industrial Park E1
#05-13
Singapore 757700

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 11 Apr 2018

As per your instruction dated 17 Sep 2018 with regard to the above matter. We have
carried out a physical inspection on the said vehicle XD 7036 X . We enclosed herewith
our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : XD 7036 X
Model : UD Trucks
Year / Capacity : 2013/10837
Chassis No : GKB5E00109
Engine No : GH11711343
Mileage : 321375
Colour : Blue

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	295/80 R22.50	Good Year	6.00	mm	Normal
REAR	O/S	:	295/80 R22.50	Good Year	6.00	mm	Normal
FRONT	N/S	:	295/80 R22.50	Good Year	6.00	mm	Normal
REAR	N/S	:	295/80 R22.50	Good Year	6.00	mm	Normal

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 20100026SD

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the o/s front portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Sincerelead Garage Pte Ltd
38 Woodlands Industrial Park E1
#05-13
Singapore 757700

5. Estimated normal period of repair : 6 working days to complete.

6. Enclosed number of photograph : 114 copies.

7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: XD 7036 X
Report No: TP/ 09-18016/DY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front headlamp	Damage	\$ 1769.20	\$ 1769.20 780
1	Front corner panel	Damage	\$ 718.68	\$ X 718.68 nn
1	Front side mirror stay	Intact	\$ 500.85	\$ nn
1	Front bumper	Intact	\$ 2030.00	\$ nn
1	Front bumper fog lamp	Damage	\$ 520.68	\$ 520.68 43
1	Front bumper signal lamp	Damage	\$ 296.00	\$ 296.00 43
1	Front side bumper	Damage	\$ 906.60	\$ X 906.60 repair
1	Front side bumper protector	Damage	\$ 99.20	\$ 99.20
1	Front door	Damage	\$ 3432.55	\$ 3432.55
1	Front door rubber	Necessary	\$ 394.75	\$ X 394.75 nn
1	Front door checker	Damage	\$ 22.50	\$ X 22.50
1	Front door signal lamp	Damage	\$ 48.00	\$ 48.00
2	Front door hinges	Damage	\$ 309.00	\$ X 309.00 nn
1	Front door GK17420 emblem	Necessary	\$ 90.00	\$ 90.00
1	Front door lock	Damage	\$ 52.50	\$ X 52.50
1	Front step bracket	Damage	\$ 183.00	\$ X 183.00
1	Front top step aluminium panel	Damage	\$ 385.50	\$ X 385.50
1	Front lower step aluminium panel	Damage	\$ 163.50	\$ X 163.50 nn
1	Front top step garnish	Damage	\$ 202.50	\$ X 202.50
1	Front lower step garnish	Damage	\$ 351.00	\$ X 351.00
1	Front door regulator	Damage	\$ 390.00	\$ X 390.00
1	Front door regulator motor	Damage	\$ 250.50	\$ X 250.50
1	Front door inner trim board	Damage	\$ 73.50	\$ 73.50
1	Front door pillar	Repair	\$ 465.00	\$
			\$ 13655.01	\$ 10659.16
	Discount	10.0%	\$ 1365.50	\$ 1065.92
			\$ 12289.51	\$ 9593.24

4609.25

10%, 4148.33

Spare Parts Total \$ 12289.51 \$ 9593.24

Vehicle No: XD 7036 X
Report No: TP/ 09-18016/DY / 2018


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 12289.51	\$ 9593.24
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 100.00	\$ 40.00 30
2	To remove and refit the door lock mechanism, regulator gear, window glass, handle, inner board, hinges, channel to facilitate the repairs.	\$ 150.00	\$ 120.00 60
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1500.00	\$ 1000.00 400
4	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1500.00	\$ 1250.00 500
			990
Total		<u>\$ 15539.51</u>	<u>\$ 12003.24</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 9600.00

SDLS: NINE THOUSAND SIX HUNDRED ONLY


Qualified Appraiser

538.33
20%: 4100
4 Days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Apr 2018		18 Apr 2018 17:17 Edit Adj Rpt	S\$4,100.00 Edit Estimates	S\$4,100.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

CLAIM SUBFOLDER DETAILS				[Created by: Insured]
Insured:	RATHINA SABAPATHY SELVA PANDIAN, ID: S2660220C, Tel: +6598627120, Email: pandian@synopsys.com			
Main Claimant:	SUPREME CONTAINER & WAREHOUSING PTE LTD, Co. Reg. No.: 197903711Z			
Vehicle Reg. No.:	XD7036X	Date of Loss:	11/04/2018 20:00 - :59 [59 Months and 8 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 555402	Policy/Cover Note No.:	A29001393AVW (Comprehensive) Coverage: 31/07/2017 - 30/07/2018	
Vehicle Reg. No. (Insured):	SLR1150G	Policy No. (Claimant):		
		Excess:	S\$500.00	
Repairer:	Sincerelead Garage Pte Ltd (HQ) 38 WOODLANDS INDUSTRIAL PARK E1, #05-13, 757700 Woodlands - Tel: 9815 8858 / 8510 9999			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 27/06/2019]			
Driver/Custodian (Insured):	RATHINA SABAPATHY SELVA PANDIAN (50 / Male), NRIC: S2660220C, Tel: +6598627120 Email: pandian@synopsys.com			
Adj Asg. Remarks:	Venue will be at 38 Woodlands Industrial Park E1, #05-13 (SincereLead Garage Pte Ltd). Contact Person- Xiao Fong/ Raymond @ 8510-9999/9815-8858.			

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- MSIG_SG (25/06/2019): Report Send Back Alerts - XD7036X (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***XD7036X (555402)**
[SLR1150G]

TP

SUPREME CONTAINER & WAREHOUSING PTE LTD

Apr 11 2018 8:00PM

[RATHINA SABAPATHY SELVA PANDIAN]

Sincerelead Garage Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page ☐	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	18/04/18 17:18	Accident Statement From: OD - Reg. No: SLR1150G, Claimant: RATHINA SABAPATHY SELVA PANDIAN		Load HTM
Photos/Images			3 per page ☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	19/09/18 08:58	General View		Load JPG ☒
2	19/09/18 08:58	General View		Load JPG ☒
3	19/09/18 08:58	General View		Load JPG ☒
4	19/09/18 08:58	General View		Load JPG ☒
5	19/09/18 08:58	General View		Load JPG ☒
6	19/09/18 08:58	General View		Load JPG ☒
7	19/09/18 08:58	General View		Load JPG ☒
8	19/09/18 08:58	General View		Load JPG ☒
9	19/09/18 08:58	General View		Load JPG ☒
10	19/09/18 08:58	General View		Load JPG ☒
11	19/09/18 08:58	General View		Load JPG ☒
12	19/09/18 08:58	General View		Load JPG ☒
13	19/09/18 08:58	General View		Load JPG ☒
14	19/09/18 08:58	General View		Load JPG ☒
15	19/09/18 08:58	General View		Load JPG ☒
16	19/09/18 08:58	General View		Load JPG ☒
17	19/09/18 08:58	General View		Load JPG ☒
18	19/09/18 08:58	General View		Load JPG ☒
19	19/09/18 08:58	General View		Load JPG ☒
20	19/09/18 08:59	Odometer Reading		Load JPG ☒
21	19/09/18 09:00	Dismantled Parts		Load JPG ☒
22	19/09/18 09:00	Dismantled Parts		Load JPG ☒
23	19/09/18 09:00	Dismantled Parts		Load JPG ☒
24	19/09/18 09:00	Dismantled Parts		Load JPG ☒
25	19/09/18 09:00	Dismantled Parts		Load JPG ☒
26	19/09/18 09:00	Dismantled Parts		Load JPG ☒
27	19/09/18 09:00	Dismantled Parts		Load JPG ☒
28	19/09/18 09:00	Dismantled Parts		Load JPG ☒
29	19/09/18 09:00	Dismantled Parts		Load JPG ☒
30	19/09/18 09:00	Dismantled Parts		Load JPG ☒
31	19/09/18 09:00	Dismantled Parts		Load JPG ☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	19/09/18 09:00	Dismantled Parts		☒
33	19/09/18 09:00	Dismantled Parts		☒
34	19/09/18 09:00	Dismantled Parts		☒
35	19/09/18 09:00	Dismantled Parts		☒
36	19/09/18 09:00	Dismantled Parts		☒
37	19/09/18 09:00	Dismantled Parts		☒
38	19/09/18 09:00	Dismantled Parts		☒
39	19/09/18 09:00	Dismantled Parts		☒
40	19/09/18 09:00	Dismantled Parts		☒
41	19/09/18 09:00	Dismantled Parts		☒
42	19/09/18 09:00	Dismantled Parts		☒
43	19/09/18 09:00	Dismantled Parts		☒
44	19/09/18 09:00	Dismantled Parts		☒
45	19/09/18 09:00	Dismantled Parts		☒
46	19/09/18 09:00	Dismantled Parts		☒
47	19/09/18 09:00	Dismantled Parts		☒
48	19/09/18 09:00	Dismantled Parts		☒
49	19/09/18 09:00	Dismantled Parts		☒
50	19/09/18 09:00	Dismantled Parts		☒
51	19/09/18 09:00	Dismantled Parts		☒
52	19/09/18 09:00	Dismantled Parts		☒
53	19/09/18 09:00	Dismantled Parts		☒
54	19/09/18 09:00	Dismantled Parts		☒
55	19/09/18 09:00	Dismantled Parts		☒
56	19/09/18 09:00	Dismantled Parts		☒
57	19/09/18 09:00	Dismantled Parts		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/04/18 17:16	TPD XD7036X GIA REPORT.pdf		☒
2	19/12/18 17:45	LOD WITH SUPPORT DOCS		☒
3	25/02/19 12:35	TPD XD7036X - REQ FOR COLORED SURVEY PHOTOGRAPHS		☒
4	22/04/19 16:56	TPD XD7036X - ENCL COLORED SURVEY PHOTOS 1		☒
5	22/04/19 16:56	TPD XD7036X - COLORED SURVEY PHOTOS 1		☒
6	22/04/19 16:57	TPD XD7036X - ENCL COLORED SURVEY PHOTOS 2 + 10 DAYS NOTICE		☒
7	22/04/19 16:57	TPD XD7036X - COLORED SURVEY PHOTOS 2		☒
8	10/07/19 11:51	Vehicle Survey Report of XD7036X		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/07/19 14:20	PRS INVOICE		☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18007239/GQF3S2-1
Date: 23/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29001393AVW

Claimant Vehicle No: XD7036X

Insured Vehicle No: SLR1150G

Date of Loss: 11/04/2018

Nature of Claim: TP

Claim No: 555402

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD7036X

Make & Model: UD TRUCKS QUON GK, 10.8 D GKB5ELDHNT (M)

Engine No: GH11711343

Reg. Date: 03/05/2013 (Man. Year: 2013)

Chassis No: GKB5E00109

Colour: Blue

Odometer: 321375 km

Engine Capacity: 10837 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5

Rear Tyre Size: 295/80R22.5 (D)

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6/6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,289.51	4,148.32	8,141.19	66.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	990.00	2,260.00	69.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,539.51	5,138.32	10,401.19	66.93
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	15,539.51	4,100.00	11,439.51	73.62

INSPECTION

Date of Assignment: 18/04/2018

Date Inspected: 17/09/2018 Inspected At:

Sincerelead Garage Pte Ltd (HQ)
38 WOODLANDS INDUSTRIAL PARK E1, #05-13
Singapore 757700

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Jul 2019)	
Parts:	N/A	UD TRUCKS QUON GK 10.8 D GKB5ELDHNT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD7036X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP	Damaged	1,769.20 FL	*780.00 FL
2	1		*FRONT CORNER PANEL	Not Necessary	718.68 FL	*- FL
3	1		*FRONT SIDE MIRROR STAY	Not Necessary	500.85 FL	*- FL
4	1		*FRONT BUMPER	Not Necessary	2,030.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP	Damaged	520.68 FL	*43.00 FL
6	1		*FRONT BUMPER SIGNAL LAMP	Damaged	296.00 FL	*43.00 FL
7	1		*FRONT SIDE BUMPER	Repair	906.60 FL	*- FL
8	1		*FRONT SIDE BUMPER PROTECTOR	Damaged	99.20 FL	*99.20 FL
9	1		*FRONT DOOR	Damaged	3,432.55 FL	*3,432.55 FL
10	1		*FRONT DOOR RUBBER	Not Necessary	394.75 FL	*- FL
11	1		*FRONT DOOR CHECKER	Not Necessary	22.50 FL	*- FL
12	1		*FRONT DOOR SIGNAL LAMP	Damaged	48.00 FL	*48.00 FL
13	2		*FRONT DOOR HINGES	Not Necessary	309.00 FL	*- FL
14	1		*FRONT DOOR GK17420 EMBLEM	Necessary	90.00 FL	*90.00 FL
15	1		*FRONT DOOR LOCK	Not Necessary	52.50 FL	*- FL
16	1		*FRONT STEP BRACKET	Not Necessary	183.00 FL	*- FL
17	1		*FRONT TOP STEP ALUMINIUM PANEL	Not Necessary	385.50 FL	*- FL
18	1		*FRONT LOWER STEP ALUMINIUM PANEL	Not Necessary	163.50 FL	*- FL
19	1		*FRONT TOP STEP GARNISH	Not Necessary	202.50 FL	*- FL
20	1		*FRONT LOWER STEP GARNISH	Not Necessary	351.00 FL	*- FL
21	1		*FRONT DOOR REGULATOR	Not Necessary	390.00 FL	*- FL
22	1		*FRONT DOOR REGULATOR MOTOR	Not Necessary	250.50 FL	*- FL
23	1		*FRONT DOOR INNER TRIM BOARD	Damaged	73.50 FL	*73.50 FL
24	1		*FRONT DOOR PILLAR	Repair	465.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	13,655.01	4,609.25
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,365.50	460.93
Total Parts (\$\$)	12,289.51	4,148.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.	New	100.00	30.00
2	TO REMOVE AND REFIT THE DOOR LOCK MECHANISM, REGULATOR GEAR, WINDOW GLASS, HANDLE, INNER BOARD, HINGES, CHANNEL TO FACILITATE THE REPAIRS.	New	150.00	60.00
3	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	1,500.00	400.00
4	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS THE PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	1,500.00	500.00
Gross Labour Cost (\$\$)			3,250.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >