

ASS. REC. BY:

REF: CS/CTI 19012139/EV43<sup>02</sup>

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 9/7/2019 @ 5:11pm

Estimated Cost: Bill to:

OD /  WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLL 1509M Insured: YM 6737D

at Workshop m/s CYS Automobile Tel: 6219 2098

of 38 woodlands Ind. Park #07-17

Policy No: Claim No: SNM 19D203218

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 9/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:40am @ 11/7/19 Person Contacted: Esther Vehicle:  IN  OUT

Date/Time	Action/Instruction	Estimated	✓
	SLL 1509M - X		
	YM 6737 D - CC4 / FWP 19013665 / Veh 3		ROD - 09/07/2018
23/7/19	Final fig \$ 7939.28 confirmed by email (Red 3708.52, 3290)		

INSPECTED BY: Steve

DATE: CTI

### ASSIGNMENT

From: \_\_\_\_\_ Date: 11/7/2019

Veh No: SLL 1509M Reg: 15/02/17

Estimated Cost: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: SLL 1509M

Make: Honda Vezel c.c. 1496

at Workshop in/s: CYS Automobile

Colour: Brown A/C: Insured / Std / NI / NA

of 38 woodlands Ind. park E1 # 07-17

Sp. Reading: 76262 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: \_\_\_\_\_

Policy No. \_\_\_\_\_

C/No: RU 11 209480

Claims No. \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: Car In Ready

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 215/60R16

R: "1"

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Bal. or Market Value: \_\_\_\_\_

Front

Rear

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

R/Bal. 5 mm

R/Bal. 5 mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. 5 mm

L/Bal. 5 mm

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

D.O.A. 9/7/19

D.O.I. 11/7/19

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Survey held at CYS Automobile

CA / REV / REP. / 24 HRS <sup>1up</sup>

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - 71K
22/7/19	Final amount \$7939.28, 7 days

RECEIVED 24 JUL 2019

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 7

1)

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2) 23/7 - typist

Add Fee:  : Site Insp \$

Transportation:

Report Format:

merimen

: Interview \$

3 + 45.00

Empy Form / File to:

P/P \$7939.28

: Tech. Insp \$

Choice

: Wash eng \$

Other

220

## Nivitha (LKK Auto)

---

**From:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Sent:** Wednesday, 10 July 2019 5:18 PM  
**To:** assignments  
**Subject:** FW: OUR REF: SNM19D203218/CHONGBS - YM6737D - FW: ARRANGE FOR SURVEY

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Wednesday, 10 July 2019 5:11 PM  
**To:** CYS Auto, Woodlands <cysauto@singnet.com.sg>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: OUR REF: SNM19D203218/CHONGBS - YM6737D - FW: ARRANGE FOR SURVEY

**WITHOUT PREJUDICE**

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** CYS Auto, Woodlands [<mailto:cysauto@singnet.com.sg>]  
**Sent:** Wednesday, 10 July, 2019 5:08 PM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

Cc: [sur@lkkauto.com](mailto:sur@lkkauto.com)

Subject: RE: OUR REF: SNM19D203218/CHONGBS - YM6737D - FW: ARRANGE FOR SURVEY

Hi officer,

We would like chua weijie to survey this vehicle.

Vehicle is already in 38 WOODLANDS INDUSTRIAL PARK E1 #07-17 (S) 757700

THANKS

Regards,  
Esther Lim  
CYS  
62192098

---

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Wednesday, 10 July, 2019 5:02 PM

To: [cysauto@singnet.com.sg](mailto:cysauto@singnet.com.sg)

Subject: RE: OUR REF: SNM19D203218/CHONGBS - YM6737D - FW: ARRANGE FOR SURVEY

**WITHOUT PREJUDICE**

Dear Mr Sim,

We refer to your email below.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert

**Chong Boon Sen**

Claims Executive  
Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](http://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** CYS Auto, Woodlands [<mailto:cysauto@singnet.com.sg>]  
**Sent:** Wednesday, 10 July, 2019 1:45 PM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Subject:** ARRANGE FOR SURVEY

Dear Officer,

**ACCIDENT INVOVLING SLL1509M & YM6737D ON 09.JUL.19 ALONG NICOLE HIGHWAY  
TWDS KPE**

Kindly help me to arrange for a surveyor for my client's vehicle SLL1509M against your insured YM6737D .

Do let me have 10 surveyor firm list to choose from.

Kindly also let me have the officer in charge of this case as well as the liability.

Vehicle is already in 38, WOODLANDS INDUSTRIAL PARK E1 #07-17 (S ) 757700

Attached will be the GIA report as well as the ESTIMATE.

Thanks.

Regards,  
Esther Lim  
CYS AUTOMOBILE SERVICES PTE LTD  
TEL: 62192098

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 23 July 2019 4:22 PM  
**To:** CYSAUTO; SUR  
**Subject:** RE: SLL 1509M-DOA: 9/7/2019 - CONFIRMED REPAIR COST AT \$7,939.28

Dear Hui Xin,

Noted with thanks.

**Kindly send Final invoice and all supporting documents directly to CHINA TAIPING**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CYSAUTO <cysauto@singnet.com.sg>  
**Sent:** Tuesday, 23 July 2019 2:59 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** RE: SLL 1509M-DOA: 9/7/2019 - CONFIRMED REPAIR COST AT \$7,939.28

Dear Ms Veron Chen,

**WITHOUT PREJUDICE**

Confirmed with thanks

Regards,  
Hui Xin



**CYS AUTOMOBILE SERVICES PTE LTD**

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: [cysauto@singnet.com.sg](mailto:cysauto@singnet.com.sg)

---

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Tuesday, July 23, 2019 2:42 PM  
**To:** CYSAUTO <cysauto@singnet.com.sg>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** SLL 1509M-DOA: 9/7/2019

Dear Hui Xin,

Finalize amount \$7939.28 @ 7 working days.

PARTS-\$6714.10 (less 20%)=5371.28  
SN-\$308  
LABOUR-\$2260  
TOTAL-\$7939.28

Please check and confirm

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5264C
Vehicle Details	
Vehicle No.:	SLL1509M
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	L15B4409480
Chassis No.:	RU11209480
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,472.00
Original Registration Date:	15 Feb 2017
First Registration Date:	15 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$10,661.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Feb 2027
PARF Rebate Amount:	\$7,995.00
Intended COE Rebate Details	
COE Expiry Date:	14 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,401.00
COE Rebate Amount:	\$36,747.00
<b>Total Rebate Amount:</b>	<b>\$44,742.00</b>

The information contained herein is correct as at 11 Jul 2019

OK



進友成汽車服務私人有限公司  
**CYS Automobile Services Pte Ltd**

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR SHEN QIAN  
 BLK 621 WOODLANDS DRIVE 52  
 #02-52 (S) 730621

POLICY NO : THIRD PARTY CLAIM  
 YOUR REF : YM6737D (CHINA)  
 OUR REF : TP 6046  
 VEHICLE NO : SLL1509M  
 MAKE/MODEL : HONDA VEZEL  
 DATE OF ACCIDENT : 09.Jul.19

SURVEY BY

DATE : 10.Jul.19

1	PC TAILGATE /	DD		S\$	1,500.50	1100 ✓
1	PC TAILGATE GLASS /	GR			1,450.70	/
1	PC TAILGATE MOULDING /	RPC			158.60	/
1	PC TAILGATE GARNISH /	GR			198.10	/
1	PC TAILGATE REFLECTOR L/H /	GR			290.10	/
2	PCS TAILGATE NO PLATE LAMP	X	NMI	48.56	97.12	X
1	PC TAILGATE WIPER ARM	X	NMI		90.60	X
1	PC TAILGATE WIPER MOTOR	X	NMI		225.60	X
1	PC TAILGATE "H" EMBLEM /	MC			24.70	/
1	PC TAILGATE VEZEL EMBLEM /	RPC			74.60	/
2	PCS TAILGATE ABSORBER	X	NMI	180.40	360.80	X
1	PC TAILGATE TOP LOCK /	BT	NMI		190.50	/
1	PC TAILGATE LOWER LOCK	X	NMI		37.40	X
1	PC TAILGATE STOPPER L/H	X	NMI		23.30	X
1	PC TAILGATE WEATHERSTRIP /	TN			105.80	/
1	PC TAILGATE INNER TRIM BOARD	?	GR		235.10	/
1	PC TAILLAMP ASSY L/H /	GR			598.20	529 ✓
1	PC TAILLAMP PANEL L/H	X	R		145.90	X
1	PC REAR BUMPER /	DD			1,163.20	801.79 ✓
2	PCS REAR BUMPER SIDE RETAINERS	/	GR	38.00	76.00	/
1	PC REAR BUMPER REFLECTOR	?	GR		145.00	/
1	PC REAR BUMPER SIDE (LH)	/	CR4		198.00	/
1	PC REAR END PANEL	?	DD		511.90	/
1	PC REAR END PANEL TOP GARNISH	/	CR4		92.80	/
1	PC REAR FENDER L/H	X	R		900.10	X
1	PC REAR FENDER INNER TRIM BOARD L/H	/	CR4		295.50	/
1	PC REAR FENDER ARCH GARNISH L/H	/	CR4		150.90	/
1	PC ROCKER PANEL GARNISH L/H	X	NMI		377.50	X
1	PC SPARE TYRE FLOOR PANEL LOWER COVER	?	X	NMI	190.00	X
				S\$	9,908.52	
					1,981.70	
				S\$	7,926.82	

*Signature*  
 (27/19)

Steve CLKK) with papu die, 11/7/19 LESS 20%  
 P/P 12.30pm  
 Roy before spy  
 7 days

6629  
 - 292  
 5303.29



進友成汽車服務私人有限公司  
**CYS Automobile Services Pte Ltd**

ROC Reg. No : A05041/2001E


GST Reg. NO: 20-0105041-E

1 SET REAR BUMPER CLIPS	✓ nec	S\$	28.00 / "S/NETT"
1 PC TAILLAMP CLIP L/H	✓ nn		4.90 X "
1 SET SPARE TYRE FLOOR PANEL LOWER COVER CLIPS	nec		30.00 20/ "
1 SET REVERSE SENSOR	✓ OR	200 ✓	350.00 "
2, PC SEALANT	nec		80.00 40/ "
	40.00	S\$	492.90 288

TO CHECK WIRING FUNCTION		S\$	30.00 ✓
TO REMOVE AND CAMERA			60.00 29
TO TRANSFER TAILGATE			70.00 30
TO REMOVE AND REFIX TAILGATE GLASS	Supp - 88.08		140.00 100
TO REMOVE AND REFIX PETROL TANK	N - 288		80.00 X
TO PUT PUTTY ON REMOVE/REFIX PANEL	L - 2269		100.00 50
TO REMOVE AND REFIX CUSHION SEATS	7939.28		80.00 30
TO VACCUM ALL THE BROKEN GLASS AND CLEAN			100.00 50
LABOUR CHARGES			1,200.00 1000
TO PUTTY AND SPRAY PAINTING CHARGES			1,200.00 950
	11,647.80	S\$	<u>11,479.72</u> 2260

SIN DOLLARS: ELEVEN THOUSAND FOUR HUNDRED SEVENTY-NINE AND CENTS SEVENTY-TWO ONLY.

YOUR FAITHFULLY,

  
 \_\_\_\_\_  
 CYS AUTOMOBILE SERVICES PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



進友成汽車服務私人有限公司  
**CYS Automobile Services Pte Ltd**

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR SHEN QIAN  
 BLK. 621 WOODLANDS DRIVE 52  
 #02-52 SINGAPORE 730621

POLICY NO : THIRD PARTY CLAIM  
 YOUR REF : YM 6737 D (CHINA)  
 OUR REF : TP 6046  
 VEHICLE NO : SLL 1509 M  
 MAKE/MODEL : HONDA VEZEL  
 DATE OF ACCIDENT : 09.07.19

SURVEY BY

*Steve 12/7/19*

DATE : 12.07.19

**SUPPLEMENTARY**

1 PC BUZZER	<i>OR</i>		S\$	85.10	
		LESS 20%		17.02	
			S\$	68.08	<i>✓</i>
1 PC DECAL	<i>APC</i>		S\$	20.00	S/NETT <i>✓</i>
LABOUR CHARGES TO SENT IDAC FOR DECAL			S\$	80.00	<i>X</i>
			<u>S\$</u>	<u>168.08</u>	<i>88.08</i>

SIN DOLLARS: ONE HUNDRED SIXTY-EIGHT AND CENTS EIGHT ONLY

YOUR FAITHFULLY,

*[Signature]*  
 \_\_\_\_\_  
 CYS AUTOMOBILE SERVICES PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119012139/EVF3N2

Date: 29/07/2019

**REFERENCE**

<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	DMCVSN18323118000		
<b>Claimant Vehicle No :</b>	SLL1509M	<b>Insured Vehicle No :</b>	YM6737D		
<b>Date of Loss:</b>	09/07/2019	<b>Nature of Claim:</b>	TP	<b>Claim No:</b>	SNM19D203218C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	SLL1509M		
<b>Make &amp; Model:</b>	HONDA VEZEL, 1.5 (A)	<b>Engine No:</b>	L15B4409480
<b>Reg. Date:</b>	15/02/2017 (Man. Year: 2016)	<b>Chassis No:</b>	RU11209480
<b>Colour:</b>	Brown	<b>Odometer:</b>	76262 km
<b>Engine Capacity:</b>	1496 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>		<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	215/60R16	<b>Rear Tyre Size:</b>	215/60R16
<b>Front Left Side:</b>	Falken 5 mm	<b>Rear Left Side:</b>	Falken 5 mm
<b>Front Right Side:</b>	Falken 5 mm	<b>Rear Right Side:</b>	Falken 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,507.80	5,679.28	2,828.52	33.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	2,260.00	880.00	28.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,647.80</b>	<b>7,939.28</b>	<b>3,708.52</b>	<b>31.84</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>815.35</b>	<b>555.75</b>	<b>259.60</b>	<b>31.84</b>
<b>Nett Amount (S\$)</b>	<b>12,463.15</b>	<b>8,495.03</b>	<b>3,968.12</b>	<b>31.84</b>

**INSPECTION**

<b>Date of Assignment:</b>	12/07/2019	
<b>Date Inspected:</b>	11/07/2019	<b>Inspected At:</b>
		CYS Automobile Services Pte Ltd (Woodlands) 38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park Singapore 757700
<b>Estimated Period of Repair:</b>	7.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLL1509M)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,500.50 FL	*1,100.00 FL
2	1		*TAILGATE GLASS	Broken	1,450.70 FL	*1,450.70 FL
3	1		*TAILGATE MOULDING	Necessary	158.60 FL	*158.60 FL
4	1		*TAILGATE GARNISH	Broken	198.10 FL	*198.10 FL
5	1		*TAILGATE REFLECTOR L/H	Broken	290.10 FL	*290.10 FL
6	2		*TAILGATE NO PLATE LAMP	Not Necessary	97.12 FL	*- FL
7	1		*TAILGATE WIPER ARM	Not Necessary	90.60 FL	*- FL
8	1		*TAILGATE WIPER MOTOR	Not Necessary	225.60 FL	*- FL
9	1		*TAILGATE H EMBLEM	Necessary	24.70 FL	*24.70 FL
10	1		*TAILGATE VEZEL EMBLEM	Necessary	74.60 FL	*74.60 FL
11	2		*TAILGATE ABSORBER	Not Necessary	360.80 FL	*- FL
12	1		*TAILGATE TOP LOCK	Bent	190.50 FL	*190.50 FL
13	1		*TAILGATE LOWER LOCK	Not Necessary	37.40 FL	*- FL
14	1		*TAILGATE STOPPER L/H	Not Necessary	23.30 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Torn	105.80 FL	*105.80 FL
16	1		*TAILGATE INNER TRIM BOARD	Broken	235.10 FL	*235.10 FL
17	1		*TAILLAMP ASSY L/H	Broken	598.20 FL	*529.00 FL
18	1		*TAILLAMP PANEL L/H	Repair	145.90 FL	*- FL
19	1		*REAR BUMPER	Dented	1,163.20 FL	*801.70 FL
20	2		*REAR BUMPER SIDE RETAINERS	Broken	76.00 FL	*76.00 FL
21	1		*REAR BUMPER REFLECTOR	Broken	145.00 FL	*145.00 FL
22	1		*REAR BUMPER SIDE	Crushed	198.00 FL	*198.00 FL
23	1		*REAR END PANEL	Dented	511.90 FL	*511.90 FL
24	1		*REAR END PANEL TOP GARNISH	Crushed	92.80 FL	*92.80 FL
25	1		*REAR FENDER L/H	Repair	900.10 FL	*- FL
26	1		*REAR FENDER INNER TRIM BOARD L/H	Crushed	295.50 FL	*295.50 FL
27	1		*REAR FENDER ARCH GARNISH L/H	Crushed	150.90 FL	*150.90 FL
28	1		*ROCKER PANEL GARNISH L/H	Not Necessary	377.50 FL	*- FL
29	1		*SPARE TYRE FLOOR PANEL LOWER COVER	Not Necessary	190.00 FL	*- FL
30	1		*BUZZER	Broken	85.10 FL	*85.10 FL
31	1		*SET REAR BUMPER CLIPS	Necessary	28.00 FS	*28.00 FS
32	1		*TAILLAMP CLIP L/H	Not Necessary	4.90 FS	*- FS
33	1		*SET SPARE TYRE FLOOR PANEL LOWER COVER CLIPS	Necessary	30.00 FS	*20.00 FS
34	1		*SET REVERSE SENSOR	Broken	350.00 FS	*200.00 FS
35	1		*SEALANT (2 Pcs)	Necessary (1 Pcs only)	80.00 FS	*40.00 FS
36	1		*DECAL	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>10,506.52</b>	<b>7,022.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>1,998.72</b>	<b>1,342.82</b>
<b>Total Parts (S\$)</b>	<b>8,507.80</b>	<b>5,679.28</b>

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING FUNCTION	New	30.00	30.00
2	TO REMOVE AND CAMERA	New	60.00	20.00
3	TO TRANSFER TAILGATE	New	70.00	30.00
4	TO REMOVE AND REFIX TAILGATE GLASS	New	140.00	100.00
5	TO REMOVE AND REFIX PETROL TANK	New	80.00	0.00
6	TO PUT PUTTY ON REMOVE/REFIX PANEL	New	100.00	50.00
7	TO REMOVE AND REFIX CUSHION SEATS	New	80.00	30.00
8	TO VACCUM ALL THE BROKEN GLASS AND CLEAN	New	100.00	50.00
9	LABOUR CHARGES	New	1,200.00	1,000.00
10	TO PUTTY AND SPRAY PAINTING CHARGES	New	1,200.00	950.00
11	LABOUR CHARGES TO SENT IDAC FOR DECAL	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,140.00</b>	<b>2,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >