



Your Ref: AEMD/105/009/2018/188

Date: 19<sup>th</sup> September 2019

Our Ref: CS1/SPF19012158/Hqf3s2

**M/s Automotive Engineering & MGT Division**

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Frankie Thay

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO. SDM 44H  
INSURED VEHICLE NO GBB 7902S ACCIDENT ON 11/12/2018**

We thank you for your instruction on 27/06/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDM 44H from M/s Kah Motor Co.Sdn Bhd.
- b) Singapore Accident Statement of Vehicles SDM 44H.
- c) Damaged vehicle photographs of SDM 44H

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

**1. Information Recorded: -**

Registration Number	: SDM 44H
Make & Model	: Honda Civic 1.6
Year of Registration	: 2018
Chassis Number	: MRHFC5650JT001340
Engine Capacity	: 1597 cc



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

2. Our finding is that the repair cost of \$2,853.78 (before GST) quoted by M/s Kah Motor CO. Sdn. Bhd. is fair & reasonable.
3. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.

Vehicle Inspection By:

LEE HOCK ANN  
*Asst. Automotive Assessor*

ADRIAN LING WAI PING  
*B. Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI  
Licensed Appraiser*