

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 15 Jul 2019

**Preliminary Advice**

|                    |                                                                                               |                         |              |
|--------------------|-----------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLP771G                                                                                     | Accident Date           | : 06/07/2019 |
| TP Vehicle No      | : SHC8908T                                                                                    | Assignment Date         | : 09/07/2019 |
| Make               | : HYUNDAI I40                                                                                 | Est. Duration of Repair | : 8.00       |
| Date of Inspection | : 10/07/2019                                                                                  |                         |              |
| Inspection At      | : CHUNNI MOTOR WORK PTE LTD - AMK (HQ)<br>BLK 10 #01-05/06, AMK AUTOPOINT<br>SINGAPORE 568047 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s body and o/s rear portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 16,099.96 |
| Revised Amount              | :S\$ | 11,455.56 |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 11,455.56 |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.