

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/SMO19012182/KTF3N2  
**Date:** 08/04/2020

### REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D19MTPV01000592  
**Claimant Vehicle No :** SLV6241Z **Insured Vehicle No :** SKR3403B  
Date of Loss: 08/07/2019 Nature of Claim: TP Claim No: CMTD1903282

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV6241Z**  
Make & Model: HONDA SHUTTLE, 1.5 GA (A) Engine No: L15B5460448  
Reg. Date: 05/01/2018 (Man. Year: 2017) Chassis No: GK81200382  
Colour: Dark Grey Odometer: 28022 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 205/50ZR16 Rear Tyre Size: 205/50ZR16  
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm  
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                         | 5,900.80        | 3,835.60        | 2,065.20        | 35.00        |
| Miscellaneous Items           | 0.00            | 0.00            | 0.00            |              |
| Labour                        | 2,270.00        | 1,550.00        | 720.00          | 31.72        |
| Paintwork Labour              | 0.00            | 0.00            | 0.00            |              |
| Towing                        | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>      | <b>8,170.80</b> | <b>5,385.60</b> | <b>2,785.20</b> | <b>34.09</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | 571.96          | 376.99          | 194.97          | 34.09        |
| <b>Nett Amount (S\$)</b>      | <b>8,742.76</b> | <b>5,762.59</b> | <b>2,980.17</b> | <b>34.09</b> |

### INSPECTION

Date of Assignment: 10/07/2019  
Date Inspected: 10/07/2019 Inspected At: Cartimes Autolution (HQ)  
160 Sin Ming Drive #02-04 Autocity  
Singapore 575722  
Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                            |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 08 Apr 2020)                                                                                                                                             |                                                            |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | HONDA SHUTTLE 1.5 GA (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                          |
| <b>Print Code:</b>   | LKK Auto Consultants Pte Ltd/SLV6241Z/08/04/2020 13:20                                                                                                                       |                                                            |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                            |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                            |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                   | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                                  | Bent          | 1,250.00 FL | *1,250.00 FL |
| 2   | 2   |          | *REAR BUMPER SIDE RETAINER                    | Serviceable   | 80.00 FL    | *- FL        |
| 3   | 2   |          | *REAR BUMPER LHS & RHS BUMPER REFLECTOR       | Serviceable   | 140.00 FL   | *- FL        |
| 4   | 2   |          | *REAR BUMPER LHS & RHS REFLECTOR GARNISH      | Serviceable   | 156.00 FL   | *- FL        |
| 5   | 1   |          | *TAILGATE                                     | Bent          | 1,180.50 FL | *1,180.50 FL |
| 6   | 1   |          | *TAILGATE CENTRE GARNISH                      | Serviceable   | 395.00 FL   | *- FL        |
| 7   | 1   |          | *TAILGATE INNER TRIM BOARD                    | Buckled       | 245.00 FL   | *245.00 FL   |
| 8   | 1   |          | *TAILGATE LOCK                                | Dented        | 95.00 FL    | *95.00 FL    |
| 9   | 2   |          | *TAILGATE RHS & LHS TAILLAMP                  | Serviceable   | 890.00 FL   | *- FL        |
| 10  | 1   |          | *REAR END PANEL                               | Bent          | 510.00 FL   | *510.00 FL   |
| 11  | 1   |          | *REAR END PANEL TOP GARNISH                   | Dented        | 125.00 FL   | *125.00 FL   |
| 12  | 1   |          | *SMART BUZZER                                 | Cracked       | 125.00 FL   | *125.00 FL   |
| 13  | 1   |          | *REAR BUMPER TOWING CAP                       | Serviceable   | 28.00 FL    | *- FL        |
| 14  | 1   |          | *REAR WINDSCREEN MOULDING                     | Necessary     | 145.00 FL   | *145.00 FL   |
| 15  | 1   |          | *REAR WINDSCREEN DAM RHS,LHS & TOP<br>(3 Pcs) | Necessary     | 115.00 FL   | *115.00 FL   |
| 16  | 1   |          | *REAR TAILGATE WEATHER STRIP                  | Distorted/Cut | 135.00 FL   | *135.00 FL   |
| 17  | 1   |          | *REAR END PANEL ANTENNA                       | Cracked       | 85.00 FL    | *85.00 FL    |
| 18  | 2   |          | *REAR RHS & LHS BUMPER SPONGE                 | Serviceable   | 155.00 FL   | *- FL        |
| 19  | 1   |          | *HONDA LOGO                                   | Necessary     | 32.00 FL    | *32.00 FL    |
| 20  | 1   |          | *SHUTTLE WORDING                              | Necessary     | 62.00 FL    | *62.00 FL    |
| 21  | 1   |          | *REAR WINDSCREEN SEALANT                      | Necessary     | 80.00 FS    | *40.00 FS    |
| 22  | 1   |          | *REAR REVERSE CAMERA                          | Serviceable   | 450.00 FS   | *- FS        |
| 23  | 1   |          | *REAR REVERSE SENSOR                          | Dented        | 280.00 FS   | *200.00 FS   |
| 24  | 1   |          | *REAR INNER TRIM BOARD CLIPS                  | Necessary     | 40.00 FS    | *40.00 FS    |
| 25  | 1   |          | *SETS REAR BUMPER CLIPS                       | Necessary     | 60.00 FS    | *40.00 FS    |
| 26  | 1   |          | *SPARE TYRE PANEL INNER TRIM                  | Dented        | 255.00 FL   | *255.00 FL   |
| 27  | 1   |          | *TAILGATE LOWER HANDLE                        | Dented        | 35.00 FL    | *35.00 FL    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>7,148.50</b> | <b>4,714.50</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | <b>1,247.70</b> | <b>878.90</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>5,900.80</b> | <b>3,835.60</b> |

LKK Auto Consultants Pte Ltd/SLV6241Z/08/04/2020 13:20. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                          | Lab.Type | Repairer's      | Amount          |
|--------------------------------|------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                      |          |                 |                 |
| 1                              | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS     | New      | 1,000.00        | 700.00          |
| 2                              | TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED        | New      | 700.00          | 600.00          |
| 3                              | TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS | New      | 120.00          | 20.00           |
| 4                              | TO REMOVE & REPLACE REVERSE SENSOR AND CHECK FOR PROPER FUNCTION                                     | New      | 150.00          | 50.00           |
| 5                              | TO REMOVE & REFIT REAR TAILGATE WINDSCREEN                                                           | New      | 150.00          | 120.00          |
| 6                              | TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS                                                     | New      | 150.00          | 60.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                      |          | <b>2,270.00</b> | <b>1,550.00</b> |

LKK Auto Consultants Pte Ltd/SLV6241Z/08/04/2020 13:20. Not valid without Reference section.

< END OF ESTIMATES >