

22/07/2019

ASS. REC. BY:

REF: CS3/ALG19012186/Gcf3L2

Special Instruction:

Surveyor: AND AileenASSIGNMENT (Office)From (Person): Chin Lee Yng

of

A19Date/Time: 9/7/19 @ 4.46pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 8627K

Insured:

SML 5493K

at Workshop m/s

King's Auto

Tel:

6457 8629

of

Bik 176 Sin Ming Drive # 02-10

Policy No:

0999994322

Claim No:

051846981126

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 9/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12.30pm @ 10/7/19

Person Contacted:

TanVehicle IN OUT

Date/Time	Action/Instruction
	<u>Johnny (X)</u>
	<u>SML 5493K: X</u>
	<u>SJU 8627K: CS3/INC19010358/Gcd3</u>
	<u>Dismantle: 15/7/2019</u>
	<u>After repair: 23/7/2019</u>

No GIA

INS. PERCY

PRS
Ed.

REF:

A14

ASSIGNMENT

From

Date:

12/7/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJU 8627K

at Workshop m/s

Kings Auto

of

BLK 176 An Mirey Drive #02-10

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Go this first.

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJU 8627K

Yr Regn:

Dec / 09

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Vios

C.C

1497

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

144/167

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053HY9305144251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FIRENZA

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

12-07-19

Survey held at

W/S

1:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

12

Resurvey No. of Trip:

2

Survey Fee:

180

Transportation:

S + RS SI

Photos

Others

TOTAL

11

191

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Report Format:

DAR

Lump Sum / LEI: \$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2019 Edit Reg		10 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: BIS MOTORING PTE LTD , Co. Reg. No.: 201735055D, Tel: +6599999999									
Main Claimant: NA									
Vehicle Reg. No.: SJU8627K		Date of Loss: 09/07/2019 08:00 - :59							
Claim Type: TP / 0518469811SG		Policy/Cover Note No.: 0999994322 (Comprehensive)							
Vehicle Reg. No. (Insured): SML5493K		Policy No. (Claimant):							
		Excess:							
Repairer: King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/07/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
AIG_SG (11/07/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	664R
Vehicle Details	
Vehicle No.:	SJU8627K
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOSE AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1NZX018150
Chassis No.:	MR053HY9305144251
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	31 Dec 2009
First Registration Date:	31 Dec 2009
Transfer Count:	2
Actual ARF Paid:	\$12,717.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2019
PARF Rebate Amount:	\$6,358.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$3,148.00
COE Rebate Amount:	\$775.00
Total Rebate Amount:	\$7,133.00

The information contained herein is correct as at 26 Jul 2019

OK

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc:
Sent: 7/9/2019 4:46:01 PM

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Tuesday, July 09, 2019 4:35 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin

Subject: [EXTERNAL] Re: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SML5493K AND SJU8627K ON 09/07/2019 // Our ref: L.19.0863.lt

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

We confirm that you have **objected** to our client's list of surveyors. Our client's vehicle is at the following address:

King's Auto Air-conditioning Service

Blk 176 Sin Ming Drive

#02-10 Sin Ming Autocare

Singapore 575721

Tel: 6457 8629

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Thanks / Rgds,
Lena
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: kurulegal@yahoo.com.sg
To: AIGSGP_ClaimsSurvey@aig.com
Subject: [EXTERNAL] PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: SML 5493K // Our ref: L.19.0863.It
Date: Tue, 9 Jul 2019 06:29:59 +0000
This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

ACCIDENT INVOLVING SJU 8627K, SML 5493K & SKW 2408S ON 09.07.19

AT/ALONG MIDDLE ROAD TOWARDS SOPHIA ROAD

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **ST (Premium) Rent & Drive Pte Ltd**, whose vehicle registration number **SJU 8627K** was damaged in the above accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thanks / Rgds,
Lena

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

Front Portion

Vehicle No:

SU 8627 K

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	OKA		
1002	991887	Frt Number Plate Base	OKA		
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	De		
1005	992341	Frt Bumper Clips	NBC		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	De		
1008	991433	Frt Bumper Reinforcement	BT		
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Base Garnish	De		
1013	991363	Frt Bumper Grille	De		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	OKA		
1022	991328	Frt Grille Emblem	NBC		
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT		
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	OKA		
1030	991821	Frt RH Headlamp Assy	OKA		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	Repair		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Flange			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	OKA		
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member	Repair		
1093	991520	Frt RH Chassis Member	Repair		
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(X) (3)Check (C)
(4)Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	SCR /		
1138	993627	Rear Number Plate Base	SCR /		
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	TN /		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NBC /		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	RE /		2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper pad lamp	Cut /		2
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	OM /		
1159	993327	Rear End Panel	BT /		
1160	993339	Rear End Panel Top Garnish	RE /		
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA /		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	BT /		
1166	995116	Rear RH Taillamp	CRA /		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	BT /		
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	BT /		
1171	991328	Bootlid Emblem	NBC /		2
1172	990356	Bootlid Handle	RE /		
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	BT /		
1178	990377	Bootlid Rubber	TN /		
1179	990382	Bootlid Hinge	BT /		2
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate inner Board			

Vehicle No: STU 8627K

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board	CRA /		
1203	994328	Spare Tyre Panel	Repair /		
1204	995065	Spare Tyre <u>Sponge</u>	CRA /		3
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	Repair /		
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	Buc /		
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	Buc /		
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding	NBC /		
1247	993955	Rear Windscreen Sealant	NBC /		
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille	RE /		
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jul 2019 Edit Reg		09 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: BIS MOTORING PTE LTD , Co. Reg. No.: 201735055D, Tel: +6599999999									
Main Claimant: NA									
Vehicle Reg. No.: SJU8627K		Date of Loss: 09/07/2019 08:00 - :59 [114 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0518469811SG		Policy/Cover Note No.: 0999994322 (Comprehensive)							
Vehicle Reg. No. (Insured): SML5493K		Policy No. (Claimant):							
		Excess:							
Repairster: King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (11/07/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU8627K (0518469811SG)

[SML5493K]

TP

NA

Jul 9 2019 8:00AM

[BIS MOTORING PTE LTD]

King's Auto Air-Conditioning Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	24/07/19 15:39	General View														Load JPG	☒	
2	24/07/19 15:39	General View														Load JPG	☒	
3	24/07/19 15:39	General View														Load JPG	☒	
4	24/07/19 15:39	General View														Load JPG	☒	
5	24/07/19 15:39	General View														Load JPG	☒	
6	24/07/19 15:39	General View														Load JPG	☒	
7	24/07/19 15:39	General View														Load JPG	☒	
8	24/07/19 15:39	General View														Load JPG	☒	
9	24/07/19 15:39	General View														Load JPG	☒	
10	24/07/19 15:39	General View														Load JPG	☒	
11	24/07/19 15:39	General View														Load JPG	☒	
12	24/07/19 15:39	General View														Load JPG	☒	
13	24/07/19 15:39	General View														Load JPG	☒	
14	24/07/19 15:39	General View														Load JPG	☒	
15	24/07/19 15:39	General View														Load JPG	☒	
16	24/07/19 15:39	General View														Load JPG	☒	
17	24/07/19 15:39	General View														Load JPG	☒	
18	24/07/19 15:39	General View														Load JPG	☒	
19	24/07/19 15:39	General View														Load JPG	☒	
20	24/07/19 15:39	General View														Load JPG	☒	
21	24/07/19 15:39	General View														Load JPG	☒	
22	24/07/19 15:39	General View														Load JPG	☒	
23	24/07/19 15:39	General View														Load JPG	☒	
24	24/07/19 15:39	General View														Load JPG	☒	
25	24/07/19 15:39	General View														Load JPG	☒	
26	24/07/19 15:39	General View														Load JPG	☒	
27	24/07/19 15:39	General View														Load JPG	☒	
28	24/07/19 15:39	General View														Load JPG	☒	
29	24/07/19 15:39	General View														Load JPG	☒	
30	24/07/19 15:39	General View														Load JPG	☒	
31	24/07/19 15:39	General View														Load JPG	☒	
32	24/07/19 15:39	General View														Load JPG	☒	
33	24/07/19 15:39	General View														Load JPG	☒	
34	24/07/19 15:39	General View														Load JPG	☒	
35	24/07/19 15:39	General View														Load JPG	☒	
36	24/07/19 15:39	General View														Load JPG	☒	
37	24/07/19 15:39	General View														Load JPG	☒	
38	24/07/19 15:39	General View														Load JPG	☒	
39	24/07/19 15:39	General View														Load JPG	☒	
40	24/07/19 15:39	General View														Load JPG	☒	
41	24/07/19 15:39	General View														Load JPG	☒	
42	24/07/19 15:39	General View														Load JPG	☒	
43	24/07/19 15:39	General View														Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	24/07/19 15:39	General View	 Load JPG	☒
45	24/07/19 15:39	General View	 Load JPG	☒
46	24/07/19 15:39	General View	 Load JPG	☒
47	24/07/19 15:39	General View	 Load JPG	☒
48	24/07/19 15:39	General View	 Load JPG	☒
49	24/07/19 15:39	General View	 Load JPG	☒
50	24/07/19 15:39	General View	 Load JPG	☒
51	24/07/19 15:39	General View	 Load JPG	☒
52	24/07/19 15:39	General View	 Load JPG	☒
53	24/07/19 15:39	General View	 Load JPG	☒
54	24/07/19 15:39	General View	 Load JPG	☒
55	24/07/19 15:39	General View	 Load JPG	☒
56	24/07/19 15:39	General View	 Load JPG	☒
57	24/07/19 15:39	General View	 Load JPG	☒
58	24/07/19 15:39	General View	 Load JPG	☒
59	24/07/19 15:39	General View	 Load JPG	☒
60	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
61	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
62	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
63	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
64	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
65	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
66	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
67	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
68	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
69	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
70	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
71	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
72	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
73	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
74	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
75	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
76	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
77	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
78	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
79	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
80	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
81	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
82	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
83	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
84	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
85	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
86	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
87	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
88	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
89	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
90	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
91	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
92	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
93	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
94	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
95	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
96	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
97	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
98	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
99	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
101	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
102	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
103	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
104	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
105	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
106	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
107	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
108	24/07/19 15:40	Photographs of Damaged Parts	 Load JPG	☒
109	24/07/19 15:40	Photo After Spray	 Load JPG	☒
110	24/07/19 15:40	Photo After Spray	 Load JPG	☒
111	24/07/19 15:40	Photo After Spray	 Load JPG	☒
112	24/07/19 15:40	Photo After Spray	 Load JPG	☒
113	24/07/19 15:40	Photo After Spray	 Load JPG	☒
114	24/07/19 15:40	Photo After Spray	 Load JPG	☒
115	24/07/19 15:40	Photo After Spray	 Load JPG	☒
116	24/07/19 15:40	Photo After Spray	 Load JPG	☒
117	24/07/19 15:40	Photo After Spray	 Load JPG	☒
118	24/07/19 15:40	Photo After Spray	 Load JPG	☒
119	24/07/19 15:40	Photo After Spray	 Load JPG	☒
120	24/07/19 15:40	Photo After Spray	 Load JPG	☒
121	24/07/19 15:40	Photo After Spray	 Load JPG	☒
122	24/07/19 15:40	Photo After Spray	 Load JPG	☒
123	24/07/19 15:40	Photo After Spray	 Load JPG	☒
124	24/07/19 15:40	Photo After Spray	 Load JPG	☒
125	24/07/19 15:40	Photo After Spray	 Load JPG	☒
126	24/07/19 15:40	Photo After Spray	 Load JPG	☒
127	24/07/19 15:40	Photo After Spray	 Load JPG	☒
128	24/07/19 15:40	Photo After Spray	 Load JPG	☒
129	24/07/19 15:40	Photo After Spray	 Load JPG	☒
130	24/07/19 15:40	Photo After Spray	 Load JPG	☒
131	24/07/19 15:40	Photo After Spray	 Load JPG	☒
132	24/07/19 15:40	Photo After Spray	 Load JPG	☒
133	24/07/19 15:40	Photo After Spray	 Load JPG	☒
134	24/07/19 15:40	Photo After Spray	 Load JPG	☒
135	24/07/19 15:40	Photo After Spray	 Load JPG	☒
136	24/07/19 15:40	Photo After Spray	 Load JPG	☒
137	24/07/19 15:40	Photo After Spray	 Load JPG	☒
138	24/07/19 15:40	Photo After Spray	 Load JPG	☒
139	24/07/19 15:40	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/07/19 10:25	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19012186/GCF3E2

Date: 17/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322

Claimant Vehicle No : SJU8627K

Insured Vehicle No : SML5493K

Date of Loss: 09/07/2019

Nature of Claim: TP

Claim No: 0518469811SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU8627K

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZX018150

Reg. Date: 31/12/2009 (Man. Year: 2009)

Chassis No: MR053HY9305144251

Colour: Silver

Odometer: 144167 km

Engine Capacity: 1497 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Firenza 6 mm

Rear Left Side:

Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side:

Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/07/2019

Date Inspected: 12/07/2019 Inspected At:

King's Auto Air-Conditioning Service (HQ)

Block 176 Sin Ming Drive, #02-10

Singapore 575721

Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cracked	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Cut	0.00 F	*- F
3	1		*FRT BUMPER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT BUMPER GARNISH	Deformed	0.00 F	*- F
8	1		*FRT BUMPER GRILLE	Deformed	0.00 F	*- F
9	1		*FRT GRILLE	Cracked	0.00 F	*- F
10	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
11	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
12	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
13	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
14	1		*BONNET	Repair	0.00 F	*- F
15	1		*AIR CON CONDENSER	Cut	0.00 F	*- F
16	1		*FRT LH CHASSIS MEMBER	Repair	0.00 F	*- F
17	1		*FRT RH CHASSIS MEMBER	Repair	0.00 F	*- F
18	1		*REAR NUMBER PLATE	Scratched	0.00 F	*- F
19	1		*REAR NUMBER PLATE BASE	Scratched	0.00 F	*- F
20	1		*REAR BUMPER	Torn	0.00 F	*- F
21	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
22	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
23	2		*REAR BUMPER LAMP	Cut	0.00 F	*- F
24	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
25	1		*REAR END PANEL	Bent	0.00 F	*- F
26	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
27	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
28	1		*REAR LH TAILLAMP PANEL	Bent	0.00 F	*- F
29	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
30	1		*REAR RH TAILLAMP PANEL	Bent	0.00 F	*- F
31	1		*BOOTLID	Bent	0.00 F	*- F
32	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
33	1		*BOOTLID HANDLE	Deformed	0.00 F	*- F
34	1		*BOOTLID LOCK	Bent	0.00 F	*- F
35	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F
36	2		*BOOTLID HINGE	Bent	0.00 F	*- F
37	1		*SPARE TYRE BOARD	Cracked	0.00 F	*- F
38	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
39	3		*SPARE TYRE SPONGE	Cracked	0.00 F	*- F
40	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
41	1		*REAR LH FENDER	Buckled	0.00 F	*- F
42	1		*REAR RH FENDER	Buckled	0.00 F	*- F
43	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
44	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
45	1		*REAR FENDER AIR GRILLE	Deformed	0.00 F	*- F
F=Franchise part.				Total Parts (\$\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >