

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG19012194/GPA3Q2  
**Date:** 02/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100448219
<b>Claimant Vehicle No :</b>	SJJ6192T	<b>Insured Vehicle No :</b>	SLA9570P
Date of Loss:	07/07/2019	Nature of Claim:	TP
		Claim No:	6975617855SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJJ6192T</b>		
Make & Model:	TOYOTA MARK X, 2.5 (A)	Engine No:	4GR0467257
Reg. Date:	19/09/2008 (Man. Year: 2008)	Chassis No:	GRX1203061035
Colour:	Black	Odometer:	250253 km
Engine Capacity:	2499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,038.40	1,374.50	2,663.90	65.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	440.00	1,720.00	79.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,198.40</b>	<b>1,814.50</b>	<b>4,383.90</b>	<b>70.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,450.00</b>		

<b>Nett Amount (S\$)</b>	<b>6,198.40</b>	<b>1,450.00</b>	<b>4,748.40</b>	<b>76.61</b>
<b>+ Loss of Use (3.0 x S\$80.00/day) (S\$)</b>		240.00		
<b>Nett Liability (S\$)</b>		<b>1,690.00</b>		

INSPECTION

Date of Assignment: 10/07/2019

Date Inspected: 10/07/2019

Estimated Period of Repair: 3.0 days

Inspected At:

Unimotor Company (HQ)  
 1, Kaki Bukit Avenue 6, Autobay@Kaki Bukit, #01-94  
 Singapore 417883

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cracked	1,965.00 FL	*1,250.00 FL
2	2		*REAR BUMPER SIDE SUPPORT HOLDER CLIPS	Not Necessary	240.00 FL	*- FL
3	2		*REAR BUMPER TOW COVER GARNISH	Not Necessary	68.00 FL	*- FL
4	1		*REAR R/H BUMPER INNER BRACKET	Not Necessary	107.00 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
6	1		*REAR TAIL END PANEL	Not Necessary	877.00 FL	*- FL
7	1		*REAR R/H TAILLAMP ASSY	Not Necessary	675.00 FL	*- FL
8	1		*REAR R/H EXHAUST CHROME	Not Necessary	189.00 FL	*- FL
9	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
					<hr/>	
					Sub Total (S\$)	4,456.001,505.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	417.60130.50
					<hr/>	
					Total Parts (S\$)	4,038.401,374.50
					<hr/>	

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE REAR DAMAGED PORTION	New	80.00	0.00
2	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	1,000.00	200.00
3	TO DISMANTLE REAR REVERSE SENSOR	New	80.00	40.00
4	TO PUTTY AND RESPRAY DAMAGED PORTION	New	800.00	200.00
5	TO SPRAY UNDERCOATING IN REPAIR	New	200.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,160.00</b>	<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >