

REPAIR ESTIMATE*

VEHICLE NO : SHD7182X

DATE: 9. Jul. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 9. Jul. 2019

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper <i>X rep.</i>			\$553.00
10	Rear Bumper Clips <i>X</i>		\$2.20	\$22.00
1	Rear Bumper Side Bracket - RH <i>X</i>			\$35.60
SUB TOTAL				\$610.60
LESS 20%				\$122.12
DISCOUNTED TOTAL				\$488.48
Labour Charge				
1	Panel Beating			\$250.00 <i>200</i>
1	Spray Painting Charge			\$500.00 <i>200</i>
1	Remove/refix Reverse Sensor			\$100.00 <i>X</i>
TOTAL LABOUR				\$850.00
ESTIMATE TOTAL				\$1,338.48
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kohli (LKK)

10/7/19 1045h

200

PIP

After

Rep-2 p.h.

Larry Ng