## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO: SHD 6594Y

MAKE

DATE 8/7/2019 16:35

CHINA

DDEL	: HYUNDAI i40	Terms	Unit Price	Δ	mount
Qty	Parts Description/ Labour	Type	Unit Frice	\$	85.00
	Bootlid Moulding			\$	553.00
	Rear Bumper / Phil			\$	22.00
	Rear Bumper Clip 10 pcs		25.60		71.20
	Rear Bumper Bracket (LH/RH)		\$ 35.60	\$	
	Rear Bumper Under Cover		4.00.00	\$	228.00
	Rear Fender Inner Lining (LH/RH)		\$ 169.30	\$	338.60
	Rear Taillang (CH) - Ent SUB TOTAL LESS 20%		\$565.60		
	SUB TOTAL		37 00 00	\$	1,297.80
	Per Feater (a) X7 LESS 20%			\$	259.56
	DISCOUNTED TOTAL			\$	1,038.24
	Rear Bumper Rubber Mat			\$	50.00
	Rear Bumper Rubber Mat Rear Bumper Reverse Sensor		811	\$	135.70
				\$	185.70
	Labour Charge				200
	Panel Beating			\$	400.00
	Spray Painting Charge		50	28	
	Wiring Charge			\$	30.00
	Towing Fees- King Dolly			\$	150.00
	Remove/Refix Reverse Sensor			\$	80.00
	Remove/Renx Reverse Sensor				
	TOTAL LABOUR	,		8	960.00
	TOTAL LABOUR	`		-	
	ESTIMATE TOTAL			\$	2,183.94
	ESTIMATE TOTAL	1		Ť	7,,,,,,,,,
			notify		
	10 1. 1111 I	IKX 20"	149		
	Kalon 1400)	ne Rel	a walled bar, and the solvey		
	1/ 98/4/19 1020hm.	. To distilly	as majes pare subject a con- ses are subject a con- sty survey is on a "Without a sejud- all modification(s) is allowed all modification (s) must be resurvey.	15" E35	· \
	1/1 00/01: 0/	• Parts pric	ty survey is on a "Williams allowed all nhodification(s) is allowed mehtary item(s) must be resurvey mehtary item(s) must be resurvey.	-anad	\
	1/ 18/7/19 1620m.	Third poil     No illegi	al modification(s) must be resurvey	e Com	pany
		• Supple	ty survey is on a allowed all nodification(s) is allowed the nodification (s) is allowed the node of t		\
	2651	is subj	Repairer		\
		11 . 1.000	wledged by Repairer		
	Us	Signal	luie.		
	111 0 1 166	Date:			
	Alle Ravir ploto				
	//	150			
		the above	vahiola The final repair	- Onar	ntum will
	This is an initial estimate based on a visual inspection of	the above	vemere. The imai repair	quai	****
	be prepared after the vehicle is surveyed by a motor Surv	veyor appo	inted by the insurance of	отра	uy.



member of COMFORTUNERO



ComfortDelGro Engineering Pte Ltd



CUSTOMER'S COP

## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition		
Name of Customer: 9476	Private is Taxi (CTPL/0	Flat Bed
Make/Model/Colour:	5. Nature of Service  Jumpstart  Recovery  Change Tyre	
Email :  7. Location:  9. Preferred Workshop:  Braddell Loyang  Sin Ming Sungei Kadut  Senoko Komoco (UBI /	Pandan Ubi Leng Kee) Cycle & Carriage (P	8. Vehicle Tow - In Workshop:  Smoky Exhaust Wheel Jammed Overheating Steering Faulty Brake Faulty Alternator Faulty Starting Problem Loss Power Accident Engine Stalled Return Taxi
10. Odometer Reading :		O/CD Player OK Faulty Not tested
Job Attended		
12. Tow Truck / Recovery Van : VF  Name of Driver : Vehicle No. : Time Dispatch : Time of Arrival : VF	Shu Sian  TZ YISH  TOW  TOW  11:30	
	. 101	Signature of Customer
Time Completed :		Signature of outsited
Cash Invoice Details (if applicable)		
13. Cash Invoice No. :		
Customer Acknowledgement	ems in my vehicle, including Global Positioning S	System (GPS), audio compact disk, thumbdrive, carpark coupo
cash cards, spectacles, pen, etc.  b. I understand that any items left behind are a	at my own risk and SPARK Car Care™ will not be ustomer decides neither to tow nor proceed with	e held liable for such losses.
8-7-2019	12210	
8-7- 2019 Date	Time	Signature of Customer
14. WORKSHOP		
Name of Attending Stoff/Guard	Date & Time of Arrival	Signature of Attending Staff/Guard
Name of Attending Staff/Guard	Date a Tille of Allivai	allegations /