10/4/21, 9:27 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG19012206/K1EA3Q2

Date:

04/10/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Nature of Claim:

1700052051 SLS4840Z

Claimant Vehicle No:

SH8586G 06/07/2019 Insured Vehicle No:

TP

Claim No:

8954230740SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH8586G

Make & Model: HYUNDAI 140, 1.7 L CRDI AT ABS AIRBAG 4DR (A) Engine No: D4FDFU528040 Chassis No:

Reg. Date: 30/04/2014 (Man. Year: 2014)

Odometer:

KMHLB41UMEU053707 564022 km

Colour: Blue

Engine Capacity: 1685 cc N/A

Market Value/New Car Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Yes No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size:

205/60 R16

Front Left Side: Front Right Side: West Lake 7 mm West Lake 7 mm Rear Left Side:

West Lake 7 mm

Rear Right Side:

West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		547.88	85.68	462.20	84.36
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,250.00	600.00	650.00	52.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	1,797.88	685.68	1,112.20	61.86
	Approved Total (Overridden) (S\$)		550.00		

	Global Sum Settlement (S\$)		0.00		
Nett Amount (S\$	5)	1,923.73	588.50	1,335.23	69.41
+ GST 7.00/7.00% (S\$	5)	125.85	38.50	87.35	69.41
(S\$	5)	1,797.88	550.00	1,247.88	69.41

INSPECTION

Date of Assignment: 09/07/2019

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 09/07/2019 Inspected At:

59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ASSY -RR BUMPE	Repair	553.00 FL	*-FL
2	1		*CAP ASSY -WHEEL HUB	Grazed	107.10 FL	*107.10 FL
3	10		*HYUNDAI BUMPER COVER CLIP	Not Necessary	22.00 FN	*- FN
4	1		*REAR FENDER (RH) (NPA)	Repair	0.00 FL	*- FL
F=Fra	anchise	e part. L=ListItemDi	sc. N=NettItemDisc.	Sub Total (S\$)	682.10	107.10 21.42
				- List Item Discount on L Items 20.00/20.00% (S\$) - Nett Item Discount on N Items 10.00/10.00% (S\$)	132.02 2.20	0.00
				Total Parts (S\$)	547.88	85.68
			Re	port was unsubmitted during this print-out.		

10/4/21, 9:27 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Labour Items						
1	PANEL BEATING	New	500.00	200.00		
2	SPRAYPAINT CHARGE	New	600.00	400.00		
3	REMOVE/REFIX REVERSE SENSOR	New	100.00	0.00		
4	RENEW BUMPER ADVERTISEMENT STICKER	New	50.00	0.00		
		Gross Labour Cost (S\$)	1,250.00	600.00		

Report was unsubmitted during this print-out.

< END OF ESTIMATES >