

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19012209/AES3Q2

**Date:** 07/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100305964

**Claimant**  
**Vehicle No :** SFS563X **Insured Vehicle No :** SKF7396A

Date of Loss: 08/07/2019 Nature of Claim: TP Claim No: 8299981376SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                           |             |                   |
|-----------------------------|-------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SFS563X</b>                            |             |                   |
| Make & Model:               | HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A) | Engine No:  | G4FJHU365732      |
| Reg. Date:                  | 28/03/2018 (Man. Year: 2018)              | Chassis No: | KMHJ3812VJU662516 |
| Colour:                     | Grey                                      | Odometer:   | 21914 km          |
| Engine Capacity:            | 1591 cc                                   |             |                   |
| Market Value/New Car Price: | N/A                                       |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b>         |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/60 R17   | Rear Tyre Size:  | 225/60 R17   |
| Front Left Side:  | Hankook 6 mm | Rear Left Side:  | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 6,753.00          | 2,909.92          | 3,843.08          | 56.91         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 2,380.00          | 1,430.00          | 950.00            | 39.92         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>             | <b>9,133.00</b>   | <b>4,339.92</b>   | <b>4,793.08</b>   | <b>52.48</b>  |
| <b>Approved Total (Overridden) (\$\$)</b>        |                   | <b>3,400.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                        | <b>9,133.00</b>   | <b>3,400.00</b>   | <b>5,733.00</b>   | <b>62.77</b>  |
| <b>+ Car Rental (7.0 x S\$100.00/day) (\$\$)</b> |                   | 700.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                   |                   | 7.45              |                   |               |
| <b>Nett Liability (\$\$)</b>                     |                   | <b>4,107.45</b>   |                   |               |

### INSPECTION

Date of Assignment: 10/07/2019

Date Inspected: 10/07/2019 Inspected At: Fong Motors (HQ)  
1 Kaki Bukit Ave 6 #01-45, Autobay@  
Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's                                                | Amount                   |
|-----|-----|----------|--------------------------------------|---------------|-----------------------------------------------------------|--------------------------|
| 1   | 1   |          | *REAR BOOT LID                       | Dented        | 1,688.60 FS                                               | *700.00 FS               |
| 2   | 1   |          | *REAR BOOT LID LOCK                  | Not Necessary | 128.50 F                                                  | *- FL                    |
| 3   | 1   |          | *REAR BOOT LID GLASS MOULDING        | Not Necessary | 118.00 F                                                  | *- F                     |
| 4   | 1   |          | *REAR BOOT LID NO PLATE GARNISH      | Deformed      | 392.00 F                                                  | *392.00 FL               |
| 5   | 1   |          | *REAR BOOT LID OUTER GARNISH BRACKET | Cracked       | 467.80 F                                                  | *159.40 FL               |
| 6   | 1   |          | *REAR WEATHERSTRIP                   | Not Necessary | 181.60 F                                                  | *- FL                    |
| 7   | 1   |          | *REAR EMBLEM -LOGO                   | Necessary     | 39.60 F                                                   | *39.60 FL                |
| 8   | 1   |          | *REAR EMBLEM -TUSON                  | Necessary     | 43.80 F                                                   | *43.80 FL                |
| 9   | 1   |          | *REAR EMBLEM -S                      | Necessary     | 30.80 F                                                   | *30.80 FL                |
| 10  | 1   |          | *REAR EMBLEM -TURBO                  | Necessary     | 38.80 F                                                   | *38.80 FL                |
| 11  | 1   |          | *REAR NO.PLATE                       | Not Necessary | 45.00 FS                                                  | *- FS                    |
| 12  | 1   |          | *REAR END PANEL                      | Repair        | 793.10 F                                                  | *- FL                    |
| 13  | 1   |          | *REAR END PANEL GARNISH              | Not Necessary | 229.50 F                                                  | *- FL                    |
| 14  | 6   |          | *REAR END PANEL CLIP                 | Not Necessary | 27.00 F                                                   | *- FL                    |
| 15  | 1   |          | *REAR BUMPER STEP GARNISH            | Deformed      | 865.00 F                                                  | *865.00 FL               |
| 16  | 1   |          | *REAR BUMPER LAMP                    | Not Necessary | 120.90 F                                                  | *- FL                    |
| 17  | 1   |          | *REAR BUMPER                         | Deformed      | 798.00 F                                                  | *798.00 FL               |
| 18  | 2   |          | *REAR BUMPER LOWER BRACKET           | Not Necessary | 105.00 F                                                  | *- FL                    |
| 19  | 2   |          | *REAR BUMPER SIDE RETAINER           | Necessary     | 115.00 F                                                  | *115.00 FL               |
| 20  | 6   |          | *REAR BUMPER CLIP                    | Necessary     | 30.00 F                                                   | *30.00 FL                |
| 21  | 1   |          | *TAIL GATE GLASS SEALANT             | Not Necessary | 80.00 FS                                                  | *- FS                    |
| 22  | 1   |          | *TAIL GATE GLASS FORM TAPE           | Not Necessary | 65.00 FS                                                  | *- FS                    |
| 23  | 1   |          | *REVERSE SENSOR                      | Damaged       | 350.00 FS                                                 | *200.00 FS               |
|     |     |          |                                      |               | <b>Sub Total (\$\$)</b>                                   | <b>6,753.00 3,412.40</b> |
|     |     |          |                                      |               | <b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b> | <b>0.00 502.48</b>       |
|     |     |          |                                      |               | <b>Total Parts (\$\$)</b>                                 | <b>6,753.00 2,909.92</b> |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars                          | Lab.Type | Repairer's      | Amount          |
|-------------------------------|--------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>    |                                      |          |                 |                 |
| 1                             | TO REMOVE AND CHARGE PARTS           | New      | 1,000.00        | 600.00          |
| 2                             | TO SPRAY PAINT THE AFFECTED AREAR    | New      | 1,000.00        | 700.00          |
| 3                             | TO REMOVE AND REPLACE REVERSE SENSOR | New      | 100.00          | 50.00           |
| 4                             | TO CHECK WIRING                      | New      | 80.00           | 30.00           |
| 5                             | TO TRANSFER PARTS TO NEW BOOT        | New      | 100.00          | 0.00            |
| 6                             | TUFF KOTE                            | New      | 100.00          | 50.00           |
| <b>Gross Labour Cost (\$)</b> |                                      |          | <b>2,380.00</b> | <b>1,430.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >