CITY CAB PTE LTD REPAIR ESTIMATE*

VEHICLE NO: SHC 421H

APPY Licle

DATE 9/7/2019 16:02

AKE			(XIVOIA O			
ODEL	: HYUNDAI IONIQ		Unit Price		Amount	
Qty	Parts Description/ Labour	Type	Unit Frice	\$	459.40	1
	Rear Bumper Rear Bumper Centre Moulding Assy			\$	451.25	
	Rear Bumper Lower Centre Moulding Assy ×			\$	47.50	
	Rear Bumper Stay			S	138.10	
	Rear Bumper Side Bracket (LH/RH) >		\$ 33.10	S	66.20	
	Real Bumper Side Bracket (Ell/Rel)		33.10	"	00.20	
	SUB TOTAL			\$	1,162.45	1
	LESS 20%			\$	232.49	
	DISCOUNTED TOTAL			\$	929.96	-
	Rear No.Plate			\$	25.00	N
	Rear Bumper Reverse Sensor			\$	135.70	
	Rear Bumper Rubber Mat			S	50.00	
				\$	210.70	
	Labour Charge				2	
	Panel Beating			\$	400.00	
	Spray Painting Charge			\$	300.00	120
	Wiring Charge			\$	50.00	
	Remove/Refix Reverse Sensor			\$	120.00	3
	TOTAL LABOUR			\$	870.00	
	ESTIMATE TOTAL	LKKAN	Consultants hence notify	S	2,010.66	
	ESTIMATE TOTAL Kahin (10/4) 10/4/19 1055L 2 by- 11/4 Pepoi phe	* To rve * To a,	berge after spray name			
	1112/2	* Paris :	amaged parts during resurvey			
	10/1/17 10552	• No thegal m	of arms a hill of Arejudice	basis		
	- ha	· Supporting	r of 5 m pr of all of all all all all all all all all all al	lid.		
	2 09	Acknowleagea	0.00	any	-	
	111	Signature:	By Replace			
	After Regar photo	ate:				
	/ /			-		