

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19012240/BBA3Q2

Date: 28/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SGS822L **Insured Vehicle No :** SML8401G

Date of Loss: 10/07/2019 **Nature of Claim:** TP **Claim No:** 5800067222SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS822L	Engine No:	K4MC813R032402
Make & Model:	RENAULT MEGANE, 1.6 (A)	Chassis No:	VF1LM0J0E41893658
Reg. Date:	26/05/2010 (Man. Year: 2009)	Odometer:	79444 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,891.20	6,231.70	2,659.50	29.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,820.00	1,480.00	44.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,191.20	8,051.70	4,139.50	33.95
Approved Total (Overridden) (\$\$)		6,400.00		
Nett Amount (\$\$)	12,191.20	6,400.00	5,791.20	47.50
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (\$\$)		535.00		
+ Doc/Search Fee (\$\$)		29.00		
Nett Liability (\$\$)		6,964.00		

INSPECTION

Date of Assignment: 10/07/2019

Date Inspected: 10/07/2019 Inspected At:

TEAM AUTOPRO PTE LTD
160 SIN MING DR #01-14 SIN MING
AUTO CITY
SINGAPORE 575722

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,890.00 FL	*1,800.00 FL
2	1		*BOOTLID LOGO	Necessary	283.00 FL	*180.00 FL
3	1		*BOOTLID EMBLEM MEGANE	Necessary	92.00 FL	*92.00 FL
4	1		*BOOTLID OUTER HANDLE	Not Necessary	239.00 FL	*- FL
5	1		*REAR BUMPER	Cut	962.00 FL	*962.00 FL
6	2		*REAR BUMPER RETAINER	Necessary	242.00 FL	*220.00 FL
7	1		*REAR BUMPER CARRIER	Broken	488.00 FL	*488.00 FL
8	2		*REAR BUMPER BRACKET	Broken (1 PCS ONLY)	202.00 FL	*101.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	853.00 FL	*680.00 FL
10	1		*REAR BUMPER PROTECTOR	Dented	629.00 FL	*629.00 FL
11	1		*REAR END PANEL	Dented	927.00 FL	*780.00 FL
12	1		*REAR END PANEL TOP GARNISH	Dislodged	98.00 FL	*98.00 FL
13	1		*TAILLAMP RH	Broken	385.00 FL	*385.00 FL
14	1		*TAILLAMP LOWER BRACKET RH	Broken	98.00 FL	*98.00 FL
15	1		*SPARE TYRE PANEL	Not Necessary	1,680.00 FL	*- FL
16	1		*SUNRIES	Not Necessary	50.00 FS	*- FS
17	2		*REVERSE SENSOR C/W CONTROL MODULE	Damaged	400.00 FS	*200.00 FS
18	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
21	1		*TAILLAMP CLIPS RH	Not Necessary	50.00 FS	*- FS
22	1		*REAR BUMPER CARRIER RIVET	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,798.00	6,883.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	906.80	651.30
Total Parts (\$\$)	8,891.20	6,231.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R BOOTLID COMPONENT	New	100.00	50.00
2	R&R REVERSE SENSOR	New	100.00	60.00
3	R&R UPHOLSTERY	New	100.00	0.00
4	R&R WIRE HARNESS AND CHECK FUNCTION	New	100.00	50.00
5	PANEL BEAT	New	1,400.00	800.00
6	RUST PROOFING	New	100.00	60.00
7	SPRAY PAINTING	New	1,400.00	800.00
Gross Labour Cost (\$\$)			3,300.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >