

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19012243/NKA3Q2

Date: 19/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLQ9406Y **Insured Vehicle No :** SLA3671X

Date of Loss: 06/07/2019 **Nature of Claim:** TP **Claim No:** 6401890892SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ9406Y	Engine No:	CAW065446
Make & Model:	VOLKSWAGEN SCIROCCO, 2.0 TSI (A)	Chassis No:	WVWZZZ13ZAV403391
Reg. Date:	31/08/2009 (Man. Year: 2009)	Odometer:	188807 km
Colour:	Green		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,831.67	6,528.46	23,303.21	78.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	1,290.00	1,370.00	51.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,491.67	7,818.46	24,673.21	75.94
Approved Total (Overridden) (S\$)		6,250.00		
(S\$)	32,491.67	6,250.00	26,241.67	80.76
+ GST 7.00/7.00% (S\$)	2,274.42	437.50	1,836.92	80.76
Nett Amount (S\$)	34,766.09	6,687.50	28,078.59	80.76
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		7,174.99		
Global Sum Settlement (S\$)		7,100.00		

INSPECTION

Date of Assignment: 10/07/2019

Date Inspected: 10/07/2019 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Cracked	1,475.94 FL	*1,475.94 FL
2	1	*FRONT BUMPER LOWER GRILLE	Deformed	314.50 FL	*314.50 FL
3	1	*FRONT RH FOG LAMP	Cracked	245.95 FL	*245.95 FL
4	1	*FRONT RH FOG LAMP GARNISH	Deformed	194.75 FL	*194.75 FL
5	1	*FRONT RH SIGNAL LAMP	Serviceable	180.00 FL	*- FL
6	2	*FRONT BUMPER RETAINER	Serviceable	132.50 FL	*- FL
7	1	*FRONT RH FENDER	Deformed	832.12 FL	*832.12 FL
8	1	*FRONT RH FENDER INNER SHIELD	Serviceable	193.50 FL	*- FL
9	1	*FRONT RH KNUCKLE ARM	Serviceable	631.60 FL	*- FL
10	1	*FRONT RH KNUCKLE ARM BEARING	Serviceable	491.60 FL	*- FL
11	1	*FRONT RH LOWER ARM	Bent	357.25 FL	*357.25 FL
12	1	*FRONT RH DRIVE SHAFT	Serviceable	2,465.15 FL	*- FL
13	1	*STEERING RACK AND PINION	Serviceable	4,878.15 FL	*- FL
14	1	*FRONT RH ABS SENSOR	Serviceable	183.74 FL	*- FL
15	1	*FRONT RH TIE ROD	Serviceable	161.85 FL	*- FL
16	1	*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
17	1	*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	30.00 FS	*- FS
18	1	*FRONT RH HEADLAMP (AFTER MARKET)	Deformed	2,500.00 FS	*900.00 FS
19	1	*FRONT BONNET (CARBON FIBER)	Repair	2,500.00 FS	*- FS
20	1	*RIM (TSW)	Deformed	2,500.00 FS	*1,500.00 FS
21	1	*BOT BRAKE FUILD	Not Necessary	60.00 FS	*- FS
22	1	*SET SHOCK ABSORBER (AFTER MARKET)	Deformed	4,500.00 FS	*600.00 FS
23	1	*SET BRAKE KIT (SCIROCCO R) /BRAKE CALIPER	Serviceable	3,500.00 FS	*- FS
24	1	*SET DISC ROTOR	Serviceable	1,600.00 FS	*- FS
25	1	*FRONT STICKER (2.0)	Necessary	50.00 FS	*20.00 FS
26	1	*FRONT BUMPER STICKER	Necessary	100.00 FS	*40.00 FS
27	1	*TYRE	Punctured	350.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **30,468.60** **6,870.51**
- List Item Discount on L Items 5.00/10.00% (\$\$) **636.93** **342.05**

Total Parts (\$\$) **29,831.67** **6,528.46**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	DIAGNOIS CHECK AND CLEAR FAULT CODE	New	300.00	150.00
3	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	New	150.00	60.00
4	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	200.00	0.00
5	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	600.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	400.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	50.00
Gross Labour Cost (\$\$)			2,660.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >