



INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00014993	Date of Loss:	09/07/2019
Vehicle Reg. No.:	SKQ8754K	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIN MINGRUI	Contact No:	+6592211242
Driver:	LIN MINGRUI		
Make/Model:	MERCEDES-BENZ C180, 1.8 (A)	Vehicle Reg. Date:	13/10/2010
Vehicle Colour:	BLACK		
Engine No:	27182030083120	Chassis No:	WDD2040492A406016
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO THE SKETCH PLAN		
Remarks:	VEHICLE AT ETHOZ BUKIT BATOK		
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)		

COST OF CLAIMS	Amount
Parts	7,996.00
Miscellaneous Items	65.00
Labour	2,485.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,546.00
+ GST 7.00% (S\$)	738.22
Nett Amount (S\$)	11,284.22

This claim is handled by: **KENNETH CORNELIUS / SIN / 8822 8339**

Generated using Merimen e-Claims Internet Estimation & Adjusting System



INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00014993	Date of Loss:	09/07/2019
Vehicle Reg. No.:	SKQ8754K	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIN MINGRUI	Contact No:	+6592211242
Driver:	LIN MINGRUI		
Make/Model:	MERCEDES-BENZ C180, 1.8 (A)	Vehicle Reg. Date:	13/10/2010
Vehicle Colour:	BLACK		
Engine No:	27182030083120	Chassis No:	WDD2040492A406016
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO THE SKETCH PLAN		
Remarks:	VEHICLE AT ETHOZ BUKIT BATOK		
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)		

COST OF CLAIMS	Amount
Parts	7,996.00
Miscellaneous Items	65.00
Labour	2,485.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,546.00
+ GST 7.00% (S\$)	738.22
Nett Amount (S\$)	11,284.22

This claim is handled by: KENNETH CORNELIUS / SIN / 8822 8339

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Parts

Particulars

	%Disc	%Depr	Amount
*FRONT BONNET <i>bt</i>	0.00	0.00	*900.00 F
*FRONT BONNET EMBLEM <i>mis</i>	0.00	0.00	*43.00 F
*FRONT BONNET HINGE LH <i>X</i>	0.00	0.00	*57.00 F
*FRONT BONNET HINGE RH <i>X</i>	0.00	0.00	*57.00 F
*FRONT BONNET INSULATOR <i>X</i>	0.00	0.00	*160.00 F
*FRONT BONNET INSULATOR CLIP <i>ne</i>	0.00	0.00	*38.00 F
*FRONT BONNET STOPPER LH (SPRING) <i>ne</i>	0.00	0.00	*9.00 F
*FRONT BONNET STOPPER RH (SPRING) <i>ne</i>	0.00	0.00	*9.00 F
*FRONT BONNET UPPER CATCH (LH) <i>X</i>	0.00	0.00	*30.00 F
*FRONT BONNET UPPER CATCH (RH) <i>X</i>	0.00	0.00	*30.00 F
*FRONT BONNET UPPER CATCH (CENTRE) <i>bt</i>	0.00	0.00	*45.00 F
*FRONT BONNET LOWER LOCK (LH) <i>X</i>	0.00	0.00	*36.00 F
*FRONT BONNET LOWER LOCK (RH) <i>X</i>	0.00	0.00	*36.00 F
*FRONT FENDER RH	0.00	0.00	-
REPAIR			
*FRONT FENDER LH <i>bt</i>	0.00	0.00	*420.00 F
*FRONT FENDER EMBLEM (LH) <i>ne</i>	0.00	0.00	*35.00 F
*FRONT FENDER CHROME PROTECTOR (LH) <i>ne</i>	0.00	0.00	*22.00 F
*FRONT FENDER INNER SHIELD LH (FRT) <i>X</i>	0.00	0.00	*86.00 F
*FRONT FENDER INNER SHIELD LH (REAR) <i>X</i>	0.00	0.00	*80.00 F
*FRONT FENDER INNER SHIELD CLIP <i>ne</i>	0.00	0.00	*30.00 F
*HEADLAMP LH <i>era</i>	0.00	0.00	*400.00 F
*HEADLAMP RH <i>era</i>	0.00	0.00	*400.00 F
*FRONT GRILLE <i>era</i>	0.00	0.00	*330.00 F
*FRONT GRILLE LOGO BASE <i>era</i>	0.00	0.00	*41.00 F
*FRONT GRILLE LOGO <i>era</i>	0.00	0.00	*85.00 F
*HEADLAMP TOP COVER (LH) <i>de</i>	0.00	0.00	*13.00 F
*HEADLAMP TOP COVER (RH) <i>de</i>	0.00	0.00	*13.00 F
*FRONT BUMPER <i>de</i>	0.00	0.00	*920.00 F
*FRONT BUMPER CLIP <i>ne</i>	0.00	0.00	*30.00 F
*FRONT NUMBER PLATE BASE <i>era</i>	0.00	0.00	*70.00 F
*FRONT BUMPER TOWING COVER <i>su</i>	0.00	0.00	*31.00 F
*FRONT BUMPER CHROME MOULDING (LH) <i>ne</i>	0.00	0.00	*47.00 F
*FRONT BUMPER CHROME MOULDING (RH) <i>ne</i>	0.00	0.00	*47.00 F
*FRONT BUMPER LOWER GRILLE <i>?</i>	0.00	0.00	*46.00 F
*FRONT BUMPER INNER FRAME (LH) <i>?</i>	0.00	0.00	*50.00 F
*FRONT BUMPER INNER FRAME (RH) <i>?</i>	0.00	0.00	*50.00 F
*FRONT BUMPER INNER FRAME (CENTRE) <i>?</i>	0.00	0.00	*45.00 F
*FRONT BUMPER FOAM <i>ent</i>	0.00	0.00	*90.00 F
*FRONT BUMPER REINFORCEMENT <i>bt</i>	0.00	0.00	*165.00 F
*FRONT BUMPER REINFORCEMENT ARM (LH) <i>?</i>	0.00	0.00	*145.00 F
*FRONT BUMPER REINFORCEMENT ARM (RH) <i>?</i>	0.00	0.00	*145.00 F
*SUPPORT TOP PANEL <i>bt</i>	0.00	0.00	*76.00 F
*SUPPORT PANEL TOP GARNISH <i>era</i>	0.00	0.00	*65.00 F
*HEADLAMP PANEL (LH) <i>bt</i>	0.00	0.00	*115.00 F

ETHOZ Protect Pte Ltd/SKQ8754K/11/07/2019 10:45. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Repairer Estimates

o. Particulars	%Disc	%Depr	Amount
*HEADLAMP PANEL (RH) <i>bt ✓</i>	0.00	0.00	*115.00 F
*HEADLAMP LOWER BRACKET (LH) <i>?</i>	0.00	0.00	*17.00 F
*HEADLAMP LOWER BRACKET (RH) <i>?</i>	0.00	0.00	*17.00 F
*RADIATOR AIR GUIDE (UPPER) <i>ad ✓</i>	0.00	0.00	*32.00 F
*RADIATOR AIR GUIDE (LOWER) <i>?</i>	0.00	0.00	*88.00 F
*BRACE PANEL <i>bt ✓</i>	0.00	0.00	*41.00 F
*INTERCOOLER <i>?</i>	0.00	0.00	*430.00 F
*CONDENSER <i>?</i>	0.00	0.00	*600.00 F
*RADIATOR <i>?</i>	0.00	0.00	*390.00 F
*RADIATOR TOP BRACKET <i>?</i>	0.00	0.00	*30.00 F
*RADIATOR TOP CLIP <i>?</i>	0.00	0.00	*14.00 F
*RADIATOR FAN ASSY <i>?</i>	0.00	0.00	*520.00 F
*POWER STEERING TUBE <i>?</i>	0.00	0.00	*160.00 F
*A PILLAR LH REPAIR	0.00	0.00	-
*A PILLAR RH REPAIR	0.00	0.00	-

Total Parts (S\$)

7,996.00

ETHOZ Protect Pte Ltd/SKQ8754K/11/07/2019 10:45. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

ASSIGNMENT

Repairer Estimates

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			35.00
1	1	FRONT NUMBER PLATE <i>CR</i>	30.00
2	1	RADIATOR COOLANT ?	
Sub Total (S\$)			65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO CARRY OUT FRONT REPAIR	New	<i>770</i> 900.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	35.00
3	TO SPRAY PAINTING ON FRONT AFFECTED AREA	New	<i>800</i> 1,100.00
4	TO REMOVE & FIX AIR COND CONDENSER INCLUDING TOP UP AIR COND GAS	New	<i>1000</i> 150.00
5	PULL OFF STRAIGHTENING FRONT CHASSIS MEMBER LH RH	New	<i>2000</i> 300.00
Gross Labour Cost (S\$)			2,485.00

ETHOZ Protect Pte Ltd/SKQ8754K/11/07/2019 10:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD 30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>
Company Registration No. 199005791M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
6 days
12/07/19 @ 0900
Excess: 600
Revert
P/P
Ready before paint