

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS FIRST CAPITAL INSURANCE LTD			Ref: CS/FCI19012284/Utf3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 18-07-2019 Code: FCI2		
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 3319B	Veh. Inspected	GBE 7807T	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D19003382MFSH	Excess (\$)	0.00	
	Assign From	SERENE LER	Assign Date	11/07/2019	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE (M)	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JTFHT02P900193289	Colour	WHITE	
	Odometer	46662	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195 R15	AUSTONE	6 mm	
	L/H Front Tyre	195 R15	AUSTONE	6 mm	
	R/H Rear Tyre	195 R15	AUSTONE	6 mm	
	L/H Rear Tyre	195 R15	AUSTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	18/05/2019	Inspection Date	11/07/2019	
	Survey held at	ey held at LIU'S BROTHER AUTO WORK SHOP			
		1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883			
5a.	a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				