



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 3387U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT (CONSISTENT)	NOT NECESSARY	710.00	-
1	REAR BOOT LOCK (CONSISTENT)	NOT NECESSARY	151.00	-
1	REAR BOOT EMBLEM (COROLLA) (CONSISTENT)	NOT NECESSARY	49.00	-
1	REAR BOOT EMBLEM (AXIO) (CONSISTENT)	NOT NECESSARY	58.00	-
2	REAR BOOT HINGE L+R @\$70.00 (CONSISTENT)	NOT NECESSARY	140.00	-
1	REAR BOOT WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	187.00	-
2	TAIL LAMP L+R @\$308.00 (CONSISTENT)	NOT NECESSARY	616.00	-
1	SET TAIL LAMP CLIP (CONSISTENT)	NOT NECESSARY	20.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	759.30	477.00
2	REAR BUMPER RETAINER L+R (CONSISTENT)	NECESSARY	310.00	170.00
1	SET REAR BUMPER CLIP (CONSISTENT)	NECESSARY	40.00	40.00
2	REAR BUMPER REFLECTOR L+R @\$38.00 (CONSISTENT)	NOT NECESSARY	76.00	-
2	REAR BUMPER BRACKET L+R @\$97.00 (CONSISTENT)	NOT NECESSARY	194.00	-
1	END PANEL (CONSISTENT)	NOT NECESSARY	662.00	-
1	END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	166.00	-
1	SET END PANEL TOP TRIM CLIP (CONSISTENT)	NOT NECESSARY	10.00	-
1	SPAREWHEEL PANEL (CONSISTENT)	NOT NECESSARY	1,030.00	-
1	SPAREWHEEL PANEL TOP BOARD (CONSISTENT)	NOT NECESSARY	309.00	-
	LESS 25% DISCOUNT		-	-171.75
			5,487.30	515.25
<u>SPECIAL NETT ITEMS</u>				
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	250.00	-
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
			390.00	-
<u>LABOUR</u>				
	TO KNOCK ,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA.		1,200.00	200.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		1,000.00	200.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.	NOT NECESSARY	60.00	-

Report Ref No. CC4/ASM19012289/Aps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO R&R REAR BOOT MECHANISM .	NOT NECESSARY	120.00	-
	TO R&R REAR LUGGAGE COMPARTMENT.	NOT NECESSARY	120.00	-
	TO R&R REVERSE SENSOR & CHECK FUNCTION .		80.00	50.00
	TO CHECK WATER SEEPAGE.	NOT NECESSARY	60.00	-
			2,640.00	450.00
GRAND TOTAL			8,517.30	965.25

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			750.00
---	--	--	---------------

Report Ref No. CC4/ASM19012289/Aps3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.