

Adjuster Letter/DV not verified.
This claim is to be authorized on the insurer's behalf.
Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.
Click on 'View Letter/DV' to verify the offer.

You cannot authorize this offer because
Adjuster Letter/DV not verified.
File to be authorized by your superior.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19012306/UGS3Q2
Date: 30/12/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No	SJJ1253J	Insured Vehicle No :	SJS7241G
Date of Loss:	09/07/2019	Nature of Claim:	TP
		Claim No:	3147562277SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ1253J	Engine No:	1NZX794597
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305078432
Reg. Date:	02/09/2008 (Man. Year: 2008)	Odometer:	232735 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,652.45	1,315.55	1,336.90	50.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,230.00	700.00	36.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,582.45	2,545.55	2,036.90	44.45
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	4,582.45	2,000.00	2,582.45	56.36
+ GST 7.00/7.00% (S\$)	320.77	140.00	180.77	56.36
Nett Amount (S\$)	4,903.22	2,140.00	2,763.22	56.36
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 15/07/2019

12/30/2020

Merimen e-Claims

Date Inspected: 15/07/2019
Estimated Period of Repair: 3.0 days

Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID VIOS BADGE	Necessary	48.00 FL	*48.00 FL
2	1		*BOOTLID SPORTS BADGE	Necessary	50.00 FL	*50.00 FL
3	1		*BOOTLID CENTRE LOGO	Necessary	55.00 FL	*55.00 FL
4	1		*BOOTLID E BADGE	Necessary	45.00 FL	*45.00 FL
5	1		*REAR BUMPER	Dented / Deformed	455.00 FL	*455.00 FL
6	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	200.00 FL	*- FL
7	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	70.00 FL	*- FL
8	2		*REAR BUMPER REFLECTORS	Not Necessary	180.00 FL	*- FL
9	8		*REAR BUMPER FASTENER CLIPS	Necessary	34.40 FL	*34.40 FL
10	2		*REAR BUMPER SPLASHIELD COVER	Not Necessary	100.00 FL	*- FL
11	1		*REAR END PANEL	Repair	605.00 FL	*- FL
12	1		*REAR END PANEL INNER TRIM	Not Necessary	80.70 FL	*- FL
13	3		*REAR END PANEL INNER TRIM CLIPS	Not Necessary	13.50 FL	*- FL
14	1		*SET REAR BUMPER PARKING SENSOR	Shorted	400.00 FS	*200.00 FS
15	1		*REAR BUMPER LOWER SPOILER (AFTER MARKET ACCESSORY)	Cracked	800.00 FS	*600.00 FS
					Sub Total (S\$)	3,136.60 1,487.40
					- List Item Discount on L Items 25.00/25.00% (S\$)	484.15 171.85
					Total Parts (S\$)	2,652.45 1,315.55

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	150.00	60.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	400.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	700.00
Gross Labour Cost (S\$)			1,930.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >