

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19012310/TEA3Q2**Date:** 16/06/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLV1136C**Insured Vehicle No :** SKX2696Y

Date of Loss: 07/07/2019

Nature of Claim: TP

Claim No: 6186853578SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLV1136C**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A)

Engine No: 2ZR8180700

Reg. Date: 21/12/2017 (Man. Year: 2017)

Chassis No: ZYX102069976

Colour: Silver

Odometer: 98928 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,042.25	6,125.65	11,916.60	66.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,350.00	2,030.00	3,320.00	62.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,392.25	8,155.65	15,236.60	65.14
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	23,392.25	6,500.00	16,892.25	72.21
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,407.45		

INSPECTION

Date of Assignment: 11/07/2019

Date Inspected: 12/07/2019 Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)

13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre

Singapore 417807

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	980.00 FL	*733.00 FL
2	1		*FRONT FENDER SPLASH SHIELD RH	Deformed	253.00 FL	*121.50 FL
3	1		*FRONT FENDER ARCH RH	Deformed	220.00 FL	*220.00 FL
4	1		*FRONT BONNET	Repair	2,550.00 FL	*- FL
5	2		*FRONT BONNET HINGE LH & RH	Not Necessary	220.00 FL	*- FL
6	1		*FRONT BUMPER	Deformed	1,850.00 FL	*1,236.70 FL
7	1		*FRONT BUMPER SIDE RETAINER LH & RH	Deformed	240.00 FL	*240.00 FL
8	1		*FRONT BUMPER FOG LAMP GRILLE RH	Cut	125.00 FL	*125.00 FL
9	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	540.00 FL	*- FL
10	1		*FRONT BUMPER CENTRE CHOME GRILLE	Not Necessary	315.00 FL	*- FL
11	1		*FRONT BUMPER LOWER MOULDING	Cut	318.00 FL	*318.00 FL
12	1		*FRONT BUMPER LOWER SPOILER	Deformed	980.00 FL	*800.00 FL
13	1		*FRONT BUMPER SIDE LAMP	Cut	240.00 FL	*240.00 FL
14	1		*FRONT WASHER TANK W/MOTOR	Not Necessary	342.00 FL	*- FL
15	1		*FRONT HEADLAMP RH	Cut	1,310.00 FL	*1,310.00 FL
16	1		*FRONT DOOR RH	Not Necessary	1,320.00 FL	*- FL
17	1		*FRONT INNER DOOR BOARD RH	Not Necessary	590.00 FL	*- FL
18	1		*FRONT DOOR LOWER MOULDING RH	Not Necessary	242.00 FL	*- FL
19	1		*FRONT DOOR UPPER MOULDING RH	Not Necessary	211.00 FL	*- FL
20	1		*FRONT DOOR GLASS RUN CHANNEL RH	Not Necessary	142.00 FL	*- FL
21	1		*FRONT DOOR LOWER TRIM COVER	Not Necessary	342.00 FL	*- FL
22	1		*FRONT DOOR BLACK TAPE	Not Necessary	25.00 FL	*- FL
23	1		*FRONT DOOR LOCK RH	Not Necessary	520.00 FL	*- FL
24	1		*FRONT DOOR POWER WINDOW REGULATOR RH	Not Necessary	585.00 FL	*- FL
25	1		*REAR DOOR RH	Not Necessary	1,420.00 FL	*- FL
26	1		*REAR INNER DOOR BOARD RH	Not Necessary	490.00 FL	*- FL
27	1		*REAR DOOR GLASS RUN CHANNEL RH	Not Necessary	142.00 FL	*- FL
28	1		*REAR DOOR LOWER MOULDING RH	Not Necessary	242.00 FL	*- FL
29	1		*REAR DOOR UPPER MOULDING RH	Not Necessary	211.00 FL	*- FL
30	1		*REAR DOOR LOWER TRIM COVER RH	Not Necessary	342.00 FL	*- FL
31	1		*REAR DOOR BLACK TAPE RH	Not Necessary	25.00 FL	*- FL
32	1		*REAR DOOR POWER WINDOW REGULATOR RH	Not Necessary	585.00 FL	*- FL
33	1		*REAR FENDER ARHC RH	Not Necessary	210.00 FL	*- FL
34	1		*FRONT ROCKER PANEL RH	Not Necessary	645.00 FL	*- FL
35	1		*FRONT SHOCK ABSORBER RH	Bent	592.00 FL	*456.00 FL
36	1		*FRONT LOWER ARM RH	Bent	298.00 FL	*298.00 FL
37	1		*FRONT TIE ROD RH	Not Necessary	145.00 FL	*- FL
38	1		*FRONT WHEEL BEARING RH	Bent	278.00 FL	*278.00 FL
39	1		*FRONT KNUCKLE ARM RH	Bent	398.00 FL	*398.00 FL
40	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	80.00 FS	*20.00 FS
41	1		*SET FRONT BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS
42	1		*FRONT FENDER HYBRID EMBLEM	Necessary	85.00 FS	*85.00 FS
43	5		*FRONT DOOR SMALL STICKER	Not Necessary	175.00 FS	*- FS
44	1		*FRONT BODY BIG STICKER	Not Necessary	300.00 FS	*- FS
45	1		*FRONT FENDER GRILLE RH	Cut	310.00 FS	*310.00 FS
46	1		*SET DOOR VISOR	Not Necessary	280.00 FS	*- FS
47	1		*FRONT 18 TYRE RH	Not Necessary	350.00 FS	*- FS
48	1		*FRONT SPORT RIM RH	Necessary	980.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,163.00	7,819.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,120.75	1,693.55
Total Parts (\$\$)	18,042.25	6,125.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIR AND REPLACE DAMAGED PARTS.	New	2,200.00	800.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED.	New	1,800.00	800.00
3	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION.	New	150.00	30.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	New	180.00	40.00
5	TO CHECK WIRING AND FOCUS HEADLAMP BEAM.	New	150.00	30.00
6	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RES TO PSECIFICATION.	New	250.00	100.00
7	TO REMOVE AND REPLACE / REFIX FRONT & REAR DOOR INNER PARTS FITTING ETC RHS.	New	150.00	0.00
8	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT TEST.	New	120.00	80.00
9	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS RHS.	New	350.00	150.00
Gross Labour Cost (\$\$)			5,350.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >