

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19012325/AGQF3E2

Date: 24/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29114889MKC

Claimant
Vehicle No : SLD1276B

Insured Vehicle No : GBB9763M

Date of Loss: 09/07/2019

Nature of Claim: TP

Claim No: 599325

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD1276B**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A)

Engine No: 1ZRX571488

Reg. Date: 03/06/2016 (Man. Year: 2016)

Chassis No: MR053REH104550410

Colour: Blue

Odometer: 0 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,567.80	2,551.91	2,015.89	44.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,690.00	1,050.00	38.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,307.80	4,241.91	3,065.89	41.95
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	7,307.80	3,400.00	3,907.80	53.47

INSPECTION

Date of Assignment: 11/07/2019

Date Inspected: 15/07/2019 Inspected At:

Ever Sen Auto Service (HQ)
Blk 3022A, Ubi Road 1, #01-49
Singapore 408716

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1276B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	778.13 F	*778.13 FL
2	1		*BOOT LID CHROME MOULDING	Not Necessary	431.42 F	*- FL
3	2		*BOOT LID HINGE L/H & R/H	Not Necessary	97.80 F	*- FL
4	1		*BOOT LID INNER LOCK	Damaged	260.15 F	*260.15 FL
5	1		*BOOT LID INNER TRIM COVER	Not Necessary	165.20 F	*- FL
6	1		*BOOT LID WEATHERSTRIPE	Not Necessary	157.10 F	*- FL
7	1		*BUMPER-REAR	Deformed	553.43 F	*553.43 FL
8	2		*BUMPER RETAINER	Necessary	132.46 F	*132.46 FL
9	1		*REVERSING SENSOR	Damaged	431.33 FS	*200.00 FS
10	2		*BIG CLIPS	Necessary	108.20 F	*30.00 FL
11	1		*BOOT REFLECTOR - LH	Cracked	170.50 F	*170.50 FL
12	1		*BUMPER BEAM - REAR	Bent	405.54 F	*378.00 FL
13	1		*REAR END PANEL	Dented	560.44 F	*560.44 FL
14	1		*REAR END PANEL CENTRE GARNISH	Deformed	166.10 F	*166.10 FL
15	1		*COROLLA EMBLEM	Necessary	75.00 FS	*40.00 FS
16	1		*ALTIS EMBLEM	Necessary	75.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,567.80	3,309.21
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	757.30
Total Parts (\$\$)	4,567.80	2,551.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ACCIDENT REPAIR PANEL BEATING	New	1,200.00	800.00
2	RESPRAY PAINT WORK ON REPAIR AREA	New	1,200.00	800.00
3	RUSTPROOFING TREATMENT	New	180.00	60.00
4	WIRING SERVICE	New	60.00	30.00
5	CONDUCT WATER LEAK TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			2,740.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >