

Adjuster Letter/DV not verified.
This claim is to be authorized on the insurer's behalf.
Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.
Click on 'View Letter/DV' to verify the offer.

You cannot authorize this offer because
Adjuster Letter/DV not verified.
File to be authorized by your superior.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19012342/KQD3E2

Date: 04/09/2019

REFERENCE

Insured/Claimant:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.	Policy No:	999995580
Date of Loss:	10/07/2019	Nature of Claim:	OD
		Claim No:	3373947805SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF182Y		
Make & Model:	MERCEDES-BENZ GLS400, 3.0 4MATIC (R21 LED SR) (A)	Engine No:	27682130848460
Reg. Date:	17/08/2018 (Man. Year: 2018)	Chassis No:	WDC1668562B137766
Colour:	Metallic Dark Blue	Odometer:	40204 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	S\$330,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/40Z R21	Rear Tyre Size:	295/40Z R21
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,229.00	6,099.50	3,129.50	33.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,000.00	1,580.00	61.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,809.00	7,099.50	4,709.50	39.88
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	10,309.00	5,599.50	4,709.50	45.68
+ GST 7.00/7.00% (S\$)	721.63	391.97	329.66	45.68
Nett Amount (S\$)	11,030.63	5,991.47	5,039.16	45.68

INSPECTION

Date of Assignment:	12/07/2019		Tong Luck Auto Pte Ltd (HQ) 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722
Date Inspected:	12/07/2019	Inspected At:	
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH (WCP)	Repair	2,400.00 F	*- F
2	1		*FRONT DOOR WEATHERSTRIP - LH (WCP)	Serviceable	185.00 F	*- F
3	20		*FRONT DOOR TRIMBOARD RIVETS - LH (WCP)	Not Necessary	130.00 F	*- F
4	1		*REAR DOOR - LH (WCP)	Bent	2,600.00 F	*2,600.00 F
5	1		*REAR DOOR WEATHERSTRIP - LH (WCP)	Necessary	185.00 F	*185.00 F
6	20		*REAR DOOR TRIMBOARD RIVETS - LH	Not Necessary	143.00 FS	*- FS
7	1		*STEPBOARD GARNISH - LH (WCP)	Cracked	1,350.00 F	*1,350.00 F
8	1		*STEPBOARD GARNISH CHROME - LH (WCP)	Bent	350.00 F	*350.00 F
9	8		*STEPBOARD GARNISH CLIPS - LH (WCP)	Necessary	80.00 F	*80.00 F
10	1		*STEPBOARD CARRIER - LH (WCP)	Cracked	980.00 F	*980.00 F
					Sub Total (\$)	8,403.00
					+ Margin on L,N Items 10.00/10.00% (\$)	826.00
					Total Parts (\$)	9,229.00
						5,545.00
						554.50
						6,099.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER LH FRONT & REAR DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR	New	300.00	80.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN LH CENTRE DOOR PILLAR INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	500.00
4	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS	New	1,200.00	400.00
Gross Labour Cost (S\$)			2,580.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >