

ASS. REC. BY:

REF: CS/MSG190123741 Df342

Special Instruction:

Surveyor: Bryan

## ASSIGNMENT (Office)

From (Person): Irene Tan Gek Ing

of MSG

Date/Time: 12.7.19 15.19p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHA 4641Z

Insured:

SLM 69720

at Workshop m/s Chuan's moto

Tel:

64836016

of BIK 10 A 01-05/06 Amt Autopoint

Policy No: 29088463

Claim No:

599543

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12.7.19 3.27p.m

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 4641Z - CS/TMI 18 001821 / LUK2

DoAS - 26/01/2018

SLM 69720 - X

15/7@2:24pm - Revised via preli advise.

ASS. REC. BY:

## ASSIGNMENT

COE June 2025

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHA 4641Z Yr Regn: 2017 JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Toyota Prime C.C. 1798Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 272221 T/Radio: Insured / Std / NI / NAEng/No: 2ZRS051080C/No: 5TDBB3FU903559561Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SR / STD A/Rim orTyre Size: F: 195/65R15R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Davanti

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 10/07/2019 D.O.I. 12/07/2019Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front 4/8

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MSIG SLM 6972U

14/09/19 Jnprl 2/5 10700/- wtu 8 days of rep (Red: 11603:52%)

RECEIVED 16 SEP 2019

  
13/9/2019

Date/Time, File Pass to?



Preli. Report

1) DLA typist

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )Survey Fee: 200

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

211Report Format : TPLump Sum / I.B.I. (\$) 10700/-

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2019 09:38		12 Jul 2019 15:19 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA4641Z	Date of Loss:	10/07/2019 13:00 - :59 [24 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 599543	Policy/Cover Note No.:	29088463 (Comprehensive) Coverage: 02/07/2018 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLM6972U	Policy No. (Claimant):							
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/07/2019]								
Driver/Custodian (Insured):	GOH YONG TONG ( / Male) , NRIC: S6821792Z Email:								
Adj Asg. Remarks:	on WP. Oi: Grab. Liab: 100%. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn or Ms Irene @ 6542 5119 / 6542 7162.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All   Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All   Search Tasks   Create New Task   Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 15 Jul 2019

## Preliminary Advice

Insured Vehicle No	: SLM6972U	Accident Date	: 10/07/2019
TP Vehicle No	: SHA4641Z	Assignment Date	: 12/07/2019
Make	: TOYOTA PRIUS HYBRID	Est. Duration of Repair	: 0.00
Date of Inspection	: 12/07/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,913.02
Revised Amount	:S\$	14,387.18
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,387.18

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

( ) The vehicle is economical/not economical for repair.

( x ) The above survey was conducted on a 'without prejudice' basis.

MC0619090208 / ComfortDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 10/07/2019 15:37  
 SUBMITTED BY: Janet Lim Slang Gek

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/07/2019 15:37
Date Of Accident	10/07/2019 14:15
Exact Location Of Accident	MOULMEIN RD T JUNCTION JALAN TAN TOCK SENG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4641Z
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
<b>Driver</b>	
Name of Driver	YEO TENG CHAI
NRIC No	S1185017J
Date Of Birth	16/06/1956
Occupation	OUTDOOR
Date Of Driving Pass	06/07/1974
Driving Experience	45 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97718250
Fax Number	
Contact Number	
Email Address	YEO.ROCTC@YAHOO.COM

Address BLK 272D SENGKANG CENTRAL  
#08-349  
Postcode 544272  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1

NAME: : -  
GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED \* TYPE OF ACCIDENT :- HEAD TO SIDE

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: -  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLM6972U  
Vehicle Make/Model/Colour MAZDA  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver GOH YONG TONG  
NRIC/Passport Number S6821792Z  
Contact Number  
Address  
Postcode  
Insurance Company Name

Nature Of Damage

LH CENTRE

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name YEO TENG CHAI

Approximate Age

Injuries Sustain

BACK AND LEG

Injured person in which vehicle?

SHA4641Z

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 10.07.2019@1530HRS

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: June



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10.07.2019 @ 1415HRS I was travelling along Moulmein Road T Junction Jalan Tan Tock Seng with 1 female passenger onboard.

As I was travelling straight suddenly veh(B) SLM 6972U dashed out from my front and hit onto my vehicle front portion.

As it took place too fast I could not take evasive action to prevent the accident.

I have company photo and video at scene to support my claims.

After the accident I felt pain on my back and leg. I will consult a doctor later.

Veh(B) SLM 6972U MR Goh Yong Tong

## DECLARATION

I/We declare the foregoing particulars are true in every respect.  
COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

*[Signature]*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 10.07.2019@1530HRS

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: June

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE**

VEHICLE NO: SHA 4641Z

DATE : 10.07.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

MCMG

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
BONNET <i>1st</i>			\$ 950.50
BONNET LOCK <i>1st</i>			\$ 132.60
RADIATOR GRILLE <i>defunct</i>			\$ 438.00
RADIATOR GRILLE EMBLEM <i>cut</i>			\$ 88.00
LAMP ASSY, FOG, LH/RH <i>N/S broken O/S NH</i>		\$ 920.00	\$ 1,840.00
FRONT BUMPER COVER <i>cut</i>			\$ 499.90
FRONT BUMPER REINFORCEMENT <i>1st</i>			\$ 696.40
FRONT BUMPER SPONGE <i>torn</i>			\$ 78.80
FRONT BUMPER CENTRE GRILLE <i>broken</i>			\$ 301.90
FRONT BUMPER CLIPS <i>442</i>			\$ 22.00
FRONT BUMPER SIDE RETAINER, LH <i>NH</i>			\$ 77.00
COVER, FRONT BUMPER HOLE, LH <i>cut</i>			\$ 28.38
FRONT BUMPER LOWER REINFORCEMENT BRACKET (LH/RH) <i>NH</i>		165.00	\$ 330.00
FRONT BUMPER CENTRE FRAME <i>NH</i>			\$ 236.90
BRACKET, FRONT BUMPER SIDE, LH <i>NH</i>			\$ 82.30
ABSORBER, FRONT BUMPER, LOWER (SPONGE LOWER) <i>NH</i>			\$ 127.70
UNIT ASSY, HEADLAMP, RH (LED) <i>monetary clack</i>			\$ 3,455.00
UNIT ASSY, HEADLAMP, LH (LED) <i>monetary broken</i>			\$ 3,455.00
HEAD LAMP PANEL (LH) <i>1st</i>			\$ 240.10
TOP PANEL CENTRE <i>Dental</i>			\$ 364.90
TOP PANEL (LH) <i>1st</i>			\$ 145.90
RADIATOR ASSY <i>1st</i>			\$ 1,881.30
CONDENSER ASSY, W/RECEIVER <i>1st</i>			\$ 1,336.60
FRONT FENDER HYBRID EMBLEM, LH <i>NH</i>			\$ 53.50
BRACE PANEL <i>1st</i>			\$ 75.20
WIRING FRONT <i>1st</i> <del>1st</del> <i>NH</i>			\$ 6,685.90
SUB TOTAL			\$ 23,623.78
LESS 20% <i>25%</i>			\$ 4,724.76
DISCOUNTED TOTAL			\$ 18,899.02
FRONT NO. PLATE <i>cut</i>			\$ 25.00
FRONT NO PLATE TRIM COVER <i>broken</i>			\$ 30.00
FRONT NO.PLATE GARNISH <i>broken</i>			\$ 99.00
			\$ 154.00

15163.98

11372.98

154.00

NETT ✓

NETT ✓

NETT ✓

SHA 4641Z

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
<b>LABOUR CHARGE</b>			
Panel Beating			S 1,000.00 700/-
Spray Painting Charge			S 1,000.00 700/-
Wiring Charge			S 50.00 30/-
Tuff Kote			S 50.00 40/-
Remove/Refix Aircon & Refill Gas			S 150.00 80/-
Remove/Refix Dashboard		1850.00	S 400.00 1150/-
Remove/Refix Fuse Box			S 120.00 150/-
Diagnosis & Resetting To Erase Fault Code			S 480.00 150/-
<b>TOTAL LABOUR</b>			S 3,250.00
<b>ESTIMATE TOTAL</b>			S 22,303.02
<p>12/07/2019 @ 11:30am</p> <p>Mr Andrew</p> <p>2/Share &amp; 8 days</p> <p>Ryan</p> <p>LKK Auto</p>			
<p>13376.98</p> <p>L/S 10700/-</p>			
<p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE**

VEHICLE NO : SHA 4641Z (Supplementary)

DATE : 15.07.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
RADIATOR COOLANT <i>NA</i>			S 40.00
LABOUR CHARGE			
Remove/Refix Engine			S 450.00 <i>250/-</i>
Wheel Alignment			S 120.00 <i>460/-</i>
TOTAL LABOUR			S 570.00
ESTIMATE TOTAL			S 610.00

15/07/2019

*ym**2KK Auto**[Signature]*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2019 09:38		12 Jul 2019 15:19 <a href="#">Edit Adj Rpt</a>	<b>S\$10,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$10,700.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA4641Z	Date of Loss:	10/07/2019 13:00 - :59 [24 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 599543	Policy/Cover Note No.:	29088463 (Comprehensive) Coverage: 02/07/2018 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLM6972U	Policy No. (Claimant):							
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 11/08/2019]								
Driver/Custodian (Insured):	GOH YONG TONG ( / Male) , NRIC: S6821792Z Email:								
Adj Asg. Remarks:	on WP. Oi: Grab. Liab: 100%. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn or Ms Irene @ 6542 5119 / 6542 7162.								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHA4641Z (599543)  
[SLM6972U]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Jul 10 2019 1:00PM  
[GRAB RENTALS PTE LTD]  
Chunni Motor Work Pte Ltd - Amk

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports
























































1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/07/19 14:17	Adjuster Immediate Advice		Load HTM	




















































Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/08/19 10:17	Front View Right		Load JPG	
2	08/08/19 10:17	Front View Left		Load JPG	
3	08/08/19 10:19	General View		Load JPG	
4	08/08/19 10:19	General View		Load JPG	
5	08/08/19 10:19	General View		Load JPG	
6	08/08/19 10:19	General View		Load JPG	
7	08/08/19 10:19	General View		Load JPG	
8	08/08/19 10:19	General View		Load JPG	
9	08/08/19 10:19	General View		Load JPG	
10	08/08/19 10:19	General View		Load JPG	
11	08/08/19 10:19	General View		Load JPG	
12	08/08/19 10:19	General View		Load JPG	
13	08/08/19 10:19	General View		Load JPG	
14	08/08/19 10:19	General View		Load JPG	
15	08/08/19 10:19	General View		Load JPG	
16	08/08/19 10:19	General View		Load JPG	
17	08/08/19 10:19	General View		Load JPG	
18	08/08/19 10:19	General View		Load JPG	
19	08/08/19 10:19	General View		Load JPG	
20	08/08/19 10:19	General View		Load JPG	
21	08/08/19 10:19	General View		Load JPG	
22	08/08/19 10:19	General View		Load JPG	
23	08/08/19 10:19	General View		Load JPG	
24	08/08/19 10:19	General View		Load JPG	
25	08/08/19 10:19	General View		Load JPG	
26	08/08/19 10:19	General View		Load JPG	
27	08/08/19 10:19	General View		Load JPG	
28	08/08/19 10:19	General View		Load JPG	
29	08/08/19 10:19	General View		Load JPG	
30	08/08/19 10:19	General View		Load JPG	
31	08/08/19 10:19	General View		Load JPG	
32	08/08/19 10:19	General View		Load JPG	
33	08/08/19 10:19	General View		Load JPG	
34	08/08/19 10:19	General View		Load JPG	
35	08/08/19 10:19	General View		Load JPG	
36	08/08/19 10:19	General View		Load JPG	
37	08/08/19 10:19	General View		Load JPG	
38	08/08/19 10:19	General View		Load JPG	
39	08/08/19 10:19	General View		Load JPG	
40	08/08/19 10:19	General View		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	08/08/19 10:19	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/08/19 10:19	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/08/19 10:19	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/08/19 10:19	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/08/19 10:19	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/08/19 10:19	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
51	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
52	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
53	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
54	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
55	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
56	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
57	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
58	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
59	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
60	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
61	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
62	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
63	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
64	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
65	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
66	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
67	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
68	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
69	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
70	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
71	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
72	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
73	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
74	08/08/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
75	08/08/19 10:20	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
76	08/08/19 10:20	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
77	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	08/08/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
114	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
115	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
116	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
117	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
118	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
119	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
120	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
121	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
122	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
123	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
124	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
125	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
126	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
127	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
128	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
129	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
130	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
131	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
132	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
133	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
134	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
135	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
136	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
137	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
138	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
139	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
140	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
141	08/08/19 10:21	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
142	08/08/19 10:21	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/07/19 09:39	OI SLM6972U E-FILE REPORT	 Load PDF	
2	11/07/19 09:39	TP SHA4641Z E-FILE REPORT	 Load PDF	
3	11/07/19 09:39	ESTIMATE	 Load PDF	
4	12/07/19 09:36	Acknowledge PRI	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/08/19 10:41	ESTIMATE	 Load PDF	



## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19012374/DTF3E2

Date: 25/09/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29088463

Claimant Vehicle No : SHA4641Z

Insured Vehicle No : SLM6972U

Date of Loss: 10/07/2019

Nature of Claim: TP

Claim No: 599543

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHA4641Z

Make &amp; Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No: 2ZRS051080

Reg. Date: 29/06/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU903559561

Colour: Blue

Odometer: 272221 km

Engine Capacity: 1798 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Davanti 5 mm

Rear Left Side: Davanti 5 mm

Front Right Side: Davanti 5 mm

Rear Right Side: Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,053.02	11,526.98	7,526.04	39.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,850.00	1,400.00	43.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,303.02	13,376.98	8,926.04	40.02
Approved Total (Overridden) (\$\$)		10,700.00		
(\$\$)	22,303.02	10,700.00	11,603.02	52.02
+ GST 7.00/7.00% (\$\$)	1,561.21	749.00	812.21	52.02
Nett Amount (\$\$)	23,864.23	11,449.00	12,415.23	52.02

## INSPECTION

Date of Assignment: 12/07/2019

Date Inspected: 12/07/2019 Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ)  
Blk 10 #01-05/06, AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2019)
<b>Parts:</b>	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA4641Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	950.50 FL	*950.50 FL
2	1		*BONNET LOCK	Bent	132.60 FL	*132.60 FL
3	1		*RADIATOR GRILLE	Deformed	438.00 FL	*438.00 FL
4	1		*RADIATOR GRILLE EMBLEM	Cut	88.00 FL	*88.00 FL
5	1		*LAMP ASSY,FOG,LH/RH	N/s Broken/O/s Not Necessary	1,840.00 FL	*920.00 FL
6	1		*FRONT BUMPER COVER	Cut	499.90 FL	*499.90 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	696.40 FL	*696.40 FL
8	1		*FRONT BUMPER SPONGE	Torn	78.80 FL	*78.80 FL
9	1		*FRONT BUMPER CENTRE GRILLE	Broken	301.90 FL	*301.90 FL
10	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
11	1		*FRONT BUMPER SIDE RETAINER,LH	Not Necessary	77.00 FL	*- FL
12	1		*COVER,FRONT BUMPER HOLE,LH	Cut	28.38 FL	*28.38 FL
13	2		*FRONT BUMPER LOWER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	330.00 FL	*- FL
14	1		*FRONT BUMPER CENTRE FRAME	Not Necessary	236.90 FL	*- FL
15	1		*BRACKET,FRONT BUMPER SIDE,LH	Not Necessary	82.30 FL	*- FL
16	1		*ABSORBER,FRONT BUMPER,LOWER (SPONGE LOWER)	Not Necessary	127.70 FL	*- FL
17	1		*UNIT ASSY,HEADLAMP,RH (LED)	Mounting Cracked	3,455.00 FL	*3,455.00 FL
18	1		*UNIT ASSY,HEADLAMP,LH (LED)	Mounting Broken	3,455.00 FL	*3,455.00 FL
19	1		*HEAD LAMP PANEL (LH)	Bent	240.10 FL	*240.10 FL
20	1		*TOP PANEL CENTRE	Dented	364.90 FL	*364.90 FL
21	1		*TOP PANEL (LH)	Bent	145.90 FL	*145.90 FL
22	1		*RADIATOR ASSY	Bent	1,881.30 FL	*1,881.30 FL
23	1		*CONDENSER ASSY,W/RECEIVER	Bent	1,336.60 FL	*1,336.60 FL
24	1		*FRONT FENDER HYBRID EMBLEM,LH	Necessary	53.50 FL	*53.50 FL
25	1		*BRACE PANEL	Bent	75.20 FL	*75.20 FL
26	1		*WIRING FRONT	Not Necessary	6,685.90 FL	*- FL
27	1		*FRONT NO PLATE GARNISH	Broken	99.00 FS	*99.00 FS
28	1		*FRONT NO PLATE TRIM COVER	Broken	30.00 FS	*30.00 FS
29	1		*FRONT NO PLATE	Cut	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>23,777.78</b>	<b>15,317.98</b>
<b>- List Item Discount on L Items 20.00/25.00% (\$\$)</b>	<b>4,724.76</b>	<b>3,791.00</b>
<b>Total Parts (\$\$)</b>	<b>19,053.02</b>	<b>11,526.98</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,000.00	700.00
2	SPRAY PAINTING CHARGE	New	1,000.00	700.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
5	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
6	REMOVE/REFIX DASHBOARD	New	400.00	150.00
7	DIAGNOSIS & RESETTING TO ERASE FAULT CODE }	New	480.00	150.00
8	REMOVE/REFIX FUSE BOX }	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,250.00</b>	<b>1,850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >