



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 6755L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LH FRONT DOOR (CONSISTENT)	BENT	1,211.40	1,211.40
1	LH FRONT DOOR HINGE TOP (CONSISTENT)	TO REPAIR SEE LABOUR	78.34	-
1	LH FRONT DOOR HINGE BOTTOM (CONSISTENT)	TO REPAIR SEE LABOUR	78.34	-
1	LH FRONT DOOR WEATHERSTRIP (CONSISTENT)	SERVICEABLE	198.70	-
1	LHF DOOR GLASS OUTER MOULDING (CONSISTENT)	SERVICEABLE	107.80	-
1	LHF POWER WINDOW MOTOR(CONSISTENT)	SERVICEABLE	187.90	-
1	LHF POWER WINDOW REGULATOR (CONSISTENT)	SERVICEABLE	570.60	-
1	LH REAR DOOR (CONSISTENT)	BENT	1,211.40	1,211.40
1	LH REAR DOOR HINGE TOP (CONSISTENT)	TO REPAIR SEE LABOUR	78.34	-
1	LH REAR DOOR HINGE BOTTOM (CONSISTENT)	TO REPAIR SEE LABOUR	78.34	-
1	LH REAR DOOR WEATHERSTRIP (CONSISTENT)	CUT	198.70	198.70
1	LHR DOOR GLASS OUTER MOULDING (CONSISTENT)	SERVICEABLE	107.80	-
1	LHR POWER WINDOW MOTOR (CONSISTENT)	SERVICEABLE	187.90	-
1	LHR POWER WINDOW REGULATOR (CONSISTENT)	SERVICEABLE	570.60	-
1	LH SIDE SKIRT (CONSISTENT)	BUCKLED / DENTED	721.50	721.50
	LESS 25% DISCOUNT		-1,396.92	-835.75
			4,190.74	2,507.25
	<b><u>LABOUR</u></b>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA .(LHF DOOR LHR DOOR,LH SIDE SKIRT).INCLUSIVE OF THE REPAIR OF LH FRONT DOOR HINGE TOP,LH FRONT DOOR HINGE BOTTOM,LH REAR DOOR HINGE TOP AND LH REAR DOOR HINGE BOTTOM.		800.00	500.00
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(LHF DOOR LHR DOOR,LH SIDE SKIRT).		800.00	660.00
	TO TUFF COAT.		150.00	60.00
	TO CHECK WIRING .		50.00	20.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT DOOR TRIM ,DOOR GLASS ,WINDOW REGULATOR ,DOOR LOCK TO ASSIST WORK LOAD.		300.00	120.00
			2,100.00	1,360.00
GRAND TOTAL			6,290.74	3,867.25

RECOMMENDED COST OF REPAIRS				3,867.25
-----------------------------	--	--	--	----------

Report Ref No. CC4/ASM19012378/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.