

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19012379/UBA3Q2

Date: 27/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100054698

Claimant
Vehicle No : SLZ7290D **Insured Vehicle No :** SJA5779E

Date of Loss: 11/07/2019 Nature of Claim: TP Claim No: 1884972863SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ7290D		
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Engine No:	A25A5121377
Reg. Date:	05/07/2019 (Man. Year: 2018)	Chassis No:	JTNB23HK303023843
Colour:	Blue	Odometer:	753 km
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,315.30	9,760.42	12,554.88	56.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,750.00	2,180.00	2,570.00	54.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,065.30	11,940.42	15,124.88	55.88
+ GST 7.00/7.00% (S\$)	1,894.57	835.83	1,058.74	55.88
Nett Amount (S\$)	28,959.87	12,776.25	16,183.62	55.88
+ Car Rental (6.5 x S\$50.00/day) (S\$)		325.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,103.25		
Global Sum Settlement (S\$)		13,100.00		

INSPECTION

Date of Assignment: 12/07/2019

Date Inspected: 12/07/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Badly Dented	1,485.90 F	*1,295.90 FL
2	1		*BOOTLID REAR LOGO	Necessary	86.60 F	*76.50 FL
3	1		*BOOTLID CAMRY EMBLEM	Necessary	82.50 F	*78.50 FL
4	1		*BOOTLID OUTER HANDLE	Not Necessary	366.20 F	*- FL
5	1		*BOOTLID LOCK STRIKER	Not Necessary	121.00 F	*- FL
6	1		*BOOTLID HYBRID EMBLEM	Necessary	102.00 F	*85.80 FL
7	1		*BOOTLID WEATHERSTRIP	Twisted	288.50 F	*288.50 FL
8	1		*BOOTLID INNER LOCK	Twisted	652.30 F	*568.60 FL
9	2		*BOOTLID REFLECTORS	Cracked	1,700.20 F	*1,383.80 FL
10	1		*BOOTLID INNER TRIM	Deformed/Torn	499.20 F	*388.20 FL
11	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL
12	2		*BOOT LID HINGES	Not Necessary	310.00 F	*- FL
13	2		*BOOTLID LICENCE PLATE LAMPS	Not Necessary	120.00 F	*- FL
14	1		*BOOTLID LICENCE PLATE TOP GARNISH	Cracked	122.50 F	*122.50 FL
15	1		*REAR BUMPER	Distorted	1,299.10 F	*1,099.60 FL
16	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	210.00 F	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
18	1		*REAR BUMPER BEAM	Distorted	510.90 F	*510.90 FL
19	1		*REAR BUMPER LOWER SKIRTING	Dented/Deformed	645.10 F	*620.90 FL
20	1		*REAR BUMPER LOWER TRAY	Torn	545.50 F	*545.50 FL
21	1		*SET REAR BUMPER LOWER TRAY CLIPS	Not Necessary	50.00 F	*- FL
22	1		*REAR END PANEL	Badly Dented	688.20 F	*519.60 FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	485.50 F	*381.95 FL
24	1		*REAR FLOOR PANEL	Repair	1,145.20 F	*- FL
25	1		*REAR FLOOR PANEL TOP BOARD	Warped	620.30 F	*486.20 FL
26	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	811.20 F	*596.85 FL
27	2		*REAR TAILLAMPS	Cracked	1,900.00 F	*1,793.90 FL
28	2		*TAILLAMP HOUSING PANELS	Repair	710.00 F	*- FL
29	2		*REAR FENDERS	Repair	1,960.00 F	*- FL
30	2		*REAR FENDER INNER TRIMS	Deformed/Torn	1,244.20 F	*1,190.20 FL
31	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
32	2		*TAILLAMP LOWER BRACKETS	Not Necessary	50.00 F	*- FL
33	1		*REAR EXHAUST	Repair	1,020.50 F	*- FL
34	2		*REAR EXHAUST MOUNTINGS	Not Necessary	130.00 F	*- FL
35	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	166.50 F	*- FL
36	1		*REAR WINDSCREEN MOULDING	Not Necessary	98.10 F	*- FL
37	1		*REAR BOOTLID LOCK SENSOR	Serviceable	228.10 F	*- FL
38	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
39	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
40	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
41	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
42	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	280.00 FS	*- FS
43	1		*SET REAR REVERSE CAMERA	Shorted	500.00 FS	*300.00 FS
44	1		*SET REAR EXHAUST CHROME	Dented	380.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,315.30	12,783.90
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	3,023.48
Total Parts (\$)	22,315.30	9,760.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	120.00	60.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
5	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	120.00	80.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
7	TO SPRAY RUST PROOFING	New	120.00	60.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
Gross Labour Cost (\$\$)			4,750.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >