

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP19010005

Date: 31 MAR 2019

Dave Lim Chong Kok
c/o Hup Ley Huat Motor Spray Painting Services
Blk 1, #01- 35
Kaki Bukit Ave 6
Singapore 417883

THIRD PARTY SURVEY
ACCIDENT OCCURED ON 25 JAN 2019

Workshop Name and Address

Hup Ley Huat Motor Spray Painting Services
Blk 1, #01- 35
Kaki Bukit Ave 6
Singapore 417883

As per your instruction dated 29 JAN 2018
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SLH3311Z

1. VEHICLE PARTICULARS

Registration No : SLH3311Z
Model : TOYOTA HARRIER
Year / Capacity : OCT 2016 / 1986 cc
Chassis No : ZSU600084355

Engine No : 3ZRB837006
Mileage : 029 539 km
Colour : Metallic black

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	235/55/R18	Bridgestone	9.00 mm	Sport
REAR O/S :	235/55/R18	Bridgestone	9.00 mm	Sport
FRONT N/S :	235/55/R18	Bridgestone	9.00 mm	Sport
REAR N/S :	235/55/R18	Bridgestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 05 working days to complete
5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SLH3311Z

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

List Items

1 pc	Rear fender	bent/distorted	\$ 972.40	\$ 972.40 R X
1 pc	Rear door assy	dent/distorted	\$ 1,644.19	\$ 1,415.00 1,644.19 DD ✓
2 pcs	Rear door hinges	dent/distorted	\$ 264.22	\$ 220.00 264.22 BT ✓
1 pc	Rear door checker	dent/distorted	\$ 174.45	\$ 174.45 NN X
2 pcs	Rear door stopper	wrapped/deformed	\$ 87.40	\$ 87.40 NN X
1 pc	Rear door lock motor assy	bent/distorted	\$ 581.45	\$ 581.45 NN X
1 pc	Front door lock cable assy		\$ 39.50	\$ 39.50 NN X
1 pc	Rear door lock striker	bent/distorted	\$ 42.10	\$ 42.10 BT ✓
1 pc	Rear door protector	deformed	\$ 132.10	\$ 70.00 132.10 DD ✓
1 pc	Rear door protector chrome	deformed	\$ 121.10	\$ 121.10 CUT ✓
1 pc	Rear door window glass channel bracket	bent	\$ 174.40	\$ 174.40 BT ✓
1 pc	Rear door window glass channel rubber	wrapped/deformed	\$ 182.10	\$ 125.00 182.10 NEC ✓
1 pc	Rear door window glass outer moulding	deformed	\$ 174.25	\$ 174.25 BT ✓
1 pc	Rear door window frame black sticker	wrapped/deformed	\$ 122.10	\$ 40.00 122.10 NEC ✓
1 pc	Rear door window regulator	disrupted	\$ 374.25	\$ 322.50 374.25 BT ✓
1 pc	Rear door window regulator motor	electronically shocked	\$ 777.63	\$ 777.63 NN X
1 pc	Rear door outer handle	grazed/distorted	\$ 134.45	\$ 134.45 NN X
1 pc	Rear door sun visor	broken/smash	\$ 378.85	\$ 378.85 BR ✓
1 pc	Rear door weatherstrip	wrapped/deformed	\$ 182.40	\$ 182.40 DIS ✓
1 pc	Front door assy	dent/distorted	\$ 1,821.80	\$ 1,415.10 1,821.80 DD ✓
2 pcs	Front door hinge	bent/distorted	\$ 263.00	\$ 263.00 NN X
1 pc	Front door checker	bent/distorted	\$ 161.60	\$ 161.60 NN X
2 pcs	Front door stopper	wrapped/deformed	\$ 87.50	\$ 87.50 NN X
1 pc	Front door weatherstrip	wrapped/deformed	\$ 182.10	\$ 182.10 DIS ✓
1 pc	Front door protector	grazed/deformed	\$ 174.40	\$ 70.00 174.40 DD ✓
1 pc	Front door protector chrome	grazed/deformed	\$ 132.10	\$ 132.10 CUT ✓
1 pc	Front door outer handle	bent/distorted	\$ 323.85	\$ 171.40 323.85 CUT ✓
1 pc	Front door outer handle fame		\$ 167.50	\$ 167.50 NN X
1 pc	Front door window frame black sticker	wrapped/deformed	\$ 132.10	\$ 40.00 132.10 NEC ✓
1 pc	Front door lock motor assy	disrupted	\$ 400.20	\$ 400.20 NN X
1 pc	Front door lock cable assy	disrupted	\$ 39.50	\$ 39.50 NN X
1 pc	Front door fame moulding	deformed	\$ 78.70	\$ 78.70 BT ✓
1 pc	Front door chrome moulding	distorted	\$ 130.60	\$ 130.60 BT ✓
1 pc	Front door pillar - Outer	bent	\$ 631.25	\$ 631.25 NN X
1 pc	Front door pillar rubber seal	wrapped/deformed	\$ 143.50	\$ 143.50 NEC ✓
1 pc	Front door window regulator	disrupted	\$ 220.50	\$ 220.50 BT ✓
1 pc	Front door window regulator motor	disrupted	\$ 777.63	\$ 777.63 NN X
1 pc	Front door window glass channel rubber	bent	\$ 210.00	\$ 125.00 210.00 CUT ✓
1 pc	Front door window glass channel bracket	bent	\$ 185.00	\$ 185.00 BT ✓
Parts Sub-Total			\$ 12,822.17	\$ 12,822.17 6153.60
Discount 25.00%			\$ 3,205.54	\$ 3,205.54 1539.90
			\$ 9,616.63	\$ 9,616.63 4619.70

Vehicle Number : SLH3311Z

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------------	------------------------------------

Special Nett Items

1 pc	Rocker panel garnish	grazed/deformed	\$ 680.00	\$ 450 ✓ 680.00 DIS ✓
2 pcs	Door window glass solar film	necessary	\$ 500.00	\$ 500.00 ✓ NHX
2 pcs	Sound clad	deformed	\$ 600.00	\$ 200.00 600.00 ✓ NEC ✓

Special Nett Sub-Total \$ 1,780.00 \$ 1,780.00 800.00

Spare Parts Total \$ 11,396.63 \$ 11,396.63 5499.70

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
------	------------------	--------------------------	-----------------------------


	Spare Parts	Total c/f \$	11,396.63	\$	11,396.63	5499.70
1	To tuff coat affected areas	\$	250.00	\$	100.00	240.00
2	To remove replace interior upholstery	\$	220.00	\$	200.00	NNX
3	To respray affected areas	\$	1,600.00	\$	800.00	4,400.00
4	To renew damaged parts, straighten and repair door center pillar (inner), rear fender inner panel and aligned all parts	\$	1,600.00	\$	800.00	1,400.00
5	To remove & replace door assy	\$	180.00	\$	100.00	150.00
6	To check and adjust computer wheel alignment	\$	120.00	\$	100.00	NNX

Total \$ 15,366.63 \$ 14,886.63 7299.70

@ 20% 1459.94
5839.76

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of:

\$ 13,500.00


Fong Kok Heng
Qualified Appraiser

4/3 5,800/2

TG Lim
1/8/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG19001854/Btf3s2-1		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 ATTN: NORSIAH		Date : 06-08-2019		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SME 841J	Veh. Inspected	SLH 3311Z	
Policy No.	0999994322	Coverage (\$)	0.00	
Claim No.	9366357072SG	Excess (\$)	0.00	
Assign From	NORSIAH	Assign Date	12/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER ELEGANCE	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600084355	Colour	BLACK	
Odometer	29539	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65R17	DUNLOP	7 mm	
L/H Front Tyre	225/65R17	DUNLOP	7 mm	
R/H Rear Tyre	225/65R17	DUNLOP	7 mm	
L/H Rear Tyre	225/65R17	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/01/2019	Inspection Date	29/01/2019	
Survey held at	HUP LEY HUAT MOTOR SPRAY PAINTING SVS BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 3311Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER	TO REPAIR SEE LABOUR	972.40	-
1	REAR DOOR ASSY	DENTED	1,644.19	1,415.00
2	REAR DOOR HINGES	BENT	264.22	220.00
1	REAR DOOR CHECKER	NOT NECESSARY	174.45	-
2	REAR DOOR STOPPER	NOT NECESSARY	87.40	-
1	REAR DOOR LOCK MOTOR ASSY	NOT NECESSARY	581.45	-
1	FRONT DOOR LOCK CABLE ASSY	NOT NECESSARY	39.50	-
1	REAR DOOR LOCK STRIKER	BENT	42.10	42.10
1	REAR DOOR PROTECTOR	DENTED	132.10	70.00
1	REAR DOOR PROTECTOR CHROME	CUT	121.10	121.10
1	REAR DOOR WINDOW GLASS CHANNEL BRACKET	BENT	174.40	174.40
1	REAR DOOR WINDOW GLASS CHANNEL RUBBER	NECESSARY	182.10	125.00
1	REAR DOOR WINDOW GLASS OUTER MOULDING	BENT	174.25	174.25
1	REAR DOOR WINDOW FRAME BLACK STRIKER	NECESSARY	122.10	40.00
1	REAR DOOR WINDOW REGULATOR	BENT	374.25	322.50
1	REAR DOOR WINDOW REGULATOR MOTOR	NOT NECESSARY	777.63	-
1	REAR DOOR OUTER HANDLE	NOT NECESSARY	134.45	-
1	REAR DOOR SUN VISOR	BROKEN	378.85	378.85
1	REAR DOOR WEATHERSTRIP	DISTORTED	182.40	182.40
1	FRONT DOOR ASSY	DENTED	1,821.80	1,415.10
2	FRONT DOOR HINGE	NOT NECESSARY	263.00	-
1	FRONT DOOR CHECKER	NOT NECESSARY	161.60	-
2	FRONT DOOR STOPPER	NOT NECESSARY	87.50	-
1	FRONT DOOR WEATHERSTRIP	DISTORTED	182.10	182.10
1	FRONT DOOR PROTECTOR	DENTED	174.40	70.00
1	FRONT DOOR PROTECTOR CHROME	CUT	132.10	132.10
1	FRONT DOOR OUTER HANDLE	CUT	323.85	171.40
1	FRONT DOOR OUTER HANDLE FAME	NOT NECESSARY	167.50	-
1	FRONT DOOR WINDOW FRAME BLACK STICKER	NECESSARY	132.10	40.00
1	FRONT DOOR LOCK MOTOR ASSY	NOT NECESSARY	400.20	-

Report Ref No. CS3/AIG19001854/Btf3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT DOOR LOCK CABLE ASSY	NOT NECESSARY	39.50	-
1	FRONT DOOR FAME MOULDING	BENT	78.70	78.70
1	FRONT DOOR CHROME MOULDING	BENT	130.60	130.60
1	FRONT DOOR PILLAR - OUTER	NOT NECESSARY	631.25	-
1	FRONT DOOR PILLAR RIBBER SEAL	NECESSARY	143.50	143.50
1	FRONT DOOR WINDOW REGULATOR	BENT	220.50	220.50
1	FRONT DOOR WINDOW REGULATOR MOTOR	NOT NECESSARY	777.63	-
1	FRONT DOOR WINDOW GLASS CHANNEL RUBBER	CUT	210.00	125.00
1	FRONT DOOR WINDOW GLASS CHANNEL BRACKET	BENT	185.00	185.00
	LESS 25% DISCOUNT		-3,205.54	-1,539.90
			9,616.63	4,619.70
	<u>SPECIAL NETT ITEMS</u>			
1	ROCKER PANEL GARNISH (SN)	DISTORTED	680.00	450.00
2	DOOR WINDOW GLASS SOLAR FILM (SN)	NOT NECESSARY	500.00	-
2	SOUND CLAD (SN)	NECESSARY	600.00	200.00
			1,780.00	650.00
	<u>LABOUR</u>			
	TO TUFF COAT AFFECTED AREAS.		250.00	100.00
	TO REMOVE REPLACE INTERIOR UPHOLSTERY.	NOT NECESSARY	220.00	-
	TO RESPRAY AFFECTED AREAS.		1,600.00	800.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR DOOR CENTER PILLAR (INNER), REAR FENDER INNER PANEL AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER.		1,600.00	800.00
	TO REMOVE & REPLACE DOOR ASSY.		180.00	100.00
	TO CHECK AND ADJUST COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			-	-
			-	-
			-	-
			3,970.00	1,800.00
	GRAND TOTAL		15,366.63	7,069.70



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,650.00
---	--	--	----------

Report Ref No. CS3/AIG19001854/Btf3s2-1

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.