

12/21/2012

ASS. REC. BY:

REF: CS/smo 19012421/A + f 30

Special Instruction:

Surveyor: Marcus ASSIGNMENT (Office)

From (Person): Ruth Chua Gek Tiang of Smo

Date/Time: 12.7.19 17.58 p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBE 6010G Insured: SLA 3216C

at Workshop m/s Sin Y4 Sin Workshop Tel: 9199 3103

of 1 kaki Bukit Ave 6 # 01 52

Policy No: D19m7pv 0100 2589 Claim No: CMTD 190 334 1

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 11.7.19

(Client's Record) \_\_\_\_\_ 11.00a.19

CA / REV / REP. / REV 24 HRS <sup>up</sup> H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 15.7.19 9.10a.m Person Contacted: wai Leong Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBE 6010G-X
	SLA 3216C -X
16/7@16:25pm	Pending estimate from repairer, sent email via member
	Got supplementary & finalise

Missin

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: GBE60109 Yr Regn: 2016 Jan.

Type: M.Car / M.Cycle / Bus / Van / Car / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar c.c 2553.

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading 131422 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN15C2F2420858063

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C Westlake

R: 155 R13 Yokohama

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 15/07/19.

Survey held at Bin Yu Sin.

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sampo.

Lump Sum \$57501 cred: 8465.08; 59%

MV:

PV:

Nett:

RECEIVED 28 NOV 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 28/11 Typist

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

390
11
361

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2019		12 Jul 2019 17:58 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [\[Created by insurer\]](#)

Insured:	CHOO YEW MENG, ID: S0033382D		
Main Claimant:	CH ENGINEERING AND SERVICES, Co. Reg. No.: 201412164D		
Vehicle Reg. No.:	GBE6010G	Date of Loss:	11/07/2019 08:00 - :59
Claim Type:	TP / CMTD1903341	Policy/Cover Note No.:	D19MTPV01002589 (Comprehensive)
Vehicle Reg. No. (Insured):	SLA3216C	Policy No. (Claimant):	
		Excess:	
Repairer:	Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit), 417883 Kaki Bukit - Tel: 91993103/97825292		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/07/2019]		
Adj Asg. Remarks:	Please assign to Mr Marcus Chua		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Denise Tay (LKKAuto)

---

**From:** sinyu sin <sinyusin@hotmail.com>  
**Sent:** Wednesday, 27 November 2019 6:21 PM  
**To:** Denise Tay (LKKAuto)  
**Subject:** Re: GBE 6010G / SOMPO / DOA: 11/7/2019

Dear Denise,

Noted.  
Thank you

Regards  
Weileang  
Sin Yu Sin Workshop  
1 Kaki Bukit Ave 6  
#01-52 (Autobay)  
Singapore 417883

Tel: 91993103 Fax: 68163103

---

**From:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Sent:** Wednesday, November 27, 2019 2:11 PM  
**To:** sinyusin@hotmail.com <sinyusin@hotmail.com>  
**Subject:** GBE 6010G / SOMPO / DOA: 11/7/2019

Dear Wei Liang,

As spoken, re-finalized at \$5750.

Please check and confirm.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Sent Message

This mail is associated with :

**\*GBE6010G (CMTD1903341)**  
**[SLA3216C]**

TP

CH ENGINEERING AND SERVICES

Jul 11 2019 8:00AM

[CHOO YEW MENG]

Sin Yu Sin Workshop

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **16/07/2019 16:25 PM**.  
**To** ruth.chua@sompo.com.sg  
**Subject** **\*GBE6010G (CMTD1903341) [SLA3216C] TP**

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBE 6010G on 15/07/2019  
We are pending estimate from repairer.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

### DOCUMENTS SUMMARY

There are no documents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/07/2019 13:07
Date Of Accident	11/07/2019 08:35
Exact Location Of Accident	JUNCTION OF FLOWER ROAD AND KOVAN ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE6010G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CH ENGINEERING AND SERVICES PTE LTD
Co Reg No	201412164D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67479730

### Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPCVE000070
Cover Note Number	

### Driver

Name of Driver	ISLAM NURUL
Passport No/FIN	G8490289L
Date Of Birth	01/06/1988
Occupation	OUTDOOR
Date Of Driving Pass	01/02/2017
Driving Experience	2 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90760358
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 7 HENDRY ROAD  
 Postcode 549263  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - CROSS JUNCTION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3  
 Passenger 1 NAME: : SHAKAWAT  
 GENDER: : MALE  
 Passenger 2 NAME: : ASRAFUL  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes,Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes,against whom?

**Circumstances of Accident**

I WAS TRAVELLING STRAIGHT. SUDDENLY VEHICLE B MADE A RIGHT TURN WITHOUT CHECKING AND HIT ONTO MY RIGHT PORTION. I APPLIED BRAKE IMMEDIATELY AFTER THE IMPACT AS IT WAS A SLOPE MY VEHICLE STILL MOVE FORWARD ABIT WHICH CAUSED MY VEHICLE DAMAGE FROM FRONT RIGHT TO REAR RIGHT.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLA3216C  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

NURUL  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight Suddenly vehicle B made a right turn <sup>without checking</sup> and <sup>immediately after the impact</sup> hit into my right portion. I applied brake, but my vehicle still move forward a bit. which caused my damage from front right to rear right.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Signature]*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

# SIN YU SIN WORKSHOP

Reg No: 53253863C

91993103

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TP Sompō  
Denise

JNISC2F2420858063

12 July 2019

**QUOTATION FOR ACCIDENT REPAIR OF GBE6010G NISSAN CABSTAR**  
**THIRD PARTY INSURER: SOMPO INSURANCE SINGAPORE PTE LTD**

S/No.	Parts List	Qty	Amount (\$)
1.	Front bumper <i>Del-d</i>	1	\$ 897.00 ✓
2.	Front bumper reinforcement beam <i>Best</i>	1	\$ 576.60 ✓
3.	Front door RH <i>Del-d</i>	1	\$ 1696.40 ✓ <i>1386.</i>
3.	Front door hinge U/L (RH) <i>new</i>	2	\$ 144.60 ✗
4.	Front door checker RH <i>new</i>	2	\$ 116.80 ✗
5.	Front door window glass outer moulding RH <i>new</i>	1	\$ 187.70 ✗
6.	Front door inner lower weather strip RH <i>new</i>	1	\$ 120.00 ✗
7.	Front door inner weather strip RH <i>new</i>	1	\$ 168.50 ✗
8.	Front door signal lamp RH <i>new</i>	1	\$ 64.30 ✗
9.	Front step panel garnish RH <i>cut</i>	1	\$ 189.10 ✓
10.	Front wheel arch RH <i>Del-d</i>	1	\$ 160.90 ✓
11.	Front radiator space tank RH <i>Del-d</i>	1	\$ 80.60 ✓
12.	Front side member lower RH <i>Ryis</i>	1	\$ 790.70 ✗
13.	Front side gate RH <i>Ryis</i>	1	\$ 2986.50 ✗
14.	Front side gate bracket RH <i>Ryis</i>	1	\$ 197.40 ✗
15.	Front side gate bracket stopper RH <i>Missing</i>	1	\$ 55.40 ✓
16.	Rear mudflap panel F/R (RH) <i>Del-d</i>	2	\$ 310.00 ✓
17.	Front absorber RH <i>Best</i>	1	\$ 320.30 ?
18.	Front lower arm RH <i>Best</i>	1	\$ 303.20 ?
19.	Front upper arm RH <i>Best new</i>	1	\$ 326.50 ✗
20.	Front knuckle RH <i>Best new</i>	1	\$ 480.80 ✗
21.	Front knuckle bearing RH <i>Best new</i>	1	\$ 165.20 ✗
Subtotal before discount			\$ 10338.50
Discount 10%			\$ 1033.85
<b>Subtotal 1</b>			<b>\$ 9304.65</b>

4918.80

4426.92

# SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

12 July 2019

## QUOTATION FOR ACCIDENT REPAIR OF GBE6010G NISSAN CABSTAR

### THIRD PARTY INSURER: SOMPO INSURANCE SINGAPORE PTE LTD

<u>S/Nett.</u>	<u>Parts</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Front side gate assy sticker RH <i>new</i>	1	<del>\$200</del> 120
2.	Front door company reg no sticker RH <i>new</i>	1	\$15 ✓
3.	Front door assy protector RH <i>new</i>	1	<del>\$200</del> 80
3.	Front rim RH <i>cut</i>	1	<del>\$300</del> 200
4.	Front rim cover RH <i>could</i>	1	<del>\$200</del> 80
5.	Front tyre RH <i>new</i>	1	<del>\$250</del> 4
<b>Subtotal 2</b>			<b>\$ 1165</b>

## LABOUR

To check front electrical wiring system	\$80	30
To remove, check & replace front undercarriage parts.	<del>\$250</del>	320
To conduct wheel alignment	\$150	80
To apply anti rust proofing to front affected area	\$120	x
To straighten, repair, realign on rear affected area and replace damaged parts	\$1000	800
To spray painting on affected area	<del>\$1000</del>	600
<b>Total Labour Cost</b>	<b>\$ 2600</b>	

Total Cost Of Repairs (Total cost of parts + Total labour cost) **\$ 13,069.65**

*1145.08*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Adrian Ling*  
*1/8 15/07/19.*  
*06 Aug.*  
*Supplementary 1145.43*  
*total: 7797.35*  
*1/8 62K*

# SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

15 July 2019

**QUOTATION FOR ACCIDENT REPAIR OF GBE6010G NISSAN CABSTAR  
THIRD PARTY INSURER: SOMPO INSURANCE SINGAPORE PTE LTD**

**Supplementary Item**

<u>S/No.</u>	<u>Parts List</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Front wheel hub RH <i>Frond</i>	1	\$ 520.90
2.	Front wheel hub bearing RH	1	\$ 163.80
2.	Front headlamp side panel RH <i>Beit</i>	1	\$ 439.70
3.	Front wiper washer tank <i>Relid.</i>	1	\$ 148.30
	Total		\$ 1272.70
	Discount 10%		\$ 127.27
	<b>Subtotal 1</b>		<b>\$ 1145.43</b>

1272.70

1145.43

*Adrian Lj*  
*#/s 16/07/19.*  
*SL/S*

X



Sin Yu Sin Workshop

14215.08

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2019		12 Jul 2019 17:58 <a href="#">Edit Adj Rpt</a>	<b>S\$5,750.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,750.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>CHOO YEW MENG, ID: S0033382D</b>								
Main Claimant:	<b>CH ENGINEERING AND SERVICES, Co. Reg. No.: 201412164D</b>								
Vehicle Reg. No.:	<b>GBE6010G</b>	Date of Loss:	11/07/2019 08:00 - :59 <b>[41 Months and 15 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / CMTD1903341</b>	Policy/Cover Note No.:	D19MTPV01002589 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLA3216C</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit), 417883 Kaki Bukit - Tel: 91993103/97825292</b>								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]</b>								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/07/2019]</b>								
Adj Asg. Remarks:	Please assign to Mr Marcus Chua								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

\*GBE6010G (CMTD1903341)  
[SLA3216C]  
TP  
CH ENGINEERING AND SERVICES  
Jul 11 2019 8:00AM  
[CHOO YEW MENG]  
Sin Yu Sin Workshop

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
2	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
3	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
4	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
5	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
6	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
7	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
8	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
9	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
10	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
11	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
12	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
13	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
14	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
15	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
16	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
17	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
18	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
19	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
20	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
21	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
22	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
23	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
24	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
25	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
26	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
27	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
28	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
29	27/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
30	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	27/11/19 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
47	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
48	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
49	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
50	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
57	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
58	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
59	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
60	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
61	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
62	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	27/11/19 09:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	12/07/19 10:42	Third Party E-filed GIA report & Lawyer Letter		Load PDF <input type="checkbox"/>
2	12/07/19 17:57	Letter from Law Firm		Load PDF <input type="checkbox"/>
3	12/07/19 17:57	PRI - LKK		Load HTM <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/12/19 11:54	Supplementary		Load PDF <input type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/SMO19012421/UTF3E2

**Date:** 06/12/2019

#### REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01002589
<b>Claimant Vehicle No :</b>	GBE6010G	<b>Insured Vehicle No :</b>	SLA3216C
Date of Loss:	11/07/2019	Nature of Claim:	TP
		Claim No:	CMTD1903341

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBE6010G</b>	Engine No:	ZD30007647N
Make & Model:	NISSAN CABSTAR, 2.0 (M)	Chassis No:	JN1SC2F24Z0858063
Reg. Date:	26/01/2016 (Man. Year: 2015)	Odometer:	131422 km
Colour:	Blue		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R13
Front Left Side:	West Lake 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,615.08	5,500.62	6,114.46	52.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,730.00	870.00	33.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,215.08</b>	<b>7,230.62</b>	<b>6,984.46</b>	<b>49.13</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,750.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,215.08</b>	<b>5,750.00</b>	<b>8,465.08</b>	<b>59.55</b>

#### INSPECTION

Date of Assignment:	12/07/2019	
Date Inspected:	15/07/2019	Inspected At: Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit) Singapore 417883
Estimated Period of Repair:	6.0 days	

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 06 Dec 2019)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 2.0 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE6010G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	897.00 FL	*897.00 FL
2	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	576.60 FL	*576.60 FL
3	1		*FRONT DOOR RH	Dented	1,696.40 FL	*1,396.00 FL
4	2		*FRONT DOOR HINGE U/L (RH)	Not Necessary	144.60 FL	*- FL
5	2		*FRONT DOOR CHECKER RH	Not Necessary	116.80 FL	*- FL
6	1		*FRONT DOOR WINDOW GLASS OUTER MOULDING RH	Not Necessary	187.70 FL	*- FL
7	1		*FRONT DOOR INNER LOWER WEATHER STRIP RH	Not Necessary	120.00 FL	*- FL
8	1		*FRONT DOOR INNER WEATHER STRIP RH	Not Necessary	168.50 FL	*- FL
9	1		*FRONT DOOR SIGNAL LAMP RH	Not Necessary	64.30 FL	*- FL
10	1		*FRONT STEP PANEL GARNISH RH	Cut	189.10 FL	*189.10 FL
11	1		*FRONT WHEEL ARCH RH	Deformed	160.90 FL	*160.90 FL
12	1		*FRONT RADIATOR SPACE TANK RH	Deformed	80.60 FL	*80.60 FL
13	1		*FRONT SIDE MEMBER LOWER RH	Repair	790.70 FL	*- FL
14	1		*FRONT SIDE GATE RH	Repair	2,986.50 FL	*- FL
15	1		*FRONT SIDE GATE BRACKET RH	Repair	197.40 FL	*- FL
16	1		*FRONT SIDE GATE BRACKET STOPPER RH	Missing	55.40 FL	*55.40 FL
17	2		*REAR MUDFLAP PANEL F/R (RH)	Dented	310.00 FL	*310.00 FL
18	1		*FRONT ABSORBER RH	Bent	320.30 FL	*320.30 FL
19	1		*FRONT LOWER ARM RH	Bent	303.20 FL	*303.20 FL
20	1		*FRONT UPPER ARM RH	Not Necessary	326.50 FL	*- FL
21	1		*FRONT KNUCKLE RH	Not Necessary	480.80 FL	*- FL
22	1		*FRONT KNUCKLE BEARING RH	Not Necessary	165.20 FL	*- FL
23	1		*FRONT SIDE GATE ASSY STICKER RH	Necessary	200.00 FS	*120.00 FS
24	1		*FRONT DOOR COMPANY REG NO STICKER RH	Necessary	15.00 FS	*15.00 FS
25	1		*FRONT DOOR ASSY PROTECTOR RH	Necessary	200.00 FS	*80.00 FS
26	1		*FRONT RIM RH	Cut	300.00 FS	*200.00 FS
27	1		*FRONT RIM COVER RH	Cracked	200.00 FS	*80.00 FS
28	1		*FRONT TYRE RH	Not Necessary	250.00 FS	*- FS
29	1		*FRONT WHEEL HUB RH	Damaged	520.90 FL	*520.90 FL
30	1		*FRONT WHEEL HUB BEARING RH	Damaged	163.80 FL	*163.80 FL
31	1		*FRONT HEADLAMP SIDE PANEL RH	Bent	439.70 FL	*439.70 FL
32	1		*FRONT WIPER WASHER TANK	Deformed	148.30 FL	*148.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 12,776.20 6,056.80**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					1,161.12	556.18
<b>Total Parts (S\$)</b>					<b>11,615.08</b>	<b>5,500.62</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT ELECTRICAL WIRING SYSTEM	New	80.00	30.00
2	TO REMOVE, CHECK & REPLACE FRONT UNDERCARRIAGE PARTS	New	250.00	220.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
4	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	120.00	0.00
5	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	800.00
6	TO SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,600.00</b>	<b>1,730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >