

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19012463/EEA3Q2

Date: 28/04/2020

REFERENCE

| | | |
|---|-----------------------------|-----------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No: | MCOM0015 |
| Claimant | | |
| Vehicle No : SLX3925T | Insured Vehicle No : | SH9484K |
| Date of Loss: 10/07/2019 | Nature of Claim: TP | Claim No: MCT19070256 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|------------|
| Reg No: | SLX3925T | | |
| Make & Model: | HONDA SHUTTLE HYBRID, 1.5 (A) | Engine No: | LEB6311403 |
| Reg. Date: | 26/03/2018 (Man. Year: 2016) | Chassis No: | GP71109398 |
| Colour: | Black | Odometer: | 103245 km |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------|------------------|------------|
| Front Tyre Size: | 195/55 R15 | Rear Tyre Size: | 195/55 R15 |
| Front Left Side: | Toyo 5 mm | Rear Left Side: | Toyo 5 mm |
| Front Right Side: | Toyo 5 mm | Rear Right Side: | Toyo 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 1,345.48 | 876.64 | 468.84 | 34.85 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,220.00 | 420.00 | 800.00 | 65.57 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 2,565.48 | 1,296.64 | 1,268.84 | 49.46 |
| + GST 7.00/7.00% (S\$) | 179.58 | 90.76 | 88.82 | 49.46 |
| Nett Amount (S\$) | 2,745.06 | 1,387.40 | 1,357.66 | 49.46 |
| + Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$) | | 321.00 | | |
| Nett Liability (S\$) | | 1,708.40 | | |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 30/07/2019 | |
| Date Inspected: | 30/07/2019 | Inspected At: Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1 Singapore 729332 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: CHEN TSUE YEE

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | (Last Synchronised: 21 Apr 2020) | |
| Parts: | N/A | HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLX3925T) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Crushed | 1,050.20 FL | *1,050.20 FL |
| 2 | 10 | | *FRONT BUMPER CLIP | Necessary | 39.00 FL | *30.00 FL |
| 3 | 1 | | *FRONT BUMPER RETAINER (LH/RH) | O/S Broken | 31.20 FL | *15.60 FL |
| 4 | 1 | | *FRONT GRILLE CHROME (LOWER) | Not Necessary | 220.70 FL | *- FL |
| 5 | 1 | | *FRONT REINFORCEMENT | Not Necessary | 297.00 FL | *- FL |
| 6 | 1 | | *FRONT NO PLATE | Not Necessary | 35.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 1,673.10 | 1,095.80 |
| - List Item Discount on L Items 20.00/20.00% (\$) | 327.62 | 219.16 |
| Total Parts (\$) | 1,345.48 | 876.64 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|---|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO DISMANTLE & CHARGE FRONT BUMPER ,FRONT REINFORCEMENT ,KNOCKING & PULL STRAIGHT FRONT CHASSIS FRAME AND ALL AREA AFFECTED BY ACCIDENT | New | 600.00 | 200.00 |
| 2 | TO PERFORM WIRE CHECKING | New | 20.00 | 20.00 |
| 3 | TO SPRAY FRONT BUMPER ,FRONT REINFORCEMENT ,FRONT REINFORCEMENT AND FRONT CHASSIS FRAME | New | 600.00 | 200.00 |
| Gross Labour Cost (\$) | | | 1,220.00 | 420.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >