

Sten

REF:

ASSIGNMENT

From
Estimated Cost
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No:
at Workshop no:
at
Insured
Policy No.
Claims No.
Sum Insured:
(Client's Record)
Make of Veh:

Excess:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

MV-78K

Veh No. SLX 3925 T Yr Regn. 26/3/18
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda Shuttle Hybrid C.C. 1496
Colour Black A/C Insured / Std / NI / NA
Sp.Reading 103245 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: 6P71109398
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/55R15
R:
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Toyo
Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 10/7/19 D.O.I. 30/7/19
Survey held at Hua Hong
Des. of Damages ☒ Frt. Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prelim. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech. Invs (\$
☐ : Weekend (\$

Survey Fee:

Transportation

☐ : S + RS (\$

☐ : Printer

☐ : Other

☐ : ...

2017/1