

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 949C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,372.00	1,372.00
1	TAIL GATE ASSY (CONSISTENT)	NOT NECESSARY	3,951.98	-
1	TAIL GATE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	166.63	-
1	TAIL GATE MERCEDES STAR LOGO (CONSISTENT)	NOT NECESSARY	45.46	-
1	TAIL GATE '2.2' LOGO (CONSISTENT)	NOT NECESSARY	78.00	-
1	TAIL GATE 'CDI' LOGO (CONSISTENT)	NOT NECESSARY	78.00	-
1	TAIL GATE VIA NO LOGO (CONSISTENT)	NOT NECESSARY	78.00	-
1	TAIL LAMP ASSY LOWER ,RH (CONSISTENT)	NOT NECESSARY	622.44	-
	LESS 20% DISCOUNT		-1,278.50	-274.40
			5,114.01	1,097.60
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	288.00	-
1	TAIL GATE 'MAXICAB' LOGO (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
			318.00	-
	<u>LABOUR</u>			
	PANEL BEATING.		850.00	200.00
	SPRAY PAINTING CHARGE.		600.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR .	NOT NECESSARY	120.00	-
	REMOVE/REFIX TAILGATE GLASS .	NOT NECESSARY	150.00	-
	TUFF KOTE.	NOT NECESSARY	50.00	-
			1,820.00	400.00
	GRAND TOTAL		7,252.01	1,497.60

RECOMMENDED COST OF LUMP SUM REPAIRS		1,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM19012469/K1pa3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

Automotive Assessor

HO LEONG CHUAN