

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : **b1 51959**
Date Estimated : **15/07/2019**
Prepared By : **Han Kwan Yong**

Page No. :

REPAIR FOR -
Shang Jing
7 Lorong 42 Geylang
#05-02

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 398028

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD5822Z	NU06331	23/06/2016	330iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To diagnose and replace front RH wire harness include resetting and checking connections for proper function	451.00		451.00
# To diagnose and replace REM control unit, set LED module, RH LED module direction indicator include programming and conducting checks for proper function	451.00		451.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.55	2.00		3.10
# BLIND RIVET *	1.25	1.00		1.25
# UNFILTERED AIR SNORKEL *	55.20	1.00		55.20
# INTAKE DUCT *	69.25	1.00		69.25
# FRT RH REPAIR WIRING SET *	596.85	1.00		596.85
# FANFARE HORN HIGH TONE ELECTRONIC *	94.70	1.00		94.70
# CONTROL UNIT REM *	501.00	1.00		501.00
# SET LED MODULE *	162.05	1.00		162.05
# CONTROL UNIT FRT LIGHT ELECTRONICS *	893.90	1.00		893.90

Total Labour :	902.00
Total Parts :	2,377.30
Total Labour & Parts :	3,279.30