

20052003

ASS. REC. BY

REF

c83/LPC19000589/R1td30-1

c83/LPC19000589/R1td30-1

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person)

ong h i

of

fpc

Date/Time

16/7/2019  
10/1/19 @ 11:17am

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

FBN 3771R

Insured:

GBG 3520K

at Workshop n/s

Gp Motoring

Tel:

9061 8091

of

285 Macpherson Road

Policy No:

Claim No:

18/19/19/VCS/02/312

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/1/19

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement

Date/Time:

11:28am 10/1/19

Person Contacted

Mr. Ken

Vehicle

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	FBN 3771R-X
	GBG 3520K-X
	Submit lump sum \$1800 cred: (600; 47%)
	Submit PRS Report
	Rasul,

Pls check parts prices  
See my remarks

RECEIVED 02 AUG 2019

87 Done.  
1/8/2019

PRR

REF: JPC


ASSIGNMENT

From: Date: 10/01/2019  
Estimated Cost:  
OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
To inspect Vehicle No. FBN 3771R  
at Workshop m/s GP Motoring  
of 282 Macpherson Road  
Insured  
Policy No.  
Claims No.  
Sum Insured.  
(Client's Record)  
Make of Veh:

Excess:

(Policy Condition)

Remark The veh had commenced its repair at the time of inspection.



Bal. or Market Value: Consistent? : Yes or No  
IDAC Accident Rpt: Consistent? : Yes or No  
GIA / PR Seen: days Res: Yes or No  
Est. Repairs: % 3 Val: Yes or No  
Lum Sum:

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBN 3771R  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: YAMAHA GDR 155 C.C. 155  
Colour: Multi A/C: Insured / Std / NI / NA  
Sp Reading: 29130 T/Radio: Insured / Std / NI / NA  
Eng/No:  
C/N: MH3SG464035045481  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/80-14  
R: 140/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or IRC

Front Rear  
R/Bal. 4 mm R/Bal. 4 mm  
L/Bal. mm L/Bal. mm  
D.O.A. D.O.I. 10/01/19 @ 12:20pm

Survey held at GP Motoring

Des. of Damages: Frt / Rear / O/S / MS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 22 JAN 2019

Date/Time, File Pass to? : Prel. Report  
21/1/2019 : Final Report  
Date/Time, File Return to?

Days Of Repair:  
Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech Invs (\$)  
☐ Weekend (\$)

Survey Fee: 150  
Transportation  
S + RS \$  
Photos  
Others

150
TOTAL
150

Report Format: TP-PRR  
Lump Sum / I.B.I: (\$)

## Nivitha (LKK Auto)

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Tuesday, 16 July 2019 11:22 AM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** MT\_Claim\_SG; SUR  
**Subject:** RE: Your ref: JEQ/FBN3771R/GP/PI Our ref: 18/19/19/VC05/021312 ACCIDENT INVOLVING FBN3771R AND GBG3520K ON 9 JANUARY 2019 [External General]  
**Attachments:** 21312 TP SR.pdf

### Lonpac External - General

Dear Nivitha

Attached is the TP survey report.


Please let us have your surveyor's review/report.

Thanks,

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Thursday, 10 January, 2019 11:29 AM  
**To:** ONG LI LI; assignments  
**Cc:** MT\_Claim\_SG; SUR  
**Subject:** RE: Your ref: JEQ/FBN3771R/GP/PI Our ref: 18/19/19/VC05/021312 RE: ACCIDENT INVOLVING FBN3771R AND GBG3520K ON 9 JANUARY 2019

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ONG LI LI [mailto:llong@lonpac.com]  
**Sent:** Thursday, 10 January 2019 11:17 AM  
**To:** Alfred Ng <alfred\_ng@juseq.com.sg>; assignments@lkkauto.com; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>

# CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Mohamad Nazrin Bin Sa'at  
C/o: GP Motoring Pte Ltd  
284 Macpherson Road,  
Singapore 348608

Date : 5 April 2019  
Our ref : GPM/01/1902/TP

Accident Date : 09 January 2019  
Inspection Date : 10 January 2019  
Repairer Name : GP Motoring Pte Ltd  
284 Macpherson Road,  
Singapore 348608

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No : FBN 3771 R  
Make / Model : Yamaha GDR 155 (AEROX)  
Chassis No : MH3SG4640JJ045481  
Engine No : G3J8E0057934

Year / Capacity : 2018 / 155 cc  
Colour : Blue  
Mileage : 5565

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	: IRC	110/80 -14	5 mm	Sport
Rear	: IRC	140/70 -14	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 60 copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$ 3,400.00 on a contractual basis.

Under normal circumstances, the repair period would be about 12 (Twelve) working days.

# **ECL APPRAISER PTE LTD**

Vehicle Registration No: FBN 3771 R

Our Ref No: GPM/01/1902/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

1	Front fork tube assy	Damage	\$ 850.00	\$ 850.00	
1	Fork under bracket	Damage	\$ 375.00	\$ 375.00	XNN Δ
1	Front rim shaft	Necessary	\$ 40.00	\$ 40.00	
1	Front wheel rim	Damage	\$ 320.00	\$ 320.00	Repair
1	N/s side mirror	Damage	\$ 110.00	\$ 110.00	
1	N/s bracket level	Damage	\$ 48.00	\$ 48.00	
1	N/s footstep panel	Damage	\$ 120.00	\$ 120.00	
1	Air fitter box cover	Damage	\$ 175.00	\$ 175.00	
1	Drove belt cover	Damage	\$ 235.00	\$ 235.00	
1	Rear n/s footrest	Damage	\$ 750.00	\$ 55 750.00	
1	Main stand	Damage	\$ 125.00	\$ 125.00	repair
1	Fairing cover (1 set) ? 1pc	Damage	\$ 955.00	\$ 450 955.00	check
			\$ 4,103.00	\$ 4,103.00	2083
		Less 10%	\$ 410.30	\$ 410.30	10%
	<b>Total Cost - List Items</b>		\$ 3,692.70	\$ 3,692.70	1874.70

## SPECIAL NETT ITEMS

1	Number plate (1 set)	Damage	\$ 28.00	\$ 28.00	XNN
1	Steering cone (1 set)	Necessary	\$ 90.00	\$ 90.00	60
1	"AEROX" emblem	Necessary	\$ 55.00	\$ 55.00	40
	<b>Total Cost - Special Nett items</b>		\$ 173.00	\$ 173.00	100

**Total cost of parts**

\$ 3,865.70	\$ 3,865.70
-------------	-------------

Vehicle Registration No: FBN 3771 R

Our Ref No: GPM/01/1902/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 3,865.70	\$ 3,865.70

## LABOUR

1	To provide towing service.	\$ 50.00	\$ <del>50.00</del> 40
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ <del>50.00</del> 30
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 380.00	\$ <del>320.00</del> 250

320

GRAND TOTAL

\$ 4,375.70 \$ 4,285.70

1874.70  
 100.00  
 320.00  


---

 2294.70  
 208  
 1835.76  
  
 418.1800  


---

 5 days

# CL APPRAISER PTE LTD

Vehicle Registration No: FBN 3771 R

Our Ref No: GPM/01/1902/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 3,400.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

## Disclaimer

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

CL APPRAISER PTE LTD



Cheong K. H  
Automotive Appraiser




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC19000589/R1td3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 02-08-2019	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBG 3520K	Veh. Inspected	FBN 3771R	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/19/19/VC05/021312	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	16/07/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA GDR155	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MH3SG4640JJ045481	Colour	MULTI COLOUR	
Odometer	29130	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	110/80-14	IRC	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70-14	IRC	4 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/01/2019	Inspection Date	10/01/2019	
Survey held at	GP MOTORING PTE LTD 282 MACPHERSON ROAD SINGAPORE 348607			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 3771R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FORK TUBE ASSY	DAMAGED	850.00	850.00
1	FORK UNDER BRACKET	NOT NECESSARY	375.00	-
1	FRONT RIM SHAFT	NECESSARY	40.00	40.00
1	FRONT WHEEL RIM	TO REPAIR SEE LABOUR	320.00	-
1	N/S SIDE MIRROR	DAMAGED	110.00	110.00
1	N/S BRACKET LEVEL	DAMAGED	48.00	48.00
1	N/S FOOTSTEP PANEL	DAMAGED	120.00	120.00
1	AIR FITTER BOX COVER	DAMAGED	175.00	175.00
1	DROVE BELT COVER	DAMAGED	235.00	235.00
1	REAR N/S FOOTREST	DAMAGED	750.00	55.00
1	MAIN STAND	TO REPAIR SEE LABOUR	125.00	-
1	FAIRING COVER	DAMAGED	955.00	450.00
	LESS 10% DISCOUNT		-410.30	-208.30
			3,692.70	1,874.70
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET NUMBER PLATE (SN)	NOT NECESSARY	28.00	-
1	SET STEERING CONE (SN)	NECESSARY	90.00	60.00
1	"AEROX" EMBLEM (SN)	NECESSARY	55.00	40.00
			173.00	100.00
<b><u>LABOUR</u></b>				
	TO PROVIDE TOWING SERVICE.		50.00	40.00
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT WHEEL RIM AND MAIN STAND.		380.00	250.00
			510.00	320.00
<b>GRAND TOTAL</b>			<b>4,375.70</b>	<b>2,294.70</b>

Report Ref No. CS3/LPC19000589/R1td3e2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00
---	--	--	--	----------

Report Ref No. CS3/LPC19000589/R1td3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.