

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19012538/UEA3Q2**Date:** 28/04/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800060537
Claimant
Vehicle No : SJV6533E **Insured Vehicle No :** SMA549A
Date of Loss: 13/07/2019 Nature of Claim: TP Claim No: 8702449883SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV6533E**
Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR0504684
Reg. Date: 04/02/2010 (Man. Year: 2009) Chassis No: ZGE200036230
Colour: Grey Odometer: 312355 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17
Front Left Side: CST 6 mm Rear Left Side: CST 6 mm
Front Right Side: CST 6 mm Rear Right Side: CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,768.17	3,038.25	1,729.92	36.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,850.00	610.00	24.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,228.17	4,888.25	2,339.92	32.37
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	7,228.17	3,900.00	3,328.17	46.04
+ GST 7.00/7.00% (S\$)	505.97	273.00	232.97	46.04
Nett Amount (S\$)	7,734.14	4,173.00	3,561.14	46.04
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		5,044.00		

INSPECTION

Date of Assignment: 16/07/2019
Date Inspected: 16/07/2019 Inspected At: Focus Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #02-48/50 Autobay
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	1,295.00 FL	*1,295.00 FL
2	1		*REAR BOOT LOCK	Dented / Shorted	491.60 FL	*491.60 FL
3	1		*REAR BOOT LOCK CATCH	Not Necessary	35.20 FL	*- FL
4	1		*REAR BOOT RUBBER	Torn	381.60 FL	*381.60 FL
5	2		*REAR BOOT SHOCK ABSORBER	Not Necessary	396.40 FL	*- FL
6	1		*REAR BOOT EMBLEM	Necessary	60.20 FL	*60.20 FL
7	1		*REAR BOOT INNER BOARD	Not Necessary	365.00 FL	*- FL
8	1		*REAR BOOT LOGO	Necessary	80.00 FL	*68.10 FL
9	1		*REAR BOOT CENTRE MOULDING	Not Necessary	295.70 FL	*- FL
10	1		*REAR END PANEL	Bent	485.20 FL	*485.20 FL
11	1		*REAR END PANEL TOP GARNISH	Twisted	305.00 FL	*305.00 FL
12	1		*REAR FENDER INNER SIDE GARNISH	Serviceable	566.90 FL	*- FL
13	1		*REAR BUMPER	Dented / Deformed	655.90 FL	*566.10 FL
14	2		*REAR BUMPER SIDE RETAINER	Not Necessary	171.80 FL	*- FL
15	2		*REAR BUMPER BRACKET	Not Necessary	187.20 FL	*- FL
16	4		*REAR BUMPER LOWER CLIPSE	Necessary	22.00 FL	*22.00 FL
17	1		*REAR WINDSCREEN SEAL	Necessary	56.20 FL	*56.20 FL
18	1		*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS
19	1		*REAR WINDSCREEN GUM	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,230.90	3,971.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,462.73	932.75
Total Parts (\$\$)	4,768.17	3,038.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	60.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	160.00	120.00
5	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
6	SPRAY PAINTING	New	900.00	800.00
Gross Labour Cost (\$)			2,460.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >