

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBE7748E190711

Estimate

Customer	Page 01 - 02
Name: India International Insurance Pte Ltd	Date: 15-07-19
Address: Motor Claims Department	Vehicle No: GBE7748E
64 Cecil Street #04-00 & #05-00	Model/Make: Toyota Hiace
IOB Building Singapore 049711	Van Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>Body OD 1925.10</i>	\$ 2,051.60	
2	Tailgate Lock <i>OD/5m</i>	\$ 394.90	
3	Tailgate Rubber <i>1w1 395.10</i>	\$ 426.70	
4	Tailgate Inner Trim Board <i>70cm</i>	\$ 165.30	
5	Tailgate Inner Trim Board Clips 1 set <i>neu</i>	\$ 50.00	
6	Tailgate Inner Lock <i>shocked</i>	\$ 359.00	
7	Tailgate Suspension 02 pcs (@ S\$335.20) <i>11</i>	\$ 670.40	
8	Tailgate "Toyota" Motif <i>neu</i>	\$ 70.50	
8	Tailgate "8 PAX" Sticker <i>neu</i>	\$ 15.00	SN 105.2
9	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 15.00	SN 105.2
10	Tailgate Windscreen Glass <i>shocked 1205.10</i>	\$ 1,311.30	
11	Tailgate Windscreen Glass Moulding <i>NS</i>	\$ 219.00	
12	Tailgate Windscreen Glass Sealant <i>neu</i>	\$ 50.00	SN 405.2
13	Tailgate Wiper Motor <i>11</i>	\$ 604.40	
14	Tailgate Wiper Arm <i>11</i>	\$ 98.00	
15	Tailgate Wiper Blade <i>11</i>	\$ 60.20	
13	Number Plate Lamp 02 pcs (@ S\$78.60) <i>11</i>	\$ 157.20	
14	Number Plate Outer Garnish <i>Bent/scr</i>	\$ 397.00	
15	Number Plate "Metal" <i>Bent</i>	\$ 35.00	SN 155.2
16	Bumper <i>2.5</i>	\$ 465.00	
17	Bumper Bracket 04 pcs (@ 34.55 x 4 <i>Bent</i>	\$ 138.20	
18	Bumper Clips 1 set <i>neu</i>	\$ 48.00	
19	Bumper Reverse Sensor <i>shocked</i>	\$ 220.00	SN 2005.2
20	Bumper Reverse Camera <i>shocked</i>	\$ 690.00	SN 3005.2
21	Air Garnish <i>11</i>	\$ 170.00	
22	Tail Lamp 02 pcs (@ S\$365.10) <i>w/scrne 015320</i>	\$ 730.20	
23	Tail Lamp Lower Garnish 02 pcs (@ S\$65.10) <i>01520</i>	\$ 130.20	
24	3rd Brake Lamp <i>11</i>	\$ 234.20	
25	Floor Panel <i>2</i>	\$3,020.00	
26	Floor Panel Beam <i>Bent</i>	\$ 260.00	
27	Floor Panel Top Wooden Board <i>NT</i>	\$ 650.00	SN X
28	End Panel Outer <i>Body OD</i>	\$ 566.10	
29	End Panel Inner <i>Body OD</i>	\$ 936.20	
30	End Panel Top Plate <i>Regul</i>	\$ 299.50	
31	End Panel Sealant <i>11</i>	\$ 50.00	SN X
32	Spare Tyre Carrier <i>Bent</i>	\$ 289.00	
C/F Balance ---->		\$16,047.10	

Not Authorized
LKL

16/7/19

L/S #8100

Take ph. After rep -

Shy.



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE7748E190711

Estimate

Customer	Page 02 - 02
Name: India International Insurance Pte Ltd	Date: 15-07-19
Address: Motor Claims Department	Vehicle No: GBE7748E
64 Cecil Street #04-00 & #05-00	Model/Make: Toyota Hiace
IOB Building Singapore 049711	Van Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$16,047.10	
32	Rear Rh Fender (Body Panel)	\$ 1,308.10	X
33	Fender Inner Panel	\$ 1,069.10	X
34	Tail Lamp Panel	\$ 936.20	X
35	Corner Panel Garnish	\$ 376.50	X
36	Corner Panel Bracket	\$ 166.50	X
	"Corporate" Advertisement & Artwork	\$ 300.00	SN 180 S.W.
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	To check all wiring & electrical component for proper function	\$ 80.00	30
	Remove and refix rear bumper reverse sensor	\$ 80.00	50
	Remove and refix rear bumper Reverse Camera	\$ 120.00	
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	✓
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 300.00	n1X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$2,500.00	1400
	To putty & spray painting & including touch up paint on accident affect	\$ 1,800.00	1000
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	✓

Total Parts & Labour of estimate for damaged vehicle

\$ 25,363.50

Total amount in Lump Sum Basis for repaired vehicle

SDLS: Four Thousand Five Hundred Only



M/s Liu's Brother Auto Engrg Wks

- Liu's Auto Consultants hence notify the resurvey of the following:
- To resurvey within 48 hours after spray painting
 - To replace damaged part(s) during resurvey
 - Part prices are subject to confirmation
 - This resurvey is on a "Without Prejudice" basis
 - No litigation or litigation is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8867.9
 252
 8867.92
 S.N - 785.00
 10145.92
 207
 8116.73