

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 17 Jul 2019

Preliminary Advice

Vehicle No	: SLH9448Z	Accident Date	: 12/07/2019
Make	: MERCEDES-BENZ CLA180	Policy No.	: 29062369QMY
Assignment Date	: 17/07/2019	Excess	: S\$500.00
Date of Inspection	: 17/07/2019	Est. Duration of Repair	: 7.00
Inspection At	: STYTECH AUTO PTE LTD (HQ) 2 KAKI BUKIT AVE 2 #02-30, KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,589.00
Revised Amount	:S\$	10,926.00
Check Items (Estimated)	:S\$	4,327.40
Total	:S\$	15,253.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	52,690.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,310.00

Remarks

(X) The vehicle is economical for repair.

(X) Vehicle repair on part by part. Some of the parts pending for parts prices.