

ASS. REC. BY:

REF:

CS/INC19012567/T1+30

Special Instruction:

Surveyor:

Taukky

ASSIGNMENT (Office)

From (Person):

Hazalya

of

INC

Date/Time:

16.7.19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XE 2401 C

Insured:

XE 3314 P

at Workshop m/s

Woon Mung

Tel:

63161131

of

42 Sungai Kadut Ave

Policy No:

Claim No:

MT 11053422-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

my

H.O.D. Endorsement:

Date/Time:

16.7.19 5.36p.m

Person Contacted:

Hung

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	XE 2401C - X
	XE 3314P - X

ASS. REC. BY: Taufik

REF:


INC

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: XE2401C Yr Regn: 2016, Nov
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
 Make: Mitsubishi Fuso FS52 c.c. 11967
 Colour: Orange A/C: Insured / Std / NI / NA
 Sp. Reading: 117506 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: FS52SS 420603
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 295/80R27.5
 R: 295/80R27.5
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 4120K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front: _____ Rear: _____
 R/Bal. 8 mm R/Bal. 8/8 mm
 L/Bal. 8 mm L/Bal. 8/8 mm
 D.O.A. _____ D.O.I. 17/7/19 @ 12pm
 Survey held at Wan May Sy Kedat
 Des. of Damages: (Frt) (Rear) / O/S / N/S / U/C / Rooftop or +.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Pending for estimate. 4/5 \$ 21,100. 720 days (Red: 4397: 40%)</u>
	<u>RECEIVED 10 FEB 2020</u>
	<u>7/2/2020</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: 20
 Resurvey No. of Trip: 2

Date/Time, File Return to?
 2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>290</u>
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	<u>290</u>

Report Format: TP
 Lump Sum / I.P.I. / 21,100/-

Denise Tay (LKKAuto)

From: Woon Meng <woonmeng@singnet.com.sg>
Sent: Wednesday, 29 January 2020 2:24 PM
To: Taufikh (LKKAuto)
Cc: Denise Tay (LKKAuto)
Subject: Accident Involving XE2401C & XE3314P On 13/07/2019 Along BKE Towards KJE
Attachments: 2401.pdf

Dear Taufikh,

We refer to the matter below for your kind attention.

Kindly be informed that we confirm acceptance of COR l/s\$21,100.

Thank you & Warmest Regards,

Woon Meng Motor Pte Ltd

50, Bukit Batok Street 23
#01-06 Midview Building, Singapore (659578)
Tel : 63161131 / 63161151 || Fax : 63167050

From: Taufikh (LKK Auto) <taufikh@lkkauto.com>
Sent: Thursday, 23 January 2020 11:50 AM
To: 'Woon Meng' <woonmeng@singnet.com.sg>
Cc: 'Denise Tay (LKKAuto)' <denisetay@lkkauto.com>
Subject: RE: Accident Involving XE2401C & XE3314P On 13/07/2019 Along BKE Towards KJE

Hi Ms Heng,

COR l/s\$21,100 , 20 days.

Regards
Taufikh
Lkk Auto

From: Woon Meng [<mailto:woonmeng@singnet.com.sg>]
Sent: Monday, 20 January 2020 3:42 PM
To: 'Taufikh (LKK Auto)'
Subject: Accident Involving XE2401C & XE3314P On 13/07/2019 Along BKE Towards KJE
Importance: High

Dear Taufikh,

We refer to the matter below for your kind attention.

May we follow-up on the finalised offer for this case please.

Thank you & Warmest Regards,

Woon Meng Motor Pte Ltd

50, Bukit Batok Street 23
#01-06 Midview Building, Singapore (659578)

Catherine Chong (LKK Auto)

From: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>
Sent: Wednesday, 17 July, 2019 4:18 PM
To: Admin-D (LKKAuto); assignments
Cc: Hazalysa Binte Ibrahim
Subject: FW: TP CASES FARMED OUT TO LKK ON 16/7/2019

Dear LKK,

Re-sent

Warmest Regards

Hazalysa Bte Ibrahim
Admin Assistant
Motor Department
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 16 July 2019 10:41 AM
To: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 16/7/2019

Dear Sir/Madam,

Thank you for the assignment.

Best Regards

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalysa Binte Ibrahim [mailto:hazalysa.ibrahim@income.com.sg]
Sent: Tuesday, 16 July 2019 9:39 AM
To: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 16/7/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Chryllis Quah	MT/1052999-001	16/7/2019	YN4523L	CHENG AUTO BODYWORKS	5 SOON LEE STREET #01-62 PIONEER POINT	Rachel Lai / 86667775	14:00-16:00	XE4682U	06/07/19	
2	Quek Swee Keng	MT/1053280-001	16/7/2019	SHA0649D	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	VADIVELAN MOHAN / 96891857		SMH8282D	12/07/19	
3	Cyndie Yong	MT/1053293-002	16/7/2019	SHC567X	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	VADIVELAN MOHAN / 96891857		GBE3067M	12/07/19	
4	Eric Tang	MT/1049207-002	16/7/2019	GBC1456Y	SIN SHENG ENGINEERING SERVICES	NO 8 TUAS AVENUE 18 (LEVEL 5) SINGAPORE 638892	Susan / 68639595		YP2865C	14/06/19	
5	Charlotte Chew	MT/1052378-002	16/7/2019	PA9599K	CROWN ASIA BUS BUILDER PTE LTD	44 SUNGEI KADUT STREET 1 SINGAPORE 729349	Faika / 6966 9995		YK6341Y	07/07/19	
6	Eric Tang	MT/1052385-002	16/7/2019	SKW3944E	HUA HONG PTE LTD	25D SUNGEI KADUT STREET 1 SINGAPORE 729332	Jerleen Tang / 6661 9688	10:00-12:00	SME7385M	07/07/19	
7	Muhammad Airwan	MT/1053422-002	16/7/2019	XE2401C	WOON MENG MOTOR PTE LTD	42 SUNGEI KADUT AVE SINGAPORE 739666	HENG SEW SOW / 63161131		XE3314P	13/07/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg




At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	737H
Vehicle Details	
Vehicle No.:	XE2401C
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2020
Vehicle Make:	mitsubishi
Vehicle Model:	FUSO FS52SS3VDEA
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	OM457LA457972C0303797
Chassis No.:	FS52SSA20005
Maximum Power Output:	-
Open Market Value:	\$110,154.00
Original Registration Date:	18 Nov 2016
First Registration Date:	18 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$5,508.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Nov 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,589.00
COE Rebate Amount:	\$31,342.00
Total Rebate Amount:	\$31,342.00

The information contained herein is correct as at 02 Jan 2020

OK

36.27

Gear Part

1632.15

XE 2401C - 15/7/19

Notes

- 1 Panel bt ✓
- 1 Cover panel n/s ova ✓
- 1 Cover lamp n/s x
- 1 Mirror stay n/s bt ✓
- 1 Mirror under n/s ova ✓
- 1 n/s glass ova ✓
- 1 n/s Rubber ova ✓
- 1 SR P neu ✓
- 1 Bumper bt ✓
- 1 Bumper Bkt n/s
- 1 Bumper cover ctr mis ✓ LH
- 1 Step girth ctr cut ✓
- 1 Handling n/s ova ✓
- 1 Bumper top girth Bkt x
- 1 Bumper top girth ctr x
- 1 Upper girth ctr bt ✓
- 1 Upper blade ctr x
- 1 Upper line x
- 1 Upper Arms cover x
- 1 Auto ether neu ✓

Tanggal 19/7/19
Resny

PE 2401 C

Notes

- 1 R/R number ^{number plate.} PE 2407 H
- 1 R/R bumper bt
- 2 R/R Tail Lamp on
- 2 R/R blade ~~at~~ plate bt
- 1 R/R Tool Box R
- 2 R/R bumper BKT bt
- 1 Touring BKT bt
- 1 R/R number lamp on
- 2 R/R Tool Box BKT bt
- 1 R/R Dessel Tank dot
- 2 R/R Dessel Tank BKT bt
- 2 R/R Dessel Tank Cable dis
- 1 R/R Ctr blade Alw aluminium plate bt
- 2 R/R Reflector Reflector on
- 1 R/R water BKT n/s x bt
- 2 4 R/R mudguard ~~at~~ o/s bt ✓, n/s x
- 2 R/R blade BKT bt
- 2 R/R Tanker BKT ~~at~~ bt ✓
- 1 Rear chassis cross member ?

OE 2401C

Notes

To Remove and Repair Rear
Damage - \$2500/2
1800.

To Spray painting Rear Dangle
1200. - \$1500/2

To Remove and Refit Diesel
Tank - \$350/2 200

To Remove and Refit Repair Rear
wire hanger, lifting - \$400/2
250

To Repair Rear Chassis
Cross member - \$3000/2
photo ~~1000~~ 2100.

To Remove and Refit Tanker
we could photo ? - \$5000/2
3000

XE 2401

Notes

To Remove and Repair Int 1050
Damage - \$1800/2 ~~1000~~

To spray painting - \$800/2 600

To Remove & Refit A/W's \$200/2
150

To change wire & fitting - \$120
40

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/07/2019 14:42
Date Of Accident	13/07/2019 13:30
Exact Location Of Accident	ALONG BKE TOWARDS KJE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE2401C
Insured/Policyholder	
Name Of Registered Owner	MECPEC TRADING CO PTE LTD
Co Reg No	NA
Email Address	NOEMAIL (192905737H)
Mobile Phone No	
Alternative Phone No	OFFICE-65607660

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FUSO
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	D18MFL0002368
Cover Note Number	

Driver

Name of Driver	TOON SAI KIONG
NRIC No	S8084460C
Date Of Birth	19/09/1980
Occupation	OUTDOOR
Date Of Driving Pass	23/09/2009
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98517966
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 739 WOODLANDS CIRCLE #05-393
Postcode	730739
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE3314P
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAMASAMY VENGATESAN
NRIC/Passport Number	035200789
Contact Number	92744965
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REFER ATTACHED
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	XE3694S
-----------------------------	---------

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along BKE going to exit KJE. Traffic was slowly. Suddenly vehicle C applied emergency brakes and I also applied and managed to stop in time. I then felt an impact from the rear and my vehicle was pushed forward and hit vehicle C.

According to vehicle C, a car jammed brake in front of his vehicle that is why he applied emergency brakes.

No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
(Email Adress : woonmeng @singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : NTUC Income Insurance Cooperative Ltd
Motor Claims Dept

Date : 17 Jul 2019

Dear Sirs :

Fax : 6339 6277

RE : ESTIMATE COST FOR MITSUBISHI FS52S - XE2401C
ACCIDENT INVOLVING XE2401C & XE3314P & XE3694S ON 13/07/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front panel.	1pc	\$ 3,318.76 <i>bt✓</i>
2	Front corner panel n/s.	1pc	\$ 475.50 <i>over</i>
3	Front corner lamp n/s.	1pc	\$ 193.44 <i>x n/s</i>
4	Front side mirror stay n/s.	1pc	\$ 630.02 <i>bt✓</i>
5	Front side mirror under n/s.	1pc	\$ 189.53 <i>over</i>
6	Front windscreen glass	1pc	\$ 1,841.18 <i>over</i>
7	Front windscreen rubber	1pc	\$ 477.20 <i>over</i>
8	Front bumper	1pc	\$ 2,120.80 <i>bt✓</i>
9	Front bumper bracket n/s.	1pc	\$ 330.02 <i>x n/s</i>
10	Front bumper center cover n/s.	1pc	\$ 222.51 <i>n/s</i>
11	Front step center garnish	1pc	\$ 262.97 <i>cut</i>
12	Front headlamp n/s.	1pc	\$ 1,507.58 <i>over</i>
13	Front bumper top garnish bracket	1pc	\$ 118.53 <i>x n/s</i>
14	Front bumper top grille center	1pc	\$ 187.50 <i>x n/s</i>
15	Front wiper arm center	1pc	\$ 288.03 <i>bt✓</i>
16	Front wiper blade center	1pc	\$ 255.02 <i>x n/s</i>
17	Front wiper link	1pc	\$ 602.26 <i>x n/s</i>
18	Front wiper arm cover	1pc	\$ 30.20 <i>x n/s</i>
19	Emblem	1pc	\$ 301.22 <i>over</i>
	Sum Carried Forward		\$ 13,352.27

Sum Carried Forward

\$ 13,352.27

20	Rear bumper	1pc	\$	2,262.59	bt ✓
21	Rear taillamp @\$282.65ea	2pcs	\$	565.30	cr ✓
22	Rear blade plate @\$333.2ea	2pcs	\$	666.40	bt ✓
23	Rear bumper bracket @\$151.03ea.	2pcs	\$	302.06	bt ✓
24	Towing bracket	1pc	\$	233.41	bt ✓
25	Rear number lamp	1pc	\$	189.15	cr ✓
26	Rear tool box bracket @\$188.6ea	2pcs	\$	377.20	bt ✓
27	Rear diesel tank	1pc	\$	1,950.62	dt ✓
28	Rear diesel tank bracket @\$129.5ea	2pcs	\$	259.00	bt ✓
29	Rear diesel tank cable @\$299.71ea.	2pcs	\$	599.42	dis ✓
30	Rear center blade aluminium	1pc	\$	311.06	bt ✓
31	Rear reflector @\$189.15ea	2pcs	\$	378.30	cr ✓
32	Rear blade bracket @\$166.53ea	2pcs	\$	333.06	bt ✓
33	Rear tanker bracket n/s @\$168.55ea.	1pc	\$	337.10	bt ✓
34	Rear chassis crossmember	1pc	\$	1,999.80	Rx ✓
			\$	24,116.74	20399.97
			\$	(6,029.18)	15299.98
			\$	18,087.56	
35	Rear water tank bracket n/s- sn.	1pc	\$	180.00	bt ✓
36	Rear tool box -sn	1pc	\$	480.00	Rx m: 520
37	Rear mudguard @\$520ea -sn.	2pcs	\$	1,040.00	LH-X, RH-bt ✓
38	Front ERP bracket	1pc	\$	15.00	new
39	Rear number plate	1pc	\$	25.00	bt ✓
	Sum Carried Forward		\$	19,827.56	740

Sum Carried Forward

\$ 19,827.56

Labour Charge & Misc

To remove, repair, replace & weld front damaged parts.

} \$ 1,800.00 ¹⁰⁵⁰

} \$ 800.00 ⁶⁰⁰

To putty & spray painting (front).

To remove & replace front windscreen glass.

\$ 200.00 ¹⁵⁰

To R & R wiring and front check lighting.

\$ 120.00 ⁴⁰

To remove, repair, replace & install rear damaged parts.

} \$ 2,500.00 ¹⁸⁰⁰

}

To remove & refit diesel tank

\$ 350.00 ²⁰⁰

To remove & refit rear wire harness and check lighting

} \$ 400.00 ²⁵⁰

}

To repair rear chassis crossmember

\$ 3,000.00 ²¹⁰⁰

To remove and refit tanker (crane)

\$ 5,000.00 ³⁰⁰⁰

To putty & spray painting (rear).

\$ 1,500.00 ¹²⁰⁰

Total

\$ 35,497.56 ¹⁰³²⁰

26429.98
4/5 \$21,100
20 days #

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Taufik 97495749
WP 17/7/19
Lumpsum, Resurvey after repair
sur@lkkauto.com -
20 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19012567/T1t3e2
73 BRAS BASAH ROAD Date: 10-02-2020
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN : MUHAMMAD AIRWAN Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 3314P	Veh. Inspected	XE 2401C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1053422-002	Excess (\$)	0.00
Assign From	HAZALUSA	Assign Date	16/07/2019

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI FUSO FS52SS3VDEA	c.c	11967
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	FS52SSA20005	Colour	ORANGE
Odometer	117506 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	PIRELLI	8 mm
L/H Front Tyre	295/80 R22.5	PIRELLI	8 mm
R/H Rear Tyre	295/80 R22.5 (D)	PIRELLI	8/8 mm
L/H Rear Tyre	295/80 R22.5 (D)	PIRELLI	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/07/2019	Inspect Date / Time	17/07/2019 (12:00 PM)
Survey held at	WOON MENG MOTOR PTE LTD 42 SUNGEI KADUT AVENUE SINGAPORE 729666		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	20 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 2401C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT PANEL	BENT	3,318.76	3,318.76
1	FRONT CORNER PANEL N/S	CRACKED	475.50	475.50
1	FRONT CORNER LAMP N/S	NOT NECESSARY	193.44	-
1	FRONT SIDE MIRROR STAY N/S	BENT	630.02	630.02
1	FRONT SIDE MIRROR UNDER N/S	CRACKED	189.53	189.53
1	FRONT WINDSCREEN GLASS	CRACKED	1,841.18	1,841.18
1	FRONT WINDSCREEN RUBBER	NECESSARY	477.20	477.20
1	FRONT BUMPER	BENT	2,120.80	2,120.80
1	FRONT BUMPER BRACKET N/S	NOT NECESSARY	330.02	-
1	FRONT BUMPER CENTER COVER N/S	MISSING	222.51	222.51
1	FRONT STEP CENTER GARNISH	CUT	262.97	262.97
1	FRONT HEADLAMP N/S	CRACKED	1,507.58	1,507.58
1	FRONT BUMPER TOP GARNISH BRACKET	NOT NECESSARY	118.53	-
1	FRONT BUMPER TOP GRILLE CENTER	NOT NECESSARY	187.50	-
1	FRONT WIPER ARM CENTER	BENT	288.03	288.03
1	FRONT WIPER BLADE CENTER	NOT NECESSARY	255.02	-
1	FRONT WIPER LINK	NOT NECESSARY	602.26	-
1	FRONT WIPER ARM COVER	NOT NECESSARY	30.20	-
1	EMBLEM	NECESSARY	301.22	301.22
1	REAR BUMPER	BENT	2,262.59	2,262.59
2	REAR TAILLAMP @\$282.65	CRACKED	565.30	565.30
2	REAR BLADE PLATE @\$333.20	BENT	666.40	666.40
2	REAR BUMPER BRACKET @\$151.03	BENT	302.06	302.06
1	TOWING BRACKET	BENT	233.41	233.41
1	REAR NUMBER LAMP	CRACKED	189.15	189.15
2	REAR TOOL BOX BRACKET @\$188.60	BENT	377.20	377.20
1	REAR DIESEL TANK	DENTED	1,950.62	1,950.62
2	REAR DIESEL TANK BRACKET @\$129.50	BENT	259.00	259.00
2	REAR DIESEL TANK CABLE @\$299.71	DISTORTED	599.42	599.42
1	REAR CENTER BLADE ALUMINIUM	BENT	311.06	311.06
2	REAR REFLECTOR @\$189.15	CUT	378.30	378.30

Report Ref No. CS/INC19012567/T1f3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BLADE BRACKET @\$166.53	BENT	333.06	333.06
2	REAR TANKER BRACKET N/S @\$168.55	BENT	337.10	337.10
1	REAR CHASSIS CROSSMEMBER	TO REPAIR SEE LABOUR	1,999.80	-
	LESS 25% DISCOUNT		-6,029.19	-5,099.99
			18,087.55	15,299.98
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WATER TANK BRACKET N/S (SN)	BENT	180.00	180.00
1	REAR TOOL BOX (SN)	TO REPAIR SEE LABOUR	480.00	-
2	REAR MUDGUARD @\$520.00 (SN)	N/S NOT NECESSARY / O/S BENT	1,040.00	520.00
1	FRONT ERP BRACKET (SN)	NECESSARY	15.00	15.00
1	REAR NUMBER PLATE (SN)	BENT	25.00	25.00
			1,740.00	740.00
	<u>LABOUR</u>			
	TO REMOVE, REPAIR, REPLACE & WELD FRONT DAMAGED PARTS.		1,800.00	1,050.00
	TO PUTTY & SPRAY PAINTING (FRONT).		800.00	600.00
	TO REMOVE & REPLACE FRONT WINDSCREEN GLASS.		200.00	150.00
	TO R & R WIRING AND FRONT CHECK LIGHTING.		120.00	40.00
	TO REMOVE, REPAIR, REPLACE & INSTALL REAR DAMAGED PARTS.		2,500.00	1,800.00
	TO REMOVE & REFIT DIESEL TANK.		350.00	200.00
	TO REMOVE & REFIT REAR WIRE HARNESS AND CHECK LIGHTING.		400.00	250.00
	TO REPAIR REAR CHASSIS CROSSMEMBER.		3,000.00	2,100.00
	TO REMOVE AND REFIT TANKER (CRANE). INCLUSIVE OF THE REPAIR OF REAR CHASSIS CROSSMEMBER AND REAR TOOL BOX.		5,000.00	3,000.00
	TO PUTTY & SPRAY PAINTING (REAR).		1,500.00	1,200.00
			15,670.00	10,390.00
GRAND TOTAL			35,497.55	26,429.98

Report Ref No. CS/INC19012567/T1f3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			21,100.00
---	--	--	-----------

Report Ref No. CS/INC19012567/T1f3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.