

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19012582/AEA3Q2
Date: 19/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100358116
Claimant Vehicle No :	SGV1154J	Insured Vehicle No :	EL555T
Date of Loss:	11/07/2019	Nature of Claim:	TP
		Claim No:	6211130022SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV1154J	Engine No:	4G18JC6349
Make & Model:	MITSUBISHI LANCER, 1.6 (M)	Chassis No:	JMYSNCS3A7U008891
Reg. Date:	05/06/2007 (Man. Year: 2007)	Odometer:	208116 km
Colour:	Red		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,209.27	2,912.37	3,296.90	53.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,030.00	2,100.00	67.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,339.27	3,942.37	5,396.90	57.79
Approved Total (Overridden) (S\$)		3,100.00		

Nett Amount (S\$)	9,339.27	3,100.00	6,239.27	66.81
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 15/07/2019

Date Inspected: 16/07/2019

Estimated Period of Repair: 4.0 days

Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)
13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
Singapore 417807

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	858.00 FL	*773.00 FL
2	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	85.00 FL	*- FL
3	1		*FRONT BUMPER BEAM	Bent	177.00 FL	*177.00 FL
4	1		*FRONT BUMPER SIDE BRACKET RH	Necessary	95.00 FL	*44.00 FL
5	1		*FRONT BUMPER LOWER LIP	Cracked	689.00 FL	*689.00 FL
6	1		*FRONT BONNET	Not Necessary	705.00 FL	*- FL
7	1		*FRONT BONNET LOCK	Not Necessary	101.00 FL	*- FL
8	1		*FRONT RADIATOR GRILLE	Cracked	165.00 FL	*165.00 FL
9	1		*FRONT RADIATOR GRILLE LOGO	Not Necessary	45.00 FL	*- FL
10	1		*FRONT HEADLAMP RH	Cracked	986.00 FL	*572.00 FL
11	1		*FRONT HEADLAMP BRACKET RH	Not Necessary	81.00 FL	*- FL
12	1		*FRONT FENDER RH	Dented	526.90 FL	*526.90 FL
13	1		*FRONT FENDER COWLING RH	Torn	112.40 FL	*112.40 FL
14	1		*FRONT FENDER SIGNAL LAMP RH	Not Necessary	115.00 FL	*- FL
15	1		*FRONT SUPPORT PANEL	Not Necessary	659.00 FL	*- FL
16	1		*FRONT SIREN	Cracked	110.00 FL	*110.00 FL
17	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
18	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	80.00 FS	*30.00 FS
19	1		*FRONT TYRE RH	Not Necessary	350.00 FS	*- FS
20	1		*FRONT RIM RH	Not Necessary	550.00 FS	*- FS
21	1		*SET FRONT CAR PLATE WITH HOLDER	Not Necessary	70.00 FS	*- FS
22	1		*COOLANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,760.30	3,229.30
- List Item Discount on L Items 10.00/10.00% (\$)	551.03	316.93
Total Parts (\$)	6,209.27	2,912.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND PANEL BEAT THE AFFECTED PARTS & FITTING TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	400.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	600.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			3,130.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >