

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19012604/AQF3E2

Date: 07/04/2020

REFERENCE

Insured/Claimant:	MICHAEL CHONG	Policy No:	
Date of Loss:	16/07/2019	Nature of Claim:	OD Claim No: 2961375732SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR9942K	Engine No:	CVK043404
Make & Model:	AUDI A5, 2.0 SPORTBACK QUATTRO (A)	Chassis No:	WAUZZZF51JA022067
Reg. Date:	02/09/2017 (Man. Year: 2017)	Odometer:	36037 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,621.00	2,073.00	15,548.00	88.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,772.00	1,722.00	4,050.00	70.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,393.00	3,795.00	19,598.00	83.78
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	21,793.00	2,195.00	19,598.00	89.93
+ GST 7.00/7.00% (\$\$)	1,525.51	153.65	1,371.86	89.93
Nett Amount (\$\$)	23,318.51	2,348.65	20,969.86	89.93

INSPECTION

Date of Assignment:	17/07/2019		
Date Inspected:	17/07/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$432.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,073.00 FS	*2,073.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	368.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	* Check	32.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	178.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	207.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	489.00 FS	*- FS
7	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	187.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	56.00 FS	*- FS
9	1		*RADIATOR GRILLE	Not Necessary	2,131.00 FS	*- FS
10	2		*ULTRA SOUND SENSOR SUPPORT - LH / RH	Not Necessary	95.00 FS	*- FS
11	1		*RADIATOR GRILLE COVER - UPPER	Not Necessary	174.00 FS	*- FS
12	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	431.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
14	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	33.00 FS	*- FS
16	1		*FRONT BUMPER TOP COVER	Not Necessary	116.00 FS	*- FS
17	1		*CAUTION STICKER	Not Necessary	13.00 FS	*- FS
18	1		*AC STICKER	Not Necessary	7.00 FS	*- FS
19	1		*FRONT BUMPER BRACKET FOR LOCK CARRIER	Not Necessary	125.00 FS	*- FS
20	2		*FRONT BUMPER SUPPORT BRACKET - LH / RH	Not Necessary	51.00 FS	*- FS
21	1		*FRONT PARKING AID SENSOR	Not Necessary	231.00 FS	*- FS
22	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
23	1		*FRONT FENDER - LH	Not Necessary	968.00 FS	*- FS
24	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	48.00 FS	*- FS
25	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	68.00 FS	*- FS
26	1		*FRONT FENDER BRACKET - LH	Not Necessary	32.00 FS	*- FS
27	1		*FRONT FENDER BRACE - LH	Not Necessary	107.00 FS	*- FS
28	1		*FRONT FENDER DEFORMATION ELEMENT - LH	Not Necessary	45.00 FS	*- FS
29	5		*POP RIVET	Not Necessary	15.00 FS	*- FS
30	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	256.00 FS	*- FS
31	1		*FRONT WHEEL SPOILER (NPA)	Not Necessary	0.00 FS	*- FS
32	1		*FRONT WHEEL SPOILER TRIM - LH	Not Necessary	32.00 FS	*- FS
33	1		*STONE CHIP GUARD - LH	Not Necessary	46.00 FS	*- FS
34	1		*FRONT FENDER TOP LEDGE COVER - LONG	Not Necessary	32.00 FS	*- FS
35	1		*FRONT FENDER TOP LEDGE COVER - SHORT	Not Necessary	14.00 FS	*- FS
36	1		*FRONT FENDER EMBLEM	Not Necessary	145.00 FS	*- FS
37	1		*FRONT HEADLIGHT - LH	Not Necessary	7,204.00 FS	*- FS
38	1		*FRONT HEADLIGHT LIFT CYLINDER - LH	Not Necessary	181.00 FS	*- FS
39	1		*FRONT HEADLIGHT BRACKET FOR LIFT CYLINDER - LH	Not Necessary	13.00 FS	*- FS
40	1		*CORRUGATED PIPE	Not Necessary	78.00 FS	*- FS
41	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	42.00 FS	*- FS
42	1		*FRONT NO. PLATE	Not Necessary	40.00 FS	*- FS
43	1		*SUNDRIES	* Check	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 17,621.00 2,073.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,300.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,772.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >