

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19012607/KEA3Q2

**Date:** 24/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SML2594Y **Insured Vehicle No :** SKG8308T

**Date of Loss:** 12/07/2019 **Nature of Claim:** TP **Claim No:** 2037556782SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SML2594Y</b>	Engine No:	2NRX440801
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3001176829
Reg. Date:	13/05/2019 (Man. Year: 2019)	Odometer:	3945 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,827.85	492.30	1,335.55	73.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	765.00	1,975.00	72.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,567.85</b>	<b>1,257.30</b>	<b>3,310.55</b>	<b>72.48</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,000.00</b>		
<b>(\$\$)</b>	4,567.85	1,000.00	3,567.85	78.11
<b>+ GST 7.00/7.00% (\$\$)</b>	319.75	70.00	249.75	78.11
<b>Nett Amount (\$\$)</b>	<b>4,887.60</b>	<b>1,070.00</b>	<b>3,817.60</b>	<b>78.11</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (\$\$)</b>		240.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.48		
<b>Nett Liability (\$\$)</b>		<b>1,317.48</b>		

### INSPECTION

Date of Assignment: 17/07/2019

Date Inspected: 17/07/2019 Inspected At:

Esteem Performance Pte Ltd - Sin  
Ming (HQ)  
385 Sin Ming Drive  
Singapore 575718

Estimated Period of Repair: 3.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	497.10 FL	*497.10 FL
2	10		*REAR BUMPER CLIP	Necessary	38.90 FL	*38.90 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	141.75 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	141.75 FL	*- FL
5	1		*REAR BUMPER BRACKET LH	Repair	121.56 FL	*- FL
6	1		*REAR BUMPER BRACKET RH	Repair	121.56 FL	*- FL
7	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Repair	325.80 FL	*- FL
9	1		*REAR BUMPER REFLECTOR RH	Cracked	120.40 FL	*120.40 FL
10	1		*TAIL LAMP LH	Not Necessary	422.75 FL	*- FL
11	10		*TAIL LAMP CLIP	Not Necessary	38.90 FL	*- FL
12	1		*REVERSE SENSOR	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,320.47</b>	<b>656.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	492.62	164.10
<b>Total Parts (\$\$)</b>	<b>1,827.85</b>	<b>492.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,BOOTLID ,END PANEL)	New	1,000.00	300.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,BOOTLID ,END PANEL)	New	1,000.00	400.00
3	TO CHECK WIRING	New	50.00	15.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
5	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	0.00
6	TO TUFF COAT	New	150.00	0.00
7	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	0.00
8	TO DO ACT WORK	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,740.00</b>	<b>765.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >