

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates	SI	ML 2594 Y	Not Nothank
Parts (a) Cost / List Price Items	\$	1,970.47	Berny Bypary
Plus/Less25%	\$	492.62	7
Total of Cost / List	\$	1,477.85	LKK Auto Consultants hence notify the Repairer of the following:
(b) Nett Price Items Less			To display damaged part(s) during resurvey Parts price are subject to confirmation. Third party survey is an a "William of the survey is an a survey is an a survey is a surv
Total of Nett Item (c) Special Nett Items	\$	350.00	No illegal mc scation(s) is allowed Supplementation(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer
Total Parts Cost	\$	1,827.85	Signature:
Labour	\$	2,740.00	
Total	\$	4,567.85	
The above total will be subjected to	7% G.S.T.		

The above total will be subjected to 7% G.S.T.

Nar	ne of Surveyor		Kenneth
Cor	npany	:	6 kck
Sur	vey conducted on	:	17/7/19 at
Rer	narks By Surveyor		
(a)	The repair of this vehicle is author	rized	/ is not authorized until further notice.
(b)	Recommended Days of Repair	1	day(s)
(c)	Resurvey	:	Required / Not Required
(d)	Excess	:\$_	
(e)	Signature of surveyor	:	



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts	S	pa	re	Pa	rts
-------------	---	----	----	----	-----

Vehicle No. :	SML 2594 Y	Submit By	:	JENNY
Make & Model:	TOYOTA VIOS	Year Manufacture	:	2019
Chassis No :	MR2B23F3001176829	Engine No.	:	
		Cost / List		

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper	By	1	\$497.10		
2	Rear bumper clip	Na	10	\$38.90		_
3	Rear bumper side retainer LH		1	\$141.75		7
4	Rear bumper side retainer RH	SL	_ 1	\$141.75		X
5	Rear bumper bracket LH	n	1	\$121.56		X
6	Rear bumper bracket RH	V	1 1	\$121.56		X
7	Rear bumper sponge		1	N/A		12.5.3
8	Rear bumper reinforcement		n1	\$325.80		A
9	Rear bumper reflector RH	Cn	2 1	\$120.40		
10	Tail lamp LH		1	\$422.75		7
11	Tail lamp clip		10	\$38.90		7
12	Reverse sensor	Sm	1	\$350.00	S.N	X
13	Miles I Held's Theres					
14						
15						1
16						T. P. Tito
17						
18						
19						-7
20						
21						
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

а	ı.	_	
2	n	$^{\circ}$	 r

Vehicle No.	:	SML 2594 Y	Submit By :	Carmen Lim
Make & Model	: _	TOYOTA VIOS	Year of Manufacture:	2019

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL)	\$1,000.00	3001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL)	\$1,000.00	4001
3	To check wiring	\$50.00	4001
4	To remove & refit reverse sensor	\$120.00	501
5	To remove & refit spare tyre, spare tyre board, carpet trim	\$150.00	X
	to assist work load.		
6	To tuff coat.	\$150.00	X
7	To conduct water leakage tests to ensure proper air and	\$120.00	X
-	sealing		
8	To do act work (Bili) Nz	\$150.00	7

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.