

Surveyor

Carl

REF:

11P

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

SML 4833U

at Workshop m/s

N-51

of 2 Kalei Bulcitt Ave 2 H01-17.

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	☒

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SML4833U

Yr Regn:

22 May 2019

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Alphard C.C. 2493

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

6603

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

AGH300241486

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

D.O.I.

17-07-19

Survey held at

W/S

5:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/7

Estimate give later

19/5/2020

Finalized & 8000 with Yang.

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

HAO YUAN FOOD AND BEVERAGES
MANAGEMENT PTE LTD
 60 PAYA LEBAR ROAD #12-05 PAYA LEBAR
 SQUARE
 SINGAPORE 409051

Contact : 91313783

ESTIMATE

Repair Code : CLM15393
 Date in : 16/07/2019
 Vehicle Num. : SML4833U
 Model : TOYOTA ALPHARD 2.5SC CVT
 Chassis/Eng# : AGH300241486/2ARJ250675

Parts and Labour Assessment

Description of part	Qty	Unit Price	2009.1	Amount
REAR AIRCON COOLING UNIT ASSY / CRA	1	2138.10		2,138.10
REAR BUMPER	1	1217.40		1,217.40
REAR BUMPER REVERSE SENSOR HOLDER BRACKET / MCC	4	83.58	(SN) 50	334.32
REAR BUMPER REVERSE SENSOR WIRE HARNESS / DM	1	455.00	(SN) 200	455.00
REAR BUMPER RH REFLECTOR / CRA	1	174.45	116	174.45
REAR BUMPER RH REVERSE SENSOR / DM	1	399.45	(SN) 200	399.45
REAR BUMPER RH WHEEL COVER / M's	1	83.25		83.25
REAR BUMPER SIDE RETAINER L/R / CHX NN	2	123.05	97	246.10
REAR BUMPER TOW HOOK COVER / M's	1	43.50	25	43.50
REAR END PANEL / BUC	1	981.45	688	981.45
REAR RH FENDER X repair	1	972.50		972.50
REAR RH FENDER GLASS MOULDING X NN	1	1495.00		1,495.00
REAR RH FENDER INNER TRIM GARNISH / RL	1	780.85	(55.8)	780.85
REAR RH TAILLAMP / Cut	1	761.70	475	761.70
REAR RH TAILLAMP LOWER GARNISH / RL	1	377.60	325	377.60
REAR TAILGATE / BUC	1	1718.45		1,718.45
REAR TAILGATE 'ALPHARD' EMBLEM / MCC	1	61.70		61.70
REAR TAILGATE DUST SEAL COVER L/R X NN	2	32.15		64.30

*** This is a computer-generated document which requires no signature. ***

page 1

Rear Bumper Bracket RH \$105 / BT

HAO YUAN FOOD AND BEVERAGES
 MANAGEMENT PTE LTD
 60 PAYA LEBAR ROAD #12-05 PAYA LEBAR
 SQUARE
 SINGAPORE 409051

Contact : 91313783

ESTIMATE

Repair Code : CLM15393

Date in : 16/07/2019

Vehicle Num. : SML4833U

Model : TOYOTA ALPHARD 2.5SC CVT

Chassis/Eng# : AGH300241486/2ARJ250675

REAR TAILGATE INNER TRIM GARNISH	1	673.6	784.45	850	784.45	/
REAR TAILGATE LOWER GUIDE RUBBER STOPPER L/R	2		43.50		87.00	
REAR TAILGATE MECHANISM LOCK	1		374.80		374.80	
REAR TAILGATE MECHANISM LOCK MOTOR	1		781.30		781.30	
REAR TAILGATE RH DAMPER	1		374.45		374.45	
REAR TAILGATE RH POWER SENSOR	1		930.00		930.00	
REAR TAILGATE SIDE FEMALE STOPPER L/R	2		59.87		119.74	
REAR TAILGATE SIDE MALE STOPPER L/R	2		52.15		104.30	
REAR TAILGATE TOP GUIDE RUBBER STOPPER L/R	2		43.70		87.40	
REAR TAILGATE WEATHER STRIP	1		384.85	318	384.85	/
REAR TAILGATE WINDSCREEN GLASS MOULDING	1		172.85		172.85	/
REAR TAILLAMP LOWER GARNISH SIDE BRACKET L/R	1		131.40	66	262.80	/
		Subtotal before discount			16,769.06	
Percentage discount 25%					4,192.27	
		Sub-total 1			12,576.80	
REAR BUMPER CLIPS - SET	1		50.00	30	50.00	/
REAR RH FENDER INNER TRIM GARNISH CLIPS - SET	1		50.00	20	50.00	/
REAR RH FENDER SEALANT	1		80.00		80.00	

*** This is a computer-generated document which requires no signature.***

page 2

~~7774.85~~ 9807.35
 25% = 5831.14
 7355.51

/ Spray Painting #02-27
0051 Fax No. : +65 6741 0310

038C

D AND BEVERAGES
PTE LTD
AR ROAD #12-05 PAYA LEBAR

ORE 409051

contact : 91313783

ESTIMATE

Repair Code : CLM15393

Date in : 16/07/2019

Vehicle Num. : SML4833U

Model : TOYOTA ALPHARD 2.5SC CVT

Chassis/Eng# : AGH300241486/2ARJ250675

REAR RH TAILLAMP CLIPS - SET <i>X NN</i>	1	30.00	30.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>/ NEC</i>	1	50.00	<i>20</i> 50.00 <i>/</i>
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>X NN</i>	1	50.00	50.00
REAR TAILGATE POWER SENSOR CLIPS L/R - SET <i>X NN</i>	2	20.00	40.00
REAR TAILGATE WINDSCREEN GLASS SEALANT <i>/ NEC</i>	1	80.00	<i>40</i> 80.00 <i>/</i>
REAR TAILLAMP LOWER GARNISH CLIPS - SET <i>X NN</i>	2	20.00	40.00
Subtotal before discount			470.00
Percentage discount 0%			<i>470</i> 0.00
Sub-total 2		<i>500 360</i>	470.00
Parts-total			13,046.80

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

120 *X* 150.00

To reset system after repair works

120 *X* 300.00

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

/ 60.00

To remove, reinstall tailgate windscreen

120 *X* 150.00

To remove, reinstall fender glass

NNX 120.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

80 *X* 180.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

900 *X* 1,500.00

To remove and reinstall exhaust pipe.

NNX 150.00

*** This is a computer-generated document which requires no signature.***

ACTIVE PTE LTD

#01-08 / Spray Painting #02-27
65 6842 0051 Fax No. : +65 6741 0510

616038C
200616038C

FOOD AND BEVERAGES
MENT PTE LTD
LEBAR ROAD #12-05 PAYA LEBAR
SINGAPORE 409051

Contact : 91313783

ESTIMATE

Repair Code : CLM15393

Date in : 16/07/2019

Vehicle Num. : SML4833U

Model : TOYOTA ALPHARD 2.5SC CVT

Chassis/Eng# : AGH300241486/2AFJ250675

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

800 600 1,600.00

To apply anti-rust chemical on repaired and replaced panel.

80 600 100.00

Labour Total

4,310.00

Parts & Labour Total

1680

17,356.80

2280

*** This is a computer-generated document which requires no signature.***

page 4

7621.14 9995.51

20%: 6500 8000

76 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: