

Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
129	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
130	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
131	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
132	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
133	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
134	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
135	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
136	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
137	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
138	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
139	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
140	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
141	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
142	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
143	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
144	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
145	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
146	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
147	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
148	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
149	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
150	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
151	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
152	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
153	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
154	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
155	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
156	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
157	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
158	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
159	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
160	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
161	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
162	04/09/19 14:21	Reinspection Photo	 Load JPG	✓
163	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
164	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
165	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
166	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
167	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
168	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
169	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
170	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
171	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
172	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
173	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
174	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
175	04/09/19 14:22	Reinspection Photo	 Load JPG	✓
176	04/09/19 14:22	Reinspection Photo	Load JPG	✓

Assessment Reports

1 per page



No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
177	04/09/19 14:22	Reinspection Photo		Load JPG	
178	04/09/19 14:22	Reinspection Photo		Load JPG	
179	04/09/19 14:22	Reinspection Photo		Load JPG	
180	04/09/19 14:22	Reinspection Photo		Load JPG	
181	04/09/19 14:22	Reinspection Photo		Load JPG	
182	04/09/19 14:22	Reinspection Photo		Load JPG	
183	04/09/19 14:22	Reinspection Photo		Load JPG	
184	04/09/19 14:22	Reinspection Photo		Load JPG	
185	04/09/19 14:22	Reinspection Photo		Load JPG	
186	04/09/19 14:22	Reinspection Photo		Load JPG	
187	04/09/19 14:22	Reinspection Photo		Load JPG	
188	04/09/19 14:22	Reinspection Photo		Load JPG	
189	04/09/19 14:22	Reinspection Photo		Load JPG	
190	04/09/19 14:22	Reinspection Photo		Load JPG	
191	04/09/19 14:22	Reinspection Photo		Load JPG	
192	04/09/19 14:22	Reinspection Photo		Load JPG	
193	04/09/19 14:22	Reinspection Photo		Load JPG	
194	04/09/19 14:22	Reinspection Photo		Load JPG	
195	04/09/19 14:22	Reinspection Photo		Load JPG	
196	04/09/19 14:22	Reinspection Photo		Load JPG	
197	04/09/19 14:22	Reinspection Photo		Load JPG	
198	04/09/19 14:22	Reinspection Photo		Load JPG	
199	04/09/19 14:22	Reinspection Photo		Load JPG	
200	04/09/19 14:22	Reinspection Photo		Load JPG	
201	04/09/19 14:22	Reinspection Photo		Load JPG	
202	04/09/19 14:22	Reinspection Photo		Load JPG	
203	04/09/19 14:22	Reinspection Photo		Load JPG	
204	04/09/19 14:22	Reinspection Photo		Load JPG	
205	04/09/19 14:22	Reinspection Photo		Load JPG	
206	04/09/19 14:22	Reinspection Photo		Load JPG	
207	04/09/19 14:22	Reinspection Photo		Load JPG	
208	04/09/19 14:22	Reinspection Photo		Load JPG	
209	04/09/19 14:22	Reinspection Photo		Load JPG	
210	04/09/19 14:22	Reinspection Photo		Load JPG	
211	04/09/19 14:22	Reinspection Photo		Load JPG	
212	04/09/19 14:22	Reinspection Photo		Load JPG	
213	04/09/19 14:22	Reinspection Photo		Load JPG	
214	04/09/19 14:22	Reinspection Photo		Load JPG	
215	04/09/19 14:22	Reinspection Photo		Load JPG	
216	04/09/19 14:23	Reinspection Photo		Load JPG	
217	04/09/19 14:23	Reinspection Photo		Load JPG	
218	04/09/19 14:23	Reinspection Photo		Load JPG	
219	04/09/19 14:23	Reinspection Photo		Load JPG	
220	04/09/19 14:23	Reinspection Photo		Load JPG	
221	04/09/19 14:23	Reinspection Photo		Load JPG	

Documentation

1 per page



No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	17/07/19 14:41	Pre-Repair Survey - AGREED LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19012624/AVF3S2

Date: 10/09/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01016944
 Claimant Vehicle No: SLM9288S Insured Vehicle No: SGX8838M
 Date of Loss: 16/07/2019 Nature of Claim: TP Claim No: CMTD1903420

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM9288S
 Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520439008
 Reg. Date: 31/05/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0148834
 Colour: White Odometer: 33944 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,148.40	17,560.00	10,588.40	37.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,000.00	5,020.00	2,980.00	37.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,148.40	22,580.00	13,568.40	37.54
Approved Total (Overridden) (S\$)		18,000.00		
(S\$)	36,148.40	18,000.00	18,148.40	50.21
+ GST 7.00/7.00% (S\$)	2,530.39	1,260.00	1,270.39	50.21
Nett Amount (S\$)	38,678.79	19,260.00	19,418.79	50.21

INSPECTION

Date of Assignment: 17/07/2019

Date Inspected: 17/07/2019 Inspected At:

96 Motorsports Pte Ltd (HQ)
 62 Kaki Bukit Avenue 6, The Ark@KB
 Singapore 417893

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

9/10/2019

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Sep 2019)

Parts: 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM9288S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Distorted	1,057.40 FL	*1,057.40 FL
2	2		*REAR BOOT HINGE L+R	Bent	290.60 FL	*290.60 FL
3	1		*REAR BOOT EMBLEM (MAZDA 3)	Necessary	54.00 FL	*54.00 FL
4	1		*REAR BOOT EMBLEM (SKYACTIV)	Necessary	64.00 FL	*64.00 FL
5	2		*REAR BOOT LAMP L+R	Cracked	980.00 FL	*530.00 FL
6	1		*REAR BOOT LOGO	Necessary	75.00 FL	*75.00 FL
7	1		*SET REAR BOOT LAMP CLIP	Necessary	30.00 FL	*30.00 FL
8	1		*REAR BOOT LOCK	Damaged	173.00 FL	*173.00 FL
9	1		*REAR BOOT LOCK SWITCH	Damaged	133.00 FL	*133.00 FL
10	2		*REAR BOOT NO. PLATE LAMP L+R	Not Necessary	73.00 FL	*- FL
11	1		*REAR BOOT INSULATOR	Deformed	132.00 FL	*132.00 FL
12	1		*REAR BOOT INSULATOR CLIP	Necessary	30.00 FL	*30.00 FL
13	1		*REAR BOOT WEATHERSTRIP	Cut	157.00 FL	*157.00 FL
14	1		*REAR BOOT REVERSE CAMERA	Damaged	287.00 FL	*287.00 FL
15	1		*REAR BUMPER	Distorted	1,050.00 FL	*1,050.00 FL
16	2		*REAR BUMPER RETAINER L+R	Necessary	74.00 FL	*74.00 FL
17	2		*REAR BUMPER BRACKET L+R	Not Necessary	50.00 FL	*- FL
18	1		*SET REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	737.00 FL	*538.00 FL
20	2		*REAR BUMPER TOWING CAP L+R	Distorted	36.00 FL	*36.00 FL
21	1		*REAR BUMPER REFLECTOR L+R	N/s Cracked	140.00 FL	*70.00 FL
22	4		*REAR BUMPER REVERSE SENSOR	Damaged	300.00 FL	*300.00 FL
23	2		*TAIL LAMP L+R	N/s Cracked / O/s Cut	1,860.00 FL	*1,698.00 FL
24	2		*TAIL LAMP PANEL L+R	Dented	800.00 FL	*622.00 FL
25	2		*TAIL LAMP CLIP L+R	Necessary	50.00 FL	*50.00 FL
26	2		*REAR FENDER L+R	N/s Buckled / O/s Repair	2,360.00 FL	*1,180.00 FL
27	2		*REAR FENDER COWLING L+R	Not Necessary	160.00 FL	*- FL
28	1		*SET REAR FENDER COWLING CLIP L+R	Not Necessary	40.00 FL	*- FL
29	2		*REAR FENDER INNER TRIM L+R	Deformed	600.00 FL	*600.00 FL
30	1		*SET REAR FENDER INNER TRIM CLIP L+R	Necessary	30.00 FL	*30.00 FL
31	1		*REAR EXHAUST GASKET	Not Necessary	40.00 FL	*- FL
32	1		*REAR WINDSCREEN	Not Necessary	980.00 FL	*- FL
33	1		*REAR END PANEL	Distorted	605.00 FL	*605.00 FL
34	1		*REAR END PANEL TOP GARNISH	Deformed	90.00 FL	*90.00 FL
35	4		*REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FL	*40.00 FL
36	1		*SPARE WHEEL PANEL	Distorted	630.00 FL	*630.00 FL
37	1		*SPARE WHEEL PANEL TOP BOARD	Deformed	450.00 FL	*450.00 FL
38	2		*REAR CHASSIS NUMBER EXTENSION L+R	Repair	367.00 FL	*- FL
39	1		*REAR EXHAUST PIPE	Bent	1,080.00 FL	*1,080.00 FL
40	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	35.00 FL	*- FL
41	1		*REAR EXHAUST PIPE GASKET	Necessary	24.00 FL	*24.00 FL
42	1		*REAR EXHAUST PIPE HEAT SEAL	Crumpled	132.00 FL	*132.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*CENTRE EXHAUST PIPE	Not Necessary	683.00 FL	*- FL
44	2		*CENTRE EXHAUST PIPE MOUNTING	Not Necessary	245.00 FL	*- FL
45	1		*CENTRE EXHAUST PIPE GASKET (NPA)	Not Necessary	0.00 FL	*- FL
46	1		*FRONT BUMPER	Deformed	930.00 FL	*930.00 FL
47	2		*FRONT BUMPER SIDE RETAINER L+R	Necessary	56.00 FL	*56.00 FL
48	2		*FRONT BUMPER BRACKET L+R	Damaged	80.00 FL	*80.00 FL
49	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
50	1		*FRONT BUMPER TOP PAD	Deformed	48.00 FL	*48.00 FL
51	1		*FRONT BUMPER TOP SUPPORT GARNISH	Deformed	438.00 FL	*438.00 FL
52	1		*FRONT BUMPER LOWER GRILLE	Cracked	301.00 FL	*301.00 FL
53	2		*FRONT BUMPER FOG LAMP L+R	Not Necessary	680.00 FL	*- FL
54	2		*FRONT BUMPER FOG LAMP GARNISH L+R	Not Necessary	256.00 FL	*- FL
55	2		*FRONT BUMPER LED LAMP L+R	Not Necessary	360.00 FL	*- FL
56	2		*FRONT BUMPER TOWING CAP L+R	Not Necessary	60.00 FL	*- FL
57	1		*FRONT BUMPER REINFORCEMENT	Bent	578.00 FL	*578.00 FL
58	1		*FRONT BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
59	4		*FRONT BUMPER SENSOR	Damaged 2pcs Only	400.00 FL	*200.00 FL
60	1		*FRONT BUMPER NO PLATE GARNISH	Deformed	104.00 FL	*104.00 FL
61	1		*FRONT GRILLE ASSY	Cracked	169.00 FL	*169.00 FL
62	1		*FRONT GRILLE TOP GARNISH	Deformed	91.00 FL	*91.00 FL
63	1		*SET FRONT GRILLE TOP GARNISH CLIP	Necessary	40.00 FL	*40.00 FL
64	1		*FRONT BONNET	Not Necessary	1,123.00 FL	*- FL
65	1		*FRONT BONNET LOCK	Not Necessary	234.00 FL	*- FL
66	2		*FRONT BONNET HINGE L+R	Not Necessary	372.00 FL	*- FL
67	2		*HEAD LAMP L+R	Cracked	3,800.00 FL	*3,800.00 FL
68	2		*HEAD LAMP BRACKET L+R	Not Necessary	240.00 FL	*- FL
69	2		*FRONT FENDER L+R	Not Necessary	1,458.00 FL	*- FL
70	2		*FRONT FENDER COWLING L+R	Not Necessary	672.00 FL	*- FL
71	2		*FRONT FENDER COWLING CLIP L+R	Not Necessary	20.00 FL	*- FL
72	1		*FRONT SUPPORT PANEL	Cracked	1,163.00 FL	*798.00 FL
73	1		*A/C CONDENSER	Dented	1,400.00 FL	*1,400.00 FL
74	1		*A/C CONDENSER ELECTRIC FAN COWLING ASSY	Not Necessary	438.00 FL	*- FL
75	1		*RADIATOR	Not Necessary	637.80 FL	*- FL
76	1		*RADIATOR ELECTRIC FAN COWLING ASSY	Not Necessary	375.00 FL	*- FL
77	1		*RADIATOR TOP HOSE	Not Necessary	132.70 FL	*- FL
78	1		*RADIATOR COOLANT	Necessary	80.00 FS	*50.00 FS
79	1		*FRONT NUMBER PLATE	Cracked	60.00 FS	*30.00 FS
80	1		*REAR NUMBER PLATE	Cracked	60.00 FS	*60.00 FS
81	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
82	1		*SPARE WHEEL PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
83	1		*SPARE WHEEL PANEL INSULATOR	Necessary	100.00 FS	*100.00 FS
84	1		*REAR FENDER SEALANT L+R	Not Necessary	180.00 FS	*- FS
85	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
86	1		*REAR WINDSCREEN TINTED FILM	Not Necessary	300.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	34,940.50	21,845.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,792.10	4,285.00
Total Parts (\$\$)	28,148.40	17,560.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK, STRAIGHTEN & REALIGN ACCIDENT AFFECTED AREA (FRONT).	New	1,000.00	400.00
2	TO KNOCK, STRAIGHTEN & REALIGN ACCIDENT AFFECTED AREA (REAR).	New	2,800.00	1,800.00
3	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.	New	2,200.00	1,700.00
4	TO RUST POOF ACCIDENT AFFECTED AREA.	New	150.00	100.00
5	TO R&R AIRCON CONDENSER & REFILL GAS.	New	150.00	120.00
6	TO CHECK WIRING LAYOUT & HEADLAMP FOCUS.	New	80.00	60.00
7	TO R&R REAR BOOT MECHANISM.	New	120.00	60.00
8	TO R&R REAR LUGGAGE COMPARTMENT.	New	120.00	80.00
9	TO R&R REAR WINDSCREEN GLASS.	New	150.00	120.00
10	TO CHECK REVERSE SENSOR, REVERSE CAMERA & CHECK FUNCTION.	New	120.00	100.00
11	TO R&R REAR EXHAUST PIPE, CENTRE PIPE SYSTEM.	New	180.00	80.00
12	TO R&R FUEL PIPE, RETURN HOSE & ATTACHMENT PARTS.	New	120.00	60.00
13	TO R&R UPHOLSTERY REAR SEAT & ATTACHMENT PARTS.	New	400.00	60.00
14	TO CHECK WATER SEEPAGE.	New	60.00	0.00
15	TO CHECK CHASSIS ALIGNMENT.	New	350.00	280.00
Gross Labour Cost (\$\$)			8,000.00	5,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >