

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2119T

DATE 16/7/2019 9:26

AAAT

MAKE :

LKK-kalvin.

Cheng

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>- detail</i>			\$ 553.00
	Rear Bumper Reinforcement <i>X500</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X500</i>	\$	80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>- see</i>			\$ 22.00
	Rear Bumper Bracket <i>X500</i>	\$	35.60	\$ 71.20
	Rear Bumper Sponge <i>X500</i>			\$ 103.50
	Rear Bumper Under Cover <i>- cut</i>			\$ 228.00
	Rear Bumper Reflector Lamp (LH) <i>- cut</i>			\$ 30.60
	SUB TOTAL			\$ 1,597.30
	LESS 20%			\$ 319.46
	DISCOUNTED TOTAL			\$ 1,277.84
	Rear Bumper Rubber Mat <i>- see</i>			\$ 50.00
	Rear Bumper Reverse Sensor <i>- sketched</i>			\$ 135.70
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 350.00 ²⁰⁰
	Spray Painting Charge			\$ 250.00 ²⁰⁰
	Wiring Charge			\$ 30.00 ³⁰
	Remove/Refix Reverse Sensor			\$ 80.00 ³⁰
	Towing fee.			\$ 60.00
	TOTAL LABOUR			\$ 710.00
	ESTIMATE TOTAL			\$ 2,173.54

Auto Const
 The Repairer of the following
 • To resurvey back related structure
 • To display damaged parts
 • Parts prices are subject to
 • Third party survey is on a "W" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Kalvin LKK
17/7/19 10:16h
2 R71
PCP
Before Paint photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.