

ASS. REC. BY:

REF: CS/CT119012636/0sf3n2

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): Chong Bun Sen

of C12

Date/Time: 17. 3. 19 11.10p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 3383K

Insured: SJW 3581E

at Workshop m/s Kan Pook Sing

Tel: 6749560

of No 61 DeFu Lane 12

Policy No: DMPC SM/6/6451A033

Claim No: SNM1910203187

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A 7.7.19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.7.19 4.47p.m

Person Contacted:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate

Minimum

mp"

(08/11/13) wef
ASS. REC. BY: Marcus

REF: CT1

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMA3383
at Workshop m/s 1278
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: 2 Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 1.76 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS 17A54231
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SMA3383R Yr Regn: 6, 18
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA /
Make: Toyota Voxy Hybrid c.c 1797
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 20994 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ZWR800305382
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65 R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front _____ Rear _____
R/Bal. 2 mm R/Bal. 2 mm
L/Bal. 2 mm L/Bal. 2 mm
D.O.A. 7/7/19 D.O.I. 20/7/19
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>3/10/19</u>	<u>Confirmed final by #3564.73 with Alice</u>
	<u>(S 1,963.04 Red - 36%)</u>

RECEIVED 03 OCT 2019

Date/Time, File Pass to?
1) 03/10/19
Typist
Date/Time, File Return to?
2) _____

: Preli. Report
 : Final Report

Days Of Repair: 5
Resurvey No. of Trip: 1

Report Format : _____
Lump Sum / I.B.I: (\$) _____)

Add Fee: : Site Insp (\$) _____)
 : Interview (\$) _____)
 : Tech. Invs (\$) _____)
 : Weekend (\$) _____)

Survey Fee: _____
Transportation: _____
Photos _____
Others _____
TOTAL 220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jul 2019		17 Jul 2019 16:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:									
Main Claimant:		LIM HIAN SER, ID: S1443944G							
Vehicle Reg. No.:		SMA3383R	Date of Loss:	07/07/2019 11:00 - :59					
Claim Type:		TP / SNM19D203187	Policy/Cover Note No.:	DMPCS16164519033					
Vehicle Reg. No. (Insured):		SJW3581E	Policy No. (Claimant):	PNP2019-00008679					
			Excess:	S\$500.00					
Repairer:		Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]							
Claimant's Insurer:		FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/07/2019]							
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3944G
Vehicle Details	
Vehicle No.:	SMA3383R
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VOXY HYBRID 1.8V CVT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	2ZR0B05857
Chassis No.:	ZWR800305382
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,113.00
Original Registration Date:	07 Jun 2018
First Registration Date:	07 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$28,359.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jun 2028
PARF Rebate Amount:	\$21,269.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$32,962.00
Total Rebate Amount:	\$54,231.00

The information contained herein is correct as at 10 Jul 2019

OK



簡福星嘍多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 ANSON ROAD #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

VEHICLE NO. : SMA3383R
 ACCIDENT DATE : 07-07-2019 11:00
 THIRD PARTY REF. : SJW3581E

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SMA3383R TOYOTA VOXY-2.0 (A)

DATE : 08-07-2019
not Allowed
all
to be the better party.
S-Ly.
P/P

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BOOT COVER	<i>3000</i> 1700.00
2	2	REAR BOOT WINDSCREEN MOULDING@\$67.20	<i>na</i> 134.40
3	1	REAR BOOT LOCK	<i>SVC</i> 495.00 X
4	1	REAR BOOT RUBBER	<i>SVC</i> 484.00 X
5	1	REAR END PANEL	<i>R</i> 715.00 X
6	1	REAR END PANEL TOP GARNISH	<i>Defcon</i> 147.60
7	1	REAR BUMPER	<i>DD</i> 534.30
8	1	REAR BUMPER SIDE LH	<i>SVC</i> 325.00 X
9	1	REAR BUMPER SIDE RETAINER SHORT LH	<i>17</i> 155.00 X
10	1	REAR BUMPER SIDE RETAINER LONG LH	<i>17</i> 106.52 X
11	10	REAR BUMPER CLIP@\$5.00	<i>na</i> 50.00
			4,846.82
LESS 20 % <i>25%</i>			1,454.05
TOTAL (A)			3,392.77

SPECIAL NETT ITEMS

1	1	REAR WINDSCREEN GUM	<i>na</i> 45.00 <i>40</i>
2	1	REAR REVERSE SENSOR	<i>shhd</i> 300.00 <i>200</i>
TOTAL (C)			345.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00 <i>20</i>
---	---	------------------------	-----------------

Let's Star Cooper is liable to notify the Insurer of the following:

- To inspect, supervise, spray painting
- To rectify damaged parts during resurvey
- Parts must be returned to confirmation
- Third party survey on a "Without Prejudice" basis
- No legal proceedings is allowed
- Emergency works must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reposer:
 Signature:
 Date:



簡福星噴吸工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SMA3383R
 ACCIDENT DATE : 07-07-2019 11:00
 THIRD PARTY REF. : SJW3581E

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
2	1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	100.00
3	1	TO REMOVE/REFIT REAR FENDER INNER GARNISH RH/LH	120.00 <i>80</i>
4	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	720.00 <i>600</i>
5	1	SPRAYPAINTING CHARGES	820.00 <i>600</i>
TOTAL (D)			1,790.00
ESTIMATE TOTAL			5,527.77
			<i>5770.11</i>

P-2566.30
1924.72
3564.73

筒福星摩哆工廠
 KAN FOOK SING MOTOR WORKSHOP
 61 DEFU LANE 12
 SINGAPORE 539147
 TEL: 67479560, 68582126, 68584361
 FAX: 67481006, 62818428

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 ANSON ROAD #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

INVOICE NO : TEST
 DATE : 28-09-2019

VEHICLE NO. : SMA3383R
 ACCIDENT DATE : 07-07-2019 11:00
 THIRD PARTY REF. : SJW3581E

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SMA3383R TOYOTA VOXY-2.0(A)

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR BOOT COVER	1700.00 —
2	REAR BOOT WINDSCREEN MOULDING @\$67.20	134.40 —
1	REAR END PANEL TOP GARNISH	147.60 —
1	REAR BUMPER	534.30 —
10	REAR BUMPER CLIP @\$5.00	50.00 —
		<hr/> 2,566.30
	LESS 25 %	641.58
	TOTAL (A)	<hr/> 1,924.73

SPECIAL NETT ITEMS

1	REAR WINDSCREEN SEALANT	40.00 —
1	REAR REVERSE SENSOR	200.00 —
	TOTAL (C)	<hr/> 240.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	20.00 —
1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	100.00 —
1	TO REMOVE/REFIT REAR FENDER INNER GARNISH RH/LH	80.00 —
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	600.00 —

VEHICLE NO. : SMA3383R
ACCIDENT DATE : 07-07-2019 11:00
THIRD PARTY REF. : SJW3581E

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	SPRAYPAINTING CHARGES	600.00
	TOTAL (D)	<u>1,400.00</u>
	TOTAL REPAIR COST :	<u>3,564.73</u>
	G S T % :	<u>249.53</u>
	INVOICE AMOUNT :	<u>3,814.26</u>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19012636/USF3N2

Date: 08/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN16164519033
Claimant Vehicle No :	SMA3383R	Insured Vehicle No :	SJW3581E
Date of Loss:	07/07/2019	Nature of Claim:	TP
		Claim No:	SNM19D203187

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA3383R	Engine No:	2ZR0B05857
Make & Model:	TOYOTA VOXY, 2.0(A)	Chassis No:	ZWR800305382
Reg. Date:	07/06/2018 (Man. Year: 2018)	Odometer:	20994 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,980.11	2,164.72	1,815.39	45.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	1,400.00	390.00	21.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,770.11	3,564.72	2,205.39	38.22
+ GST 7.00/7.00% (S\$)	403.91	249.53	154.38	38.22
Nett Amount (S\$)	6,174.02	3,814.25	2,359.77	38.22

INSPECTION

Date of Assignment:	17/07/2019	
Date Inspected:	10/07/2019	Inspected At:
		Kan Fook Sing Motor Workshop (Defu)
		No. 61 Defu Lane 12
		Singapore 539147
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$3,564.73

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2019)	
Parts: M1-MPV	TOYOTA VOXY 2.0(A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMA3383R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT COVER	Badly Dented	1,700.00 FL	*1,700.00 FL
2	2	*REAR BOOT WINDSCREEN MOULDING	Necessary	134.40 FL	*134.40 FL
3	1	*REAR BOOT LOCK	Serviceable	495.00 FL	*- FL
4	1	*REAR BOOT RUBBER	Serviceable	484.00 FL	*- FL
5	1	*REAR END PANEL	Repair	715.00 FL	*- FL
6	1	*REAR END PANEL TOP GARNISH	Deformed/Cracked	147.60 FL	*147.60 FL
7	1	*REAR BUMPER	Dented	534.30 FL	*534.30 FL
8	1	*REAR BUMPER SIDE LH	Serviceable	325.00 FL	*- FL
9	1	*REAR BUMPER SIDE RETAINER SHORT LH	Not Necessary	155.00 FL	*- FL
10	1	*REAR BUMPER SIDE RETAINER LONG LH	Not Necessary	106.52 FL	*- FL
11	10	*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
12	1	*REAR WINDSCREEN GUM	Necessary	45.00 FS	*40.00 FS
13	1	*REAR REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,191.82	2,806.30
- List Item Discount on L Items 25.00/25.00% (S\$)	1,211.71	641.58
Total Parts (S\$)	3,980.11	2,164.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	30.00	20.00
2	TO REMOVE/REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
3	TO REMOVE/REFIT REAR FENDER INNER GARNISH RH/LH	New	120.00	80.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	720.00	600.00
5	SPRAYPAINTING CHARGES	New	820.00	600.00
Gross Labour Cost (S\$)			1,790.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >